



## Pipeline Safety Division Investigation Report

### Investigation regarding: C & R Concrete Contractors

UPPAC Database Record ID: 4554

Report Date: 6/27/2013

Investigator: Mike Orr

Damage Date: 2/7/2013

Damage Address: 1600 Red Sunset Drive, Brownsburg, Hendricks

### The Parties

Excavator: C & R Concrete Contractors

Address: 3219 E Tulip Drive, Indianapolis, In 46227

Facility Owner: Vectren

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Grader/Scraper

Type of Work Performed: Driveway

### Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$795

### Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number: Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

**Synopsis:** Excavator struck and damaged an underground natural gas service while performing concrete work.

**Findings:** Reported by Vectren; excavator's response to initial notice was received on 6/3/2013. Excavator not only failed to request a locate ticket; but, commented he's been in the business 20 years and never requested a locate. Excavator did not notify the gas operator of release of product until the following day, did not notify 911 nor the association as required by law.

**Conclusion:** There was a flagrant and reckless failure to provide notice of excavation.

**Violation: IC 8-1-26-16(g) Failure to provide notice of excavation.**



# DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 03-29-2013

## Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

## Excavator Information, if known

Full name: C & R Concrete Contractors, Inc.

Business address (number and street): 3219 E Tulip Court

City, State, and ZIP code: Indianapolis, IN 46227

Telephone number (area code): Unknown

Fax number (area code): Unknown

E-mail address: Unknown

## Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Data Not Collected

Type of work performed: Driveway

---

**Date and Location of Damage**

Date of damage (month, day, year): 2-7-2013

County: Hendricks

City: Brownsburg

Street address (number and street, city, state, and ZIP code):  
1600 Red Sunset Drive, Brownsburg, IN

Nearest intersection: Unknown

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (in hours): 1

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 794.8

---

**Affected Facility Information**

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? \_\_\_\_\_

---

**Notification, Locating, Marking**

Did excavator request locates prior to commencing work? No

Enter Indiana 811 ticket number, if known: \_\_\_\_\_

Was the locate request completed within two working days? No

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? No

Type of markings used: Other

If other, please specify: None

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? No

Did the excavator notify Indiana 811 in the event of this damage? No

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

### **Description of Cause**

Select from the list the most accurate cause for the damage: --No notification made to the one-call center

---

### **Additional Comments**

1" plastic service severed by skid steer. Did Not request locates.

Flags in photos are from service installation (Jan, 2013) and damage ticket called in by Vectren.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

NOW DUE


\$794.80

C & R CONCRETE  
3219 E TULIP COURT,  
INDIANAPOLIS, IN 46227

PAID

Type: GAS  
Invoice: FDS0017455  
BillToID: 33016  
Billing Date: 2/27/2013  
Date of Loss: 2/7/2013  
5953 103.0510

Please return this portion with your remittance.



Mail Payment To:  
Vectren Utilities Holdings Group, Inc.  
1239 Reliable Parkway  
Chicago, IL 60686-0012  
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5  
Risk Management/Claims Department

NOW DUE  
\$794.80

C & R CONCRETE  
3219 E TULIP COURT,  
INDIANAPOLIS, IN 46227

Type: GAS  
Invoice: FDS0017455  
BillToID: 33016  
Billing Date: 2/27/2013  
Date of Loss: 2/7/2013

**Invoice For Costs to Repair and Reconstruct Damaged Property**

Address: 1600 RED SUNSET DR, BROWNSBURG

1" PLASTIC SERVICE SEVERED BY SKIDSTEER. DID NOT REQUEST LOCATES OR HAND EXPOSE.

*Paid \$700.00  
Negotiated \$ 94.80  
8794.80*

*3/20/13  
3/20/13*

Material:	\$56.13
Company Labor:	\$455.54
Contract Labor:	\$0.00
Transportation/Equipment:	\$283.13
Misc:	\$0.00
Gas Loss:	\$0.00
Adjustments:	\$0.00
Payments:	\$0.00
<b>Total:</b>	<b>\$794.80</b>

*\$700.00* 5953 103.0510

*3/13  
Jackie  
317-784-8100  
left vm*

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

Task No: 103.0510 Capital / O & M (circle one)  
Date of Damage 2 / 6 / 13  
Cost Center # 5953  
Time Occurred 3:00 am / pm  
Time Found 8:00 AM 2/7/13 am / pm  
Latitude 39.849430 Longitude: -86.424780

Vectren Claim Number: \_\_\_\_\_

Police Report / MO #: \_\_\_\_\_

Vectren Claims Camera:

# FACILITIES DAMAGE REPORT GAS

VE00358  
Form 3000

**DAMAGE SITE:**

Address 1600 REDSUNSET DR Lot # \_\_\_\_\_

County HENDRICKS City BROWNSBURG State IN Township \_\_\_\_\_

**FACILITY TYPE:**

- Distribution  Propane
- Service  Storage
- Transmission: (include supplemental report)

**FACILITIES DAMAGED:**

	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	Other			

927

**TYPE OF MATERIAL:**

- Cast Iron
- Plastic (HDPE)
- Plastic (MDPE)
- Steel
- Other \_\_\_\_\_

**DAMAGE TYPE:**

- Severed
- Not Cut
- Severed
- Size 1 x 1

**PRESSURE:**

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 55 PSIG
- 60 PSIG
- 6 WC (.2163)
- 7 WC (252)
- Other \_\_\_\_\_

**PROTECTION IN PLACE:**

- Building  Fence  None
- Post  Rail  Vault  N/A
- Other \_\_\_\_\_

**DURATION OF ESCAPING GAS:**

Minutes: 0

**LEAK REPORT**

NUMBER: wo 9458692

EFV Activated  Yes  No  N/S

Number of Customers Affected: 1  
Total Hours Service \_\_\_\_\_  
Was Off: \_\_\_\_\_

**SERVICE ORDER NUMBER:** \_\_\_\_\_

**DAMAGED BY:**

- Company Crew
- Contractor
- County
- Developer
- Farmer
- Municipality
- Property Owner/ Tenant
- Railroad
- State
- Unknown
- Utility
- Vehicle Accident
- Other \_\_\_\_\_

**TYPE OF CONSTRUCTION:**

- Agriculture
- Building Construction
- Building Demolition
- Cable TV
- Curbs / Sidewalk
- Drainage
- Driveway
- Electric
- Engineering / Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Pole
- Natural Gas
- Public Transit Authority
- Railroad Maintenance
- Other \_\_\_\_\_

**WORKING FOR:**

- City  County  Developer
- State  Property Owner
- Utility

**VISUAL OBSERVATION AT DAMAGE SITE:**

- Visual Observation:  Above Ground  Below Ground
- Locate Applicable  Yes  No  N/S
- Facilities Properly Marked  Yes  No  N/S
- Marking Methods:  Conventional  Flags  None  Whiskers
- Offset  Paint  Stakes
- Locate Marking Faded:  Yes  No  N/S
- Wrong Address Requested  Yes  No  N/S

**Facilities Improperly Located:**

- Qualified Locator Could Not Have Accurately Located
- Inaccurate Maps / Cards
- Broken or No Tracer Wire (Plastic)
- Insulation Preventing Accurate Locate

**Locator Error:**

- Failure to Follow Policy
- Inappropriate Site Markings
- Incomplete Locate
- No Locates Performed
- Qualified Locator Could Have Accurately Located
- Wrong Address Located
- Marking Off By: \_\_\_\_\_ (Feet / Inches)

- Were Facility Marks Visible  Yes  No
- Was Area White Lined  Yes  No  Destroyed
- Positive Response  Yes  No  Destroyed
- Tolerance Zone Violated  Yes  No
- Part of Project  Yes  No
- Company Representative On-Site  Yes  No

Observation by (ID#): 5563

Name of Locator: \_\_\_\_\_

**LOCATING ORGANIZATION:**

- Contract Locator
- Unknown / Other
- Utility Owner

**NO LOCATE REQUESTED**

**NOTIFICATIONS AND OTHER DETAILS OF LOCATE:**

Locate Ticket: \_\_\_\_\_  
Date: \_\_\_\_\_ Time: \_\_\_\_\_ am / pm

**TYPE OF REQUEST:**

- Regular Request  Emergency Request
- Locate Company Notified
- Contact Name: \_\_\_\_\_
- Time Called: \_\_\_\_\_ am / pm
- Time Locator Arrived at the Site: \_\_\_\_\_ am / pm

Company Notified of Locate Near Critical Facilities  
 Yes  No  N/S

Copy of Mark Out Request Provided Within 2 Working Days  
 Yes  No  N/S

**ONE-CALL CENTER:**

- TUPPS
- OUPS
- Unknown

REC 1 5 2013

Vectren Claim Number: \_\_\_\_\_

**TYPE OF EQUIPMENT:**

- Auger
- Backhoe / Track hoe (SKIDSTEER)
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle

**ROOT DAMAGING CAUSE:**

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided

**CONTRACTOR REPAIRS:**

- Contractor Working for Vectren Made Repairs at Own Expense
  - Yes  No  N/S
- Contractor Repaired Damage
  - Yes  No  N/S

Name of Contractor: \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 # of Overtime Hours; \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 Crew Type: \_\_\_\_\_

**MATERIALS OR ROAD WORK:**

- Meter was replaced \_\_\_\_\_ (Stores Code)
- Regulator Was Replaced \_\_\_\_\_ (Stores Code)
- Temporary Asphalt Repair: \_\_\_\_\_ (sq. ft.)
- Permanent Asphalt Repair: \_\_\_\_\_ (sq. ft.)

**RIGHT OF WAY:**

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

Other \_\_\_\_\_  Other \_\_\_\_\_

Did Excavator Notify You  Yes  No

Excavation Required  Yes  No

Media at Site  Yes  No

Was There Ignition of Gas?  Yes  No

INVOICE:  Yes  No  N/S

**DAMAGING PARTY:**  
 Name: C & R CONCRETE  
 Address: 3219 E. Tulip DR  
 City/ State/ Zip: INDpls 46227  
 Phone: (317) 784-8100  
M. HENDERSON 2/7/13  
 Prepared / Investigated By: \_\_\_\_\_ Date: \_\_\_\_\_

**PARTY TO INVOICE:**  
 Name: SAME  
 Address: \_\_\_\_\_  
 City/ State/ Zip: \_\_\_\_\_  
 Phone: (\_\_\_\_\_) \_\_\_\_\_  
[Signature] 2-8-13  
 Reviewed by Field Supervisor: \_\_\_\_\_ Date: \_\_\_\_\_

CONTRACTOR ONSITE ADVISED THAT SERVICE WAS HIT ON 2/6/13 IN AFTERNOON AROUND 3PM. WHEN THEY ARRIVED BACK ONSITE 2/7/13 THEY SMELLED GAS BY ROSSIE GRANT WHO DID NOT CALL AND CALLED FOR REPAIR. ADVISED THAT THEY DID NOT HAVE A LOCATE # AND THEY HAVE DONE THIS FOR 25 YEARS AND "NEVER" GET LOCATES.







## Service Order Status

Monday, February 18, 2013

## Enter Service Order Number:

5515069



Print View

Refresh Data

Banner Instance:  CS03PROD  CS01PROD  CS02PROD

Order Number: N5515069 \*\*\* Needs Review \*\*\*

Order Type: LEAK

Order Status: Completed

Customer: 600069542 - DREES PREMIER HOMES

Prem: 5729378 - 1600 RED SUNSET DR

Technician: 2256 - Godfrey, Gary

## Order Dates and Times

Need Date: 2/7/2013 8:11:00 AM  
 Time Created: 2/7/2013 7:47:11 AM  
 Time Dispatched: 2/7/2013 7:47:11 AM  
 Time In Route: 2/7/2013 7:50:04 AM  
 Time On-Site: 2/7/2013 7:56:28 AM  
 Tech Complete: 2/7/2013 9:16:17 AM  
 Time Closed: 2/7/2013 9:16:17 AM

## Events Performed/Completion Code

LKOT - CMP

## Meter Information

## Current ReadStatus

Old Meter: 0229 Active  
 New Meter:

## Completion Notes

MAP # 46-111 1" LINE CUT , CREW REPAIRED. I DID R  
 ELIGHT. LEFT OK ! "0229" G.GODFREY

## Request Notes

2/7/13- PER EDDIE WALTER W/ DREES HOMES/ CELL PH# 317-714-2975/ HOME UNDER CONST/ DUG 2/6 TO LAY CON  
 CRETE/ GAS ODOR OS NEAR STREET/ HISS OR BLOW?/ NO GAS ENTER INSIDE/ X-RD- 600E/ US36/ NO PETS/ METER  
 OS/ ADV PREC/ ON SITE..

## MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	2/7/2013 7:48:06 AM	Godfrey, Gary
AsnAssignmentEnRoute_evt	2/7/2013 7:50:04 AM	Godfrey, Gary
AsnAssignmentOnSite_evt	2/7/2013 7:56:28 AM	Godfrey, Gary
OrdOrderComplete_evt	2/7/2013 9:16:17 AM	Godfrey, Gary

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

# Ticket Detail: 1302070151



ATTIN Seq: 78 Transmitted: Thu Feb 07 07:24:13 CST 2013

SBCIN 00077 IUPPSa 02/07/2013 08:22:43 1302070151-00A EMER NEW STRT

EMERGENCY EMERGENCY

Ticket : 1302070151 Date: 02/07/2013 Time: 08:16 Oper: KCUNNINGHAM Chan:001

State: IN Cnty: HENDRICKS Twp: LINCOLN  
Cityname: BROWNSBURG Inside: N Near: Y  
Subdivision: ARBOR SPRINGS Lot: 40

Address : 1600  
Street : REDSUNSET DR  
Cross 1 : KELLEY LN Within 1/4 mile: Y  
Location: LOCATE ENTIRE FRONT OF THE PROPERTY  
:  
Grids : 3950A8625B 3950A8625C 3951D8625B 3951D8625C  
Boundary: n 39.850328 s 39.849225 w -86.427354 e -86.424734

Work type : REPAIR CUT GAS SERVICE  
Done for : VECTREN  
Start date: 02/07/2013 Time: 08:19 Hours notice: 0/000 Priority: EMER  
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y  
Duration : 1 DAY Depth: 3 FEET

Company : VECTREN Type: MEMB  
Co addr : 1995 E MAIN ST  
City : DANVILLE State: IN  
Caller : GARY GODFREY Phone: (317)718-3603  
Contact : GARY GODFREY - CELL Phone:  
BestTime:  
Mobile : (317)341-0988

Remarks : All tickets are taken and processed on Eastern Daylight Time  
CREW EN ROUTE  
Will you be white-lining the dig site area? YES  
:

Submitted date: 02/07/2013 Time: 08:16  
Members: ID0002 ID2020 ID4471 ID5291 ID5473 ID6921 ID9999 SBCIN SM

-----  
Email\_From: att-tickets@tickets.translore.com  
Email\_Subject: ATT Translore - 1302070151  
Email\_Sent\_Date: 2013-02-07 07:24:13 CST  
Email\_MessageID: <1360243453853.1123930971.TransLore.att-tickets@tickets.translore.com>  
Email\_host: tickets6.811tickets.com  
Email\_user: 811.in.att  
Email\_To: 811.in.att@tickets.811tickets.com  
Email\_ContentType: text/plain; charset=ISO-8859-1

Ticket Detail: 1302070151



Ticket Position: 39.8497765,-86.4260440

Ticket Detail: 1302070151



Attachments

Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	20130207093223_IM G8675.jpg	Feb 7, 2013 8.49 AM CST	Manship, Chad	2/7/13 9:32 AM	



Property of United States Infrastructure Corporation  
Photo taken on 2/7/2013 9:32:23 AM

# Ticket Detail: 1302070151



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	20130207093226_IM G8676.jpg	Feb 7, 2013 8.51 AM CST	Manship, Chad	2/7/13 9:32 AM	



Property of United States Infrastructure Corporation  
Photo taken on 2/7/2013 9:32:26 AM

Ticket Detail: 1302070151



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	20130207093229_IM G8677.jpg	Feb 7, 2013 8:47 AM CST	Manship, Chad	2/7/13 9:32 AM	



Property of United States Infrastructure Corporation  
Photo taken on 2/7/2013 9:32:29 AM

Ticket Detail: 1302070151



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	20130207093232_IM G8678.jpg	Feb 7, 2013 8.48 AM CST	Manship, Chad	2/7/13 9:32 AM	



Property of United States Infrastructure Corporation  
Photo taken on 2/7/2013 9:32:32 AM

Ticket Detail: 1302070151



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	20130207093235_IM G8679.jpg	Feb 7, 2013 8:47 AM CST	Manship, Chad	2/7/13 9:32 AM	



Property of United States Infrastructure Corporation  
Photo taken on 2/7/2013 9:32:35 AM

Ticket Detail: 1302070151



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	20130207093238_IM G8680.jpg	Feb 7, 2013 8:47 AM CST	Manship, Chad	2/7/13 9:32 AM	



Property of United States Infrastructure Corporation  
Photo taken on 2/7/2013 9:32:38 AM

Ticket Detail: 1302070151



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	20130207093244_IM G8681.jpg	Feb 7, 2013 8:47 AM CST	Manship, Chad	2/7/13 9:32 AM	



Property of United States Infrastructure Corporation  
Photo taken on 2/7/2013 9:32:44 AM

Ticket Detail: 1302070151



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	20130207093248_IM G8682.jpg	Feb 7, 2013 8:47 AM CST	Manship, Chad	2/7/13 9:32 AM	



Property of United States Infrastructure Corporation  
Photo taken on 2/7/2013 9:32:48 AM

# Ticket Detail: 1302070151



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1302070151	callout_2013-02-07- 07-30-03.mp3	Feb 7, 2013 7.40 AM CST	Manship, Chad		
Ticket 1302070151	response_sent_68845 472.txt	Feb 7, 2013 9.00 AM CST	System		
Ticket 1302070151	response_sent_68846 923.txt	Feb 7, 2013 9.09 AM CST	System		
Ticket 1302070151	response_sent_68848 049.txt	Feb 7, 2013 9.17 AM CST	System		



## INFORMATION REQUEST

State Form 54909 (R / 3-13)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

**Case Number:** 4554 \_\_\_\_\_

**Date of Damage** (*month, day, year*): 02/07/13 \_\_\_\_\_

---

### Location of Damage:

Address (*number and street*): 1600 Red Sunset Drive \_\_\_\_\_

City, State and ZIP Code: Brownsburg, IN \_\_\_\_\_

Nearest Intersection: Northfield Drive & US 136 \_\_\_\_\_

---

### Excavator Information:

Business Name: C & R Concrete Contractors, Inc. \_\_\_\_\_

Responsible Party Personal Name: Rossi Grant \_\_\_\_\_

Title (*if any*): Operations Manager \_\_\_\_\_

Address (*number and street*): 3219 E. Tulip Drive \_\_\_\_\_

City, State and ZIP Code: Indianapolis, IN 46227 \_\_\_\_\_

Preferred Telephone Number (area code): 317-784-8100 \_\_\_\_\_

Email Address: rag3219@comcast.net \_\_\_\_\_

---

### Utility Information:

Utility Name: Vectren Utilities Holding Group, Inc. \_\_\_\_\_

Contact Person: Josh West \_\_\_\_\_

Title (*if any*): \_\_\_\_\_

---

**Cause of Damage Information**

Type of Equipment (*select one*):

Type of Work Performed (*select one*):

Repair Cost: \$ 700.00

Did a leak result from damage:  Yes  No

Was there ignition:  Yes  No

Excavator Notify 911 due to leak:  Yes  No

Excavator Notify 811 upon damage:  Yes  No

Excavator Notify Utility upon Damage:  Yes  No

---

**Locate Information**

Excavator Request Locate:  Yes  No

Indiana 811 Locate Ticket Number: \_\_\_\_\_

Locate Marks Visible:  Yes  No

Locate Marks Correct:  Yes  No

Excavator "White Lined":  Yes  No

Was Locate Provided within Two (2) Working Days:  Yes  No

Utility Employees On-site during Excavation:  Yes  No

---

**Incident Information:**

Fire Department Response:  Yes  No

Police Department Response:  Yes  No

Ambulance Response:  Yes  No

**Additional Information / Comments**

Gas lines in Indiana are suppose to be a minimum of 18" to 24" below the surface. The gas line we hit was only 2"-3" below the surface. There were no visible locate markings in the area we were cutting out the driveway. Since we are working for a new home builder we have always waived the responsibility for calling 811 and obtaining the locates to them (prehaps incorrectly). When we are on non-builder jobs we call for locates.

Vectren took pictures of the gas line, from the pictures you should be able to see thier relationship to the surface.

Printed Name: Richard Grant, President

Signature:  Date (month, day, year): 06/03/13

*\*If submitting this form electronically, typing your name in the signature box will act as an electronic signature.*

**Please return completed form to:**

[PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)

**Or mail to:**

**Indiana Utility Regulatory Commission  
Pipeline Safety Division - Case Number 4554  
101 West Washington Street, 1500E  
Indianapolis, IN 46204**

**Or fax to:  
317-233-2410**