



Pipeline Safety Division Investigation Report

Investigation regarding: Gatlin Plumbing

UPPAC Database Record ID: 4592

Report Date: 9/16/2013

Investigator: Mike Orr

Damage Date: 4/2/2013 2:28:12 PM

Damage Address: E 35th Ave, Hobart, Lake

The Parties

Excavator: **Gatlin Plumbing**

Address: 1111 East Main Street, Griffith, In 46319

Facility Owner: **NIPSCO**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes
3/18/2013

Indiana 811 Ticket Number: 1303141459

Original Start Date:

Locate Instructions: FROM THE ABOVE INTERSECTION TRAVEL GOING WEST ON EAST 35TH AVENUE FOR APPROX 750 FEET--THEN LOCATE GOING WEST ALONG BOTH SIDES OF EAST 35TH AVENUE INCLUDING THE RIGHT OF WAYS AND ENTIRE ROADWAY FOR APPROX 750 FEET

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas service while performing water work.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 5/29/2013. Excavator had a valid locate ticket; however, the gas operator self reported a failure to provide facility locate markings.

Conclusion: There was a failure to provide facility locate markings.

Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.



150 West Market Street, Suite 600
Indianapolis, IN 46204

May 31, 2013

[Via Electronic Transmission – PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)

Pipeline Safety Division – Case No. 4592
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 4592

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 4/2/2013

Event Location: E 35th Ave

City: Hobart

Facility Owner: Nipsco

Excavator: Gatlin Plumbing

Other Party: N/A

Pipeline Division Case No. 4592

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 4592	
Date of Event	4/2/2013
Event Location	E 35th Ave
Event City	Hobart
Facility Owner	Nipsco
Excavator	Gatlin Plumbing
Date of IURC Information Request	May 1, 2013
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	Gatlin Plumbing
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	1111 East Main Street
CITY/ STATE/ZIP	Griffith / IN / 46319
PREFERRED TELEPHONE	(219)924-6972
CELL PHONE TELEPHONE	(219)798-3788
EMAIL ADDRESS	gatlinplumbing@comcast.net
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	3107 35 th Avenue
CITY/STATE/ZIP	Lake Station / IN / 46405
NEAREST INTERSECTION	Liverpool Road
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	3/4"
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	X
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	
Probing Device	

Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	X
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y – 1304022611
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1303141459
LOCATE MARKS VISIBLE (YES/NO)	N
LOCATE MARKS CORRECT (YES/NO)	N/A
EXCAVATOR "WHITE LINED" (YES/NO)	Y
MAPS USED TO MARK FACILITIES (YES/NO)	N
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	Y
POLICE DEPARTMENT RESPONSE (YES/NO)	N/A
AMBULANCE RESPONSE (YES/NO)	N/A
ADDITIONAL INFORMATION/COMMENTS	
<p>Facility was not located or marked.</p> <p>Emergency ticket# 1304022813.</p>	

Facility: Distribution Lines; Folder: N/A; Assigned To: USIC

NIPSCO 00456 IUPPSa 03/14/2013 12:29:07 1303141459-00A NORM NEW GRID

NORMAL NOTICE

Ticket : 1303141459 Date: 03/14/2013 Time: 12:23 Oper: JSMITH Chan:088

State: IN Cnty: LAKE Twp: HOBART
Cityname: LAKE STATION Inside: Y Near: N
Subdivision:

Address :

Street : E 35TH AVE

Cross 1 : LIVERPOOL RD Within 1/4 mile: Y

Location: FROM THE ABOVE INTERSECTION TRAVEL GOING WEST ON EAST 35TH AVENUE FOR APPROX 750 FEET--THEN LOCATE GOING WEST ALONG BOTH SIDES OF EAST 35TH AVENUE INCLUDING THE RIGHT OF WAYS AND ENTIRE ROADWAY FOR APPROX 750 FEET

:

Grids : 4133C8717A 4133C8718D

Boundary: n 41.555273 s 41.554159 w -87.300597 e -87.296345

Work type : INSTALLING WATER MAIN

Done for : NEW CHICAGO WATER WORKS

Start date: 03/18/2013 Time: 12:45 Hours notice: 96/048 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N

Duration : 1 MONTH Depth: 5 FEET

Company : GATLIN PLUMBING Type: CONT

Co addr : 1111 EAST MAIN STREET

City : GRIFFITH State: IN Zip: 46319

Caller : MATT MURPHY Phone: (219)924-6972

Contact : AARON GRAHAM--NEW CELL 03/14/ Phone:

BestTime:

Mobile : (219)798-3788

Fax : (219)924-1401

Email : GATLINPLUMBING@COMCAST.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time

Will you be white-lining the dig site area? YES

:

Submitted date: 03/14/2013 Time: 12:23

Members: COMCN ID1158 ID5769 ID8000 NIPSCO SM

Facility: Transmission Lines; Folder: GM & T tickets; Assigned To: N/A

NIPSCO 00859 IUPPSa 04/02/2013 14:28:12 1304022611-00A EMER DAMG GRID

DAMAGE SEE REMARKS

Ticket : 1304022611 Date: 04/02/2013 Time: 14:25 Oper: LWORTON Chan:062

State: IN Cnty: LAKE Twp: HOBART
Cityname: LAKE STATION Inside: Y Near: N
Subdivision:

Address :
Street : E 35TH AVE
Cross 1 : LIVERPOOL RD Within 1/4 mile: Y
Location: FROM THE ABOVE INTERSECTION TRAVEL GOING WEST ON EAST 35TH AVENUE FOR
APPROX 750 FEET--THEN LOCATE GOING WEST ALONG BOTH SIDES OF EAST 35TH AVENUE
INCLUDING THE RIGHT OF WAYS AND ENTIRE ROADWAY FOR APPROX 750 FEET
:
Grids : 4133C8717A 4133C8718D
Boundary: n 41.555273 s 41.554159 w -87.300597 e -87.296345

Work type : INSTALLING WATER MAIN
Done for : NEW CHICAGO WATER WORKS
Start date: 04/02/2013 Time: 14:25 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 MONTH Depth: 5 FEET

Company : GATLIN PLUMBING Type: CONT
Co addr : 1111 EAST MAIN STREET
City : GRIFFITH State: IN Zip: 46319
Caller : MATT MURPHY Phone: (219)924-6972
Contact : AARON GRAHAM--NEW CELL 03/14/ Phone:
BestTime:
Mobile : (219)798-3788
Fax : (219)924-1401
Email : GATLINPLUMBING@COMCAST.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time
HAS DAMAGED A GAS SERVICE LINE THAT BELONGS TO NIPSCO AT THE INTERSECTION OF
COLORADO AND 35TH ST--- LINE IS NOT BLOWING BUT GAS CAN BE SMELLED---- LINE IS
ONE INCH STEEL SERVICE LINE--- IS CALLING 911--- CREW IS ON SITE--- WILL CALL
NIPSCO TO REPORT THE DAMAGE--- PREVIOUS TICKET #1303141459--- THANK YOU
Will you be white-lining the dig site area? YES
:

Submitted date: 04/02/2013 Time: 14:25
Members: COMCN ID1158 ID5769 ID8000 NIPSCO SM

Facility: Transmission Lines; Folder: GM & T tickets; Assigned To: N/A

NIPSCO 00898 IUPPSa 04/02/2013 14:58:22 1304022813-00A EMER NEW STRT

EMERGENCY SEE REMARKS

Ticket : 1304022813 Date: 04/02/2013 Time: 14:54 Oper: CWATSON Chan:052

State: IN Cnty: LAKE Twp: HOBART
Cityname: LAKE STATION Inside: Y Near: N
Subdivision:

Address :

Street : E 35TH AVE

Cross 1 : COLORADO ST Within 1/4 mile: Y

Location: LOCATE A 200 FOOT RADIUS OF THE ABOVE INTERSECTION

:

Grids : 4133C8717A 4133D8717A

Boundary: n 41.555242 s 41.554144 w -87.298484 e -87.297022

Work type : REPAIR GAS LINE

Done for : NIPSCO

Start date: 04/02/2013 Time: 14:55 Hours notice: 0/000 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 1 DAY Depth: 6 FEET

Company : NIPSCO Type: MEMB

Co addr : 801 EAST 86TH AVENUE

City : MERRILLVILLE State: IN Zip: 46410

Caller : TANECIA GHOLSTON Phone: (800)322-2806

Contact : STEVE TAYLOR---CELL Phone:

BestTime:

Mobile : (219)314-9567

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW ON SITE

Will you be white-lining the dig site area? NO

:

Submitted date: 04/02/2013 Time: 14:54

Members: COMCN ID1158 ID5769 ID8000 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA 150 MAXIMO WO # _____

OPERATING AREA CONTACT WHEELER STANLEY JOB ORDER # 477204

TRACKING NUMBER 018-2013-0402-004 LOCATE REF # 1303141459
Locate Performed By: USFC

DATE AND TIME OF ACCIDENT 4-2 13:30 PM DATE OF REPORT 4-2-13

PLACE OF DAMAGE (INCLUDE CITY) LAKE STATION 35th COLOADO

DAMAGE WAS TO:
ELECTRIC - POLE / TRANSFORMER: # _____ SIZE _____ YEAR INSTALLED _____ BROKEN YES () NO ()

OTHER (DESCRIBE) _____

GAS: SERVICE MAIN () SIZE 3/4" MATERIAL: PLASTIC () STEEL METER () REG STATION () STUB ()
OTHER (DESCRIBE) _____

DEPTH OF FACILITY (inches) 30" PRESSURE (PSI) 40-45 Lbs.

RELEASE OF GAS: YES NO () IGNITION OF GAS: YES () NO EVACUATION REQUIRED: YES () # _____ NO

INTERRUPTION OF SERVICE: YES NO () NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED 13:37 TIME RESTORED 07:30
4/2/13 4/13/13

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 1/2" HOLE IN MAIN

LOCATE MARKS ON SITE: YES () DISTANCE BETWEEN FACILITY AND LOCATE MARKS _____ NO
HOW LOCATED: PAINT () FLAGS () BOTH () WHITE LINED

PARTY THAT CAUSED DAMAGES (NAME) USFC LOCATORS / (GATLIN PLUMBING)

ADDRESS OF PARTY (INCLUDE CITY) 111 E. MAIN STREET GRIFFITH IN 46319

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE ARON GAWM, GATLIN PLUMBING

WITNESS NAME AND ADDRESS 1111 E. MAIN ST. GRIFFITH IN. 46319

WITNESS REMARKS _____

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY _____ REPORT # _____

FIRE AGENCY CARE STATION REPORT # _____

OTHER () _____ Any Injuries? () YES # K X NO

PHOTOS TAKEN: YES () NO () TAKEN BY: _____ (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES () NO

WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW
() AGRICULTURE/FARMING () CABLE TV () CURB/SIDEWALK
() BLDG CONSTRUCTION () DEMOLITION () DRAINAGE
() DRIVEWAY () ELECTRIC () SURVEYING
() FENCING () GRADING () IRRIGATION () MILLING
() LANDSCAPING () PIPELINE () ROAD WORK () SEWER
() POLE/SIGN POST

TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW
() AUGER () HAND TOOLS () BACKHOE/TRACKHOE
() MILLING EQUIPMENT () PROBING DEVICE () BORING / DRILLING
() EXPLOSIVES () TRENCHER () FARM EQUIPMENT
() VACCUUM EQUIPMENT () GRADER () OTHER

REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW
() AUTOMOTIVE ACCIDENT () EXCAVATING BEFORE LOCATES DUE () CARELESS MACHINE OPERATOR
() NO NOTIFICATION () MARKS DISTURBED () STUB () OTHER BAD LOCATE

• SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM

Fact Based Investigation Report

Notification ID 01820130402004
Damage Date 04/02/2013 14:28
Notified By MATT MURPHY ()
Damage Address E 35TH AVE
LAKE STATION, IN
District Northern Indiana
Notification Date 04/02/2013
14:35

Damaged Customer NIPSCO

Investigation Date From 04/02/2013 14:05:00 **To** 04/02/2013 14:30:00

Excavator Involved GATLIN PLUMBING
Type of Excavation Water Main Project

Orig. Locate Request 1303141459 **Start Date**
Type of Ticket **Locate Req. Info** N/A

Damage Request # 1304022611 **Start Date** 04/02/2013 14:25

Pictures Taken By Scott Day **Date** 04/02/2013 14:15
Photography Type Digital **Frame #** 1

Investigator Emp. # 131986 **Investigator Name** Scott Day
Based on your investigation, is further investigation needed? Possibly

Fact Based Investigation Customer Information
Facility Description Low Profile **Facility ID** Gas Service
Locator Name & EMP # Day Scott - 131986 **Locator Not Known**

Investigation Findings

Other
Other Notes
Line not marked

Investigation Methods

Investigation Results Verified By Utility Representative
Investigator Verified Existing Marks By Hooking Up
Visual, Facility Exposed At Time Of Investigation

Investigator Statement/Causal Factors

This is part of a large ongoing project that Scott is working on. Steel gas service for this address was damaged in front. Was not blowing but may have been pulled out of fitting or Tee. No markings were done on this gas service.

Names of Utility Representatives Contacted or on Site and Statement

Nipsco on site for repairs. No statements.

Names of Excavator's Representatives Contacted or on Site and Statement

Contractor in area working. No statements

Other individuals on site

Scott stated that he doesn't know why he missed this one. Everything else around it was marked.

Were any markings visible on the damage site upon arrival?	No
Were any other indicators of facility present in the area?	No
Was the excavation within the tolerance zone of marks?	No
Extent of facility damage	damaged steel gas service
Replacement Footage	N/A
Was contractor assistance required? If yes, who?	No
What contractor equipment was used?	Backhoe
Is the facility shown on the utility records?	No
If yes, list record numbers	



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

May 1, 2013

Matt Murphy
Gatlin Plumbing
1111 East Main Street
Griffith, In 46319

**Re: Notice of Preliminary Determination of Violation
Pipeline Safety Division Case No. 4592**

Date of Event: 4/2/2013
Event Location: E 35th Ave, Hobart, Lake County
Excavator: Gatlin Plumbing
Facility Owner: Nipsco

MAY 7 2013

Dear Matt Murphy,

On behalf of the Indiana Utility Regulatory Commission ("Commission"), I am writing to inform you that information has been filed with the Commission's Pipeline Safety Division regarding an alleged violation of Indiana Code chapter 8-1-26, the Indiana Damage to Underground Facilities Act ("the Act"). You are receiving this letter because you have been identified as the Respondent Excavator.

To ensure safety, the Indiana Underground Plant Protection Service (Indiana 811) and gas operators routinely provide reports to the Pipeline Safety Division when an operator's facility is damaged. The Division has received a report from one of these entities that on **4/2/2013**, you or your business damaged a pipeline facility owned by **Nipsco** and located at **E 35th Ave, Hobart, Lake County**.

Based upon the information received, the Pipeline Safety Division is commencing an investigation into the event concerning you or your business to determine whether any statutory violations were committed regarding public safety, specifically the following:

- IC 8-1-26-16(g): Failure to provide notice of excavation.
- IC 8-1-26-16(h): Failure to perform required white lining.
- IC 8-1-26-20(b): Failure to maintain two (2) feet clearance with mechanized equipment.
- IC 8-1-26-18(f): Failure to properly locate facilities (operator violation)

The Division provides both you and Nipsco with an opportunity to send in documentation explaining what occurred. This may include maps, photographs, narrative statements, and any other evidence you wish to provide. You have thirty (30) days from the date this letter is received to send in information, but an extension may be given for good cause shown. Please note that the Division's investigation will be completed after this time period, even if you do not respond or fail to provide

Information Request
Pipeline Safety Division
Indiana Utility Regulatory Commission

Case No. 4592

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information: Gatlin Plumbing & Heating, Inc.
Responsible Party Personal Name: Aaron Graham
Title (if any): Estimator / Project Manager
Address: 1111 E. Main Street
City, State Zip: Griffith, IN 46319-2897
Preferred Telephone: 219-924-6972
Cell Phone Number: 219-798-3788
Email Address: gatlinplumbing@comcast.net

Facility Information:

Business Name: Nipsco
Responsible Party Personal Name: Mary L. Lechowicz
Title (if any): Leader Facility Damages
Address: 801 E. 86th Avenue
City, State Zip: Merrillville, IN 46410-6271
Preferred Telephone: 219-647-4033
Cell Phone Number: Unknown
Email Address: www.nipsco.com

Locator Service Information:

Business Name: USIC
Responsible Party Personal Name: Unknown
Title (if any): Unknown
Address: Unknown
City, State Zip: Unknown
Preferred Telephone: Unknown
Cell Phone Number: Unknown
E-mail Address: Unknown

Other (Witness, Police, Fire, Other) Information:

Personal Contact: None

Business / Organization Name:

Title (if any): Unknown

Address: Unknown

City, State Zip: Unknown

Preferred Telephone: Unknown

Cell Phone Number: Unknown

E-mail Address: Unknown

Utility Line Impact:

Location of Damage: Lake County

Address: 3107 35th Ave

City, State Zip: Lake Station, IN

Nearest Intersection: 35th Ave. & Colorado St.

Product Type (circle one):

Natural Gas

Facility Type (circle one):

Service Line: 5/8" steel service line

Size (Diameter /etc): 5/8"

Pressure (PSIG/Inches): Unknown

Interruption in Service: Yes Number of Customers Affected: 1

Evacuation: No If yes, How Many Evacuated? None

Repair Cost (if known): N/A

Cause of Damage Information:

Type of Equipment : John Deere 200 Excavator

Type of Work Performed: Installing Water Main

Release of Product: Yes

Ignition and/or Fire: No

Excavator Notify 811: Yes

Locate Information:

Excavator Request Locate: Yes
Indiana 811 Locate Ticket Number: 1303141459
Locate Marks Visible: No
Locates Marks Correct: No
Excavator "White Lined": Yes
Maps Used to Mark Facilities: None
Was Locate Provided within Two (2) Working Days: Yes
Operator Employees On-site during Excavation: No

Incident Impact Information:

Number of Outpatient Treated: None
Number of Inpatient Treated: None
Number of Fatalities: None
Fire Department Response: Yes
Police Department Response: No
Ambulance Response: No

Additional Information:


We were installing water main east along the south side of 35th Ave. when an unmarked gas service was struck. The gas service was later identified and marked in white paint by the locator.(See attached photos)

Crew on site: Darl Gatlin, Jr. – Excavator Operator Edward Dunn – Loader Operator
Gerald Jackson, Jr. - Foreman Doyle Sayers – Laborer Joe Yankauskas - Laborer

YOUR PIPELINE SAFETY DIVISION CASE NO: 4592

YOUR FULL NAME: AARON GRAHAM
FULL NAME OF BUSINESS ENTITY: GATLIN PLUMBING & HEATING, INC.
YOUR BUSINESS TITLE: ESTIMATOR / PROJECT MANAGER
ADDRESS: 1111 E. MAIN STREET
CITY: GRIFFITH STATE: IN ZIP CODE: 46319
YOUR TELEPHONE NUMBER: 219-924-6972 CELL NO: 219-798-3788
YOUR EMAIL ADDRESS: GATLINPLUMBING@COMCAST.NET

TODAY'S DATE: May 28th, 2013

YOUR SIGNATURE: 

TITLE IF ANY: ESTIMATOR/PROJECT MANAGER

Please return your Narrative Statement and Answers to the above questions to:

Pipeline Safety Division – Case No. 4592
Indiana Utility Regulatory Commission
101 West Washington Street, #1500E
Indianapolis, IN 46204

Or scan document(s) and Email to:

PipelineDamageCase@urc.in.gov





NO PARKING
TOW AWAY ZONE

ADDITIONAL
WALL PARKING

EL
MOKEN





NO HALL PARKING
POST THIS POINT

ADDITIONAL
HALL PARKING