



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Robert Henry Corporation

UPPAC Database Record ID: 4884

Report Date: 9/25/2013

Investigator: Mike Orr

Damage Date: 5/31/2013 11:29:21 AM

Damage Address: Southwood Dr, North, Lake

The Parties

Excavator: **Robert Henry Corporation**

Address: 404 South Frances Street, South Bend, In 46617

Facility Owner: **NIPSCO**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Directional Drilling

Type of Work Performed: Electric

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes
5/20/2013

Indiana 811 Ticket Number: 1305160614

Original Start Date:

Locate Instructions: AT 9201 - 9211 - 9221 - 9229 AND 9237 SOUTHWOOD DR LOCATE THE ENTIRE PROPERTY AT ALL ADDRESSES

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas service while performing electric work.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 8/7/2013. Excavator had a valid locate ticket and the gas operator provided accurate locate markings; however, the excavator failed to maintain required clearance from the gas service with the directional boring rod.

Conclusion: There was a failure to maintain clearance with mechanized equipment within the tolerance zone.

Violation: IC 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.



150 West Market Street, Suite 600
Indianapolis, IN 46204

August 12, 2013

[Via Electronic Transmission – PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)

Pipeline Safety Division – Case No. 4884
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 4884

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 5/31/2013
Event Location: Southwood Dr
City: Indianapolis
Facility Owner: Nipsco
Excavator: Robert Henry Corporation
Other Party: N/A
Pipeline Division Case No. 4884

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

| IURC INFORMATION REQUEST | |
|---|---|
| Pipeline Safety Division Case No. 4884 | |
| Date of Event | 5/31/2013 |
| Event Location | Southwood Dr |
| Event City | North |
| Facility Owner | Nipsco |
| Excavator | Robert Henry Corporation |
| Date of IURC Information Request | July 12, 2013 |
| THE PARTIES | |
| EXCAVATOR: | |
| BUSINESS NAME | |
| RESPONSIBLE PARTY PERSONAL NAME | Robert Henry Corporation |
| TITLE (IF ANY) | |
| ADDRESS | 404 South Frances Street |
| CITY/ STATE/ZIP | South Bend, IN 46617 |
| PREFERRED TELEPHONE | 419 230 1924 |
| CELL PHONE TELEPHONE | |
| EMAIL ADDRESS | |
| FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE: | |
| BUSINESS NAME | NORTHERN INDIANA PUBLIC SERVICE COMPANY |
| RESPONSIBLE PARTY PERSONAL NAME | LUKE SELKING |
| TITLE | |
| ADDRESS | 1501 HALE AVENUE |
| CITY/STATE/ZIP | FORT WAYNE, IN 46802 |
| PREFERRED TELEPHONE | 260/439-1290 |
| SECONDARY TELEPHONE | |
| EMAIL ADDRESS | LSELKING@NISOURCE.COM |
| LOCATOR SERVICE INFORMATION | |
| BUSINESS NAME | USIC |
| RESPONSIBLE PARTY PERSONAL NAME | Morgan Thompson |
| TITLE (IF ANY) | Claims Coordinator |
| ADDRESS | 9045 N. River Rd. Suite 300 |
| CITY/ STATE/ZIP | Indianapolis, IN 46240 |
| PREFERRED TELEPHONE | 1-317-538-7301 |
| CELL PHONE TELEPHONE | Same |
| EMAIL ADDRESS | morganthompson@usicinc.com |
| OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION | |
| PERSONAL CONTACT | |
| BUSINESS/ORGANIZATION NAME | |
| TITLE (IF ANY) | |

| | |
|---------------------------------------|-----------------------|
| ADDRESS | |
| CITY/ STATE/ZIP | |
| PREFERRED TELEPHONE | |
| CELL PHONE TELEPHONE | |
| EMAIL ADDRESS | |
| UTILITY LINE IMPACT | |
| LOCATION OF DAMAGE | |
| ADDRESS | 9201 South Wood Drive |
| CITY/STATE/ZIP | Munster, IN, 46321 |
| NEAREST INTERSECTION | Oriole Dr |
| PRODUCT TYPE (Select One) | |
| NATURAL GAS | X |
| LIQUID PIPELINE | |
| UNKNOWN/OTHER | |
| FACILITY TYPE (Select One) | |
| DISTRIBUTION | |
| GATHERING | |
| SERVICE/DROP | X |
| TRANSMISSION | |
| UNKNOWN/OTHER | |
| SIZE (DIAMETER/ETC.) | 5/8" |
| PRESSURE (PSIG/INCHES) | |
| INTERRUPTION IN SERVICE (YES/NO) | Yes |
| NUMBER OF CUSTOMERS AFFECTED | 1 |
| EVACUATION (YES/NO) | No |
| IF YES, HOW MANY EVACUATED | |
| REPAIR COST (IF KNOWN) (\$) | |
| CAUSE OF DAMAGE INFORMATION: | |
| TYPE OF EQUIPMENT (Select One) | |
| Auger | |
| Backhoe/Trackhoe | |
| Boring/Drilling | |
| Directional Drilling | X |
| Explosives | |
| Farm Equipment | |
| Grader/Scraper | |
| Hand Tools | |
| Milling Equipment | |
| Probing Device | |

| | |
|--|---|
| Trancher | |
| Vacuum Equipment | |
| Unknown/Other | Click here to enter text. |
| TYPE OF WORK PERFORMED (Select One) | |
| Agriculture | |
| Cable TV | |
| Curb/Sidewalk | |
| Bldg. Construction | |
| Bldg. Demolition | |
| Drainage | |
| Driveway | |
| Electric | X |
| Engineering/Surveying | |
| Fencing | |
| Grading | |
| Irrigation | |
| Landscaping | |
| Liquid Pipeline | |
| Milling | |
| Natural Gas | |
| Pole | |
| Public Transit Authority | |
| Railroad Maintenance | |
| Road Work | |
| Sewer (Sanitary/Storm) | |
| Site Development | |
| Steam | |
| Storm Drain/Culvert | |
| Street Light | |
| Telecommunications | |
| Traffic Signal | |
| Traffic Sign | |
| Water | |
| Waterway Improvement | |
| Unknown/Other | |
| | |
| RELEASE OF PRODUCT (YES/NO) | Yes |
| IGNITION AND/OR FIRE (YES/NO) | No |
| EXCAVATOR NOTIFY 811 (YES/NO) | Yes 1305311438 |
| LOCATE INFORMATION: | |
| EXCAVATOR REQUEST LOCATE (YES/NO) | Yes |

| | |
|---|------------|
| INDIANA 811 LOCATE TICKET NUMBER | 1305160614 |
| LOCATE MARKS VISIBLE (YES/NO) | Yes |
| LOCATE MARKS CORRECT (YES/NO) | Yes |
| EXCAVATOR "WHITE LINED" (YES/NO) | No |
| MAPS USED TO MARK FACILITIES (YES/NO) | Yes |
| OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO) | No |
| INCIDENT IMPACT INFORMATION | |
| NUMBER OF OUTPATIENT TREATED | 0 |
| NUMBER OF INPATIENT TREATED | 0 |
| NUMBER OF FATALITIES | 0 |
| FIRE DEPARTMENT RESPONSE (YES/NO) | N/A |
| POLICE DEPARTMENT RESPONSE (YES/NO) | N/A |
| AMBULANCE RESPONSE (YES/NO) | N/A |
| ADDITIONAL INFORMATION/COMMENTS | |
| Excavator hit accurately marked facility NIPSCO Emergency Repair Ticket Number: 1305311540 | |

Fact Based Investigation Report

Notification ID 01820130531003
Damage Date 05/31/2013 11:29
Notified By KYLE JAKUBOWICV ()
Damage Address SOUTHWOOD DR
MUNSTER, IN
District Northern Indiana
Notification Date 05/31/2013 11:35

Damaged Customer NIPSCO

Investigation Date From 05/31/2013 14:05:00 **To** 05/31/2013 14:10:00

Excavator Involved ROBERT HENRY

Type of Excavation Directional bore

Orig. Locate Request 1305160614 **Start Date** 05/16/2013 19:10
Type of Ticket Routine **Locate Req. Info** N/A

Damage Request # 1305311438 **Start Date** 05/31/2013 14:05

Pictures Taken By Tony Wesley **Date** 05/31/2013 14:05

Photography Type Digital **Frame #**

Investigator Emp. # 134728 **Investigator Name** Tony Wesley

Based on your investigation, is further investigation needed? No

Fact Based Investigation Customer Information

Facility Description Low Profile **Facility ID** Gas Service

Locator Name & EMP # Belegal Phil - 117702 **Locator Not Known**

Investigation Findings

Facility Marked Accurately

Other Notes

Investigation Methods

Visual, Facility Exposed At Time Of Investigation

Investigator Statement/Causal Factors

Line was hit when Robert Henry was pulling back the bore rods. The line was potholed and exposed. This facility was marked correctly at the damage site and again was potholed from the original markings. Post locate photos can be found on ticket 1305160611 photos 1002420-1002423.

Names of Utility Representatives Contacted or on Site and Statement

Tommy Buher NIPSCO Field Coordinator

Names of Excavator's Representatives Contacted or on Site and Statement

n/a

Other individuals on site

n/a

Were any markings visible on the damage site upon arrival? Yes

Were any other indicators of facility present in the area? No

| | |
|---|-------------|
| Was the excavation within the tolerance zone of marks? | Yes |
| Extent of facility damage | cut service |
| Replacement Footage | 2' |
| Was contractor assistance required? If yes, who? | No |
| What contractor equipment was used? | |
| Is the facility shown on the utility records? | No |
| If yes, list record numbers | |

Facility: Transmission Lines; Folder: GM & T tickets; Assigned To: N/A

NIPSCO 00501 IUPPSa 05/31/2013 11:46:43 1305311540-00A EMER NEW STRT

EMERGENCY EMERGENCY

Ticket : 1305311540 Date: 05/31/2013 Time: 11:44 Oper: BMCWHORTER Chan:045

State: IN Cnty: LAKE Twp: NORTH
Cityname: MUNSTER Inside: Y Near: N
Subdivision:

Address : 9201
Street : SOUTHWOOD DR
Cross 1 : BLUEBIRD LN Within 1/4 mile: Y
Location: LOCATE--ENTIRE PROPERTY
:
Grids : 4132A8729A 4132A8730D 4132B8729A 4132B8730D
Boundary: n 41.547421 s 41.545211 w -87.500232 e -87.498742

Work type : REPAIRING GAS LINE
Done for : NIPSCO
Start date: 05/31/2013 Time: 11:45 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 DAY Depth: 8 FEET

Company : NIPSCO Type: MEMB
Co addr : 801 EAST 86TH AVENUE
City : MERRILLVILLE State: IN Zip: 46410
Caller : MARK DILOAS Phone: (800)322-2806
Contact : TONY SANCHEZ - CELL Phone:
BestTime:
Mobile : (219)742-5267

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW EN ROUTE
Will you be white-lining the dig site area? NO
:

Submitted date: 05/31/2013 Time: 11:44
Members: COMCN IB ID6978 NIPSCO SM

Facility: Transmission Lines; Folder: GM & T tickets; Assigned To: N/A

NIPSCO 00165 IUPPSa 05/16/2013 08:37:36 1305160614-00A NORM NEW GRID

NORMAL NOTICE

Ticket : 1305160614 Date: 05/16/2013 Time: 08:36 Oper: AGRIGGS Chan:074

State: IN Cnty: LAKE Twp: NORTH
Cityname: MUNSTER Inside: Y Near: N
Subdivision:

Address :
Street : SOUTHWOOD DR
Cross 1 : ORIOLE DR Within 1/4 mile: Y
Location: AT 9201 - 9211 - 9221 - 9229 AND 9237 SOUTHWOOD DR LOCATE THE ENTIRE
PROPERTY AT ALL ADDRESSES
***Boring Where = UNDER DRIVEWAYS AND YARDS
:
Grids : 4132A8729A 4132A8730D 4132B8729A 4132B8730D
Boundary: n 41.547779 s 41.544296 w -87.500170 e -87.498709

Work type : INSTALL NEW UNDERGROUND POWER
Done for : NIPSCO
Start date: 05/20/2013 Time: 08:45 Hours notice: 96/048 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
Duration : 2 WEEKS Depth: 5 FEET

Company : ROBERT HENRY CORPORATION Type: CONT
Co addr : 404 SOUTH FRANCES STREET
City : SOUTH BEND State: IN Zip: 46617
Caller : KYLE JAKUBOWICV Phone: (419)230-1924
Contact : MIKE WOODRUFF CELL Phone:
BestTime:
Mobile : (419)230-1924

Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? NO
:

Submitted date: 05/16/2013 Time: 08:36
Members: COMCN IB ID6978 NIPSCO SM

Facility: Transmission Lines; Folder: N/A; Assigned To: N/A

NIPSCO 00453 IUPPSa 05/31/2013 11:29:25 1305311438-00A EMER DAMG GRID

DAMAGE SEE REMARKS

Ticket : 1305311438 Date: 05/31/2013 Time: 11:24 Oper: KREED Chan:090

State: IN Cnty: LAKE Twp: NORTH
Cityname: MUNSTER Inside: Y Near: N
Subdivision:

Address :
Street : SOUTHWOOD DR
Cross 1 : ORIOLE DR Within 1/4 mile: Y
Location: AT 9201 - 9211 - 9221 - 9229 AND 9237 SOUTHWOOD DR LOCATE THE ENTIRE
PROPERTY AT ALL ADDRESSES
***Boring Where = UNDER DRIVEWAYS AND YARDS
:
Grids : 4132A8729A 4132A8730D 4132B8729A 4132B8730D
Boundary: n 41.547779 s 41.544296 w -87.500170 e -87.498709

Work type : INSTALL NEW UNDERGROUND POWER
Done for : NIPSCO
Start date: 05/31/2013 Time: 11:25 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y
Duration : 2 WEEKS Depth: 5 FEET

Company : ROBERT HENRY CORPORATION Type: CONT
Co addr : 404 SOUTH FRANCES STREET
City : SOUTH BEND State: IN Zip: 46617
Caller : KYLE JAKUBOWICV Phone: (419)230-1924
Contact : MIKE WOODRUFF CELL Phone:
BestTime:
Mobile : (419)230-1924

Remarks : All tickets are taken and processed on Eastern Daylight Time
HIT NIPSCO GAS SERVICE LINE - GAS IS BLOWING LIGHTLY UNDER WATER- IT CAN BE
SMELLED BUT NOT HEARD - LINE HIT IN THE REAR OF 9201 SOUTHWOOD DR - LINE IS 1/2
INCH PLASTIC - COLOR UNKNOWN - HAS NOT CALLED 911 BUT WAS ADVISED TO DO SO -
CREW ON SITE - WILL CALLED NIPSCO - PREVIOUS TICKET 1305160614 - THANK YOU
Will you be white-lining the dig site area? NO
:

Submitted date: 05/31/2013 Time: 11:24
Members: COMCN IB ID6978 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY

FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA Hammond MAXIMO WO # _____
OPERATING AREA CONTACT Tony Sanchez JOB ORDER # 552944
TRACKING NUMBER 01820130531003 LOCATE REF # 1305311540
Locate Performed By: _____

DATE AND TIME OF ACCIDENT 5-31-13 2013 10:36 AM DATE OF REPORT 5-31-13
PLACE OF DAMAGE (INCLUDE CITY) 9201 Southwood DR MUNSTER

DAMAGE WAS TO:
ELECTRIC - POLE / TRANSFORMER: # _____ SIZE _____ YEAR INSTALLED _____ BROKEN YES () NO ()

OTHER (DESCRIBE) _____

GAS: SERVICE MAIN () SIZE 5/8" MATERIAL: PLASTIC STEEL () METER () REG STATION () STUB ()
OTHER (DESCRIBE) _____

DEPTH OF FACILITY (Inches) 36" PRESSURE (PSI) 45 Lbs.

RELEASE OF GAS: YES NO () IGNITION OF GAS: YES () NO EVACUATION REQUIRED: YES () # _____ NO

INTERRUPTION OF SERVICE: YES NO () NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED 10:36 AM TIME RESTORED 15:30

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: cut in 2

LOCATE MARKS ON SITE: YES DISTANCE BETWEEN FACILITY AND LOCATE MARKS within 2' NO ()
HOW LOCATED: PAINT FLAGS BOTH () WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) Robert Henry Corp

ADDRESS OF PARTY (INCLUDE CITY) 574-232-2091

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE Kyle Jakubowicz

WITNESS NAME AND ADDRESS D. Findley - Hammond Gas. Bore shaft were hollow

WITNESS REMARKS 5/8" pl gas service that was exposed. Tony Sanchez expand that hole to make repair. 5-31-13 4:30pm.

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY _____ REPORT # _____

FIRE AGENCY MUNSTER REPORT # _____

OTHER () _____ Any Injuries? () YES # _____ NO

PHOTOS TAKEN: YES NO () TAKEN BY: Tommy Buher dpc (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES () NO

- WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW
- | | | | |
|--|--|--|---|
| <input type="checkbox"/> AGRICULTURE/FARMING | <input type="checkbox"/> CABLE TV | <input type="checkbox"/> CURB/SIDEWALK | <input type="checkbox"/> TELECOMMUNICATIONS |
| <input type="checkbox"/> BLDG CONSTRUCTION | <input type="checkbox"/> DEMOLITION | <input type="checkbox"/> DRAINAGE | <input type="checkbox"/> WATER |
| <input type="checkbox"/> DRIVEWAY | <input checked="" type="checkbox"/> ELECTRIC PRIMARY | <input type="checkbox"/> SURVEYING | <input type="checkbox"/> DRAINS/CULVERTS |
| <input type="checkbox"/> FENCING | <input type="checkbox"/> GRADING | <input type="checkbox"/> IRRIGATION | <input type="checkbox"/> MOWING |
| <input type="checkbox"/> LANDSCAPING | <input type="checkbox"/> PIPELINE | <input type="checkbox"/> MILLING | <input type="checkbox"/> OTHER _____ |
| <input type="checkbox"/> POLE/SIGN POST | <input type="checkbox"/> ROAD WORK | <input type="checkbox"/> SEWER | |

- TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW
- | | | |
|--|---|---|
| <input type="checkbox"/> AUGER | <input type="checkbox"/> HAND TOOLS | <input type="checkbox"/> BACKHOE/TRACKHOE |
| <input type="checkbox"/> MILLING EQUIPMENT | <input type="checkbox"/> PROBING DEVICE | <input checked="" type="checkbox"/> BORING / DRILLING |
| <input type="checkbox"/> EXPLOSIVES | <input type="checkbox"/> TRENCHER | <input type="checkbox"/> FARM EQUIPMENT |
| <input type="checkbox"/> VACCUUM EQUIPMENT | <input type="checkbox"/> GRADER | <input type="checkbox"/> OTHER _____ |

- REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW
- | | | |
|--|--|--|
| <input type="checkbox"/> AUTOMOTIVE ACCIDENT | <input type="checkbox"/> EXCAVATING BEFORE LOCATES DUE | <input type="checkbox"/> CARELESS MACHINE OPERATOR |
| <input type="checkbox"/> NO NOTIFICATION | <input type="checkbox"/> MARKS DISTURBED | <input type="checkbox"/> STUB |
| | | <input checked="" type="checkbox"/> OTHER <u>soil conditions were bad causing svc to drop onto bore head</u> |

• SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM

COMMENTS: Directional bore through service
line marked

PERSON PREPARING REPORT M GARD

FIELD SUPERVISOR Kellie Dunlap, Nick Vesci

FIELD MANAGER Rick Smith

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information

FOR OFFICE USE ONLY:

- | | | |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE | YES | NO |
| • NO IN 811 LOCATE CALLED IN | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST | YES | NO |

COMPLETED BY: _____ DATE: _____



Property of United States Infrastructure Corporation
Photo taken on 5/11/2011 11:47:04 AM



INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 4884

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.

Upon completion of answers select email button for submission.

The Parties

Excavator Information:

Business Name: THE ROBERT HENRY CORPORATION

Responsible Party Personal Name: KYLE JAKUBOWICZ

Title (if any): FOREMAN

Address (number and street): 404 S. FRANCES STREET

City, State and ZIP Code: SOUTH BEND INDIANA 46617

Preferred Telephone Number (area code): (574) 232-2091

Cellular Telephone Number (area code): _____

Email Address: jhenry@roberthenrycorp.com

Facility Information:

Business Name: NIPSCO GAS

Responsible Party Personal Name: _____

Title (if any): _____

Address (number and street): 801 E. 86TH ST.

City, State and ZIP Code: MERRILLVILLE INDIANA 46410

Preferred Telephone Number (area code): (219) 647-4033

Cellular Telephone Number (area code): _____

Email Address: _____

Locator Service Information:

Business Name: _____

Responsible Party Personal Name: _____

Title (if any): _____

Address (number and street): _____

City, State and ZIP Code: _____

Preferred Telephone Number (area code): _____

Cellular Telephone Number (area code): _____

Email Address: _____

Cause of Damage Information (SEE HIT REPORT PLEASE)

Type of Equipment (select one): POT HOLE WAS DUG EXPOSING GAS LINE, BUT GAS LINE WAS HIT WHEN PULLING BACK WITH DRILL ROD

Type of Work Performed (select one): INSTALLING PRIMARY ELECTRIC

Other Information (Witness, Police, Fire, Other):

Personal Contact: FOREMAN

Business/Organization Name: THE ROBERT HENRY CORPORATION

Title (if any): _____

Address (number and street): 404 S. FRANCES ST.

City, State and ZIP Code: SOUTH BEND INDIANA 46617

Preferred Telephone Number (area code): (574) 232-2091

Cellular Telephone Number (area code): _____

Email Address: jhenry@roberthencrycorp.com

Utility Line Impact

Location of Damage:

Address (number and street): 9201 Southwood Dr.

City, State and ZIP Code: MUNSTER, IN., FAIRMEADOWS SUBDIVISION

Nearest Intersection: _____

Product Type (select one):

Facility Type (select one):

Size (Diameter/etc.): ?

Pressure (PSIG/Inches): ?

Interruption in Service: Yes No Number of Customers Affected: 1

Evacuation: Yes No If yes, How Many Evacuated? 0

Repair Cost (if known): \$ _____

Release of Product: Yes No

Ignition and/or Fire: Yes No

Excavator Notify 811: Yes No

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1305160614

RELOCATE: 1305311438

- Locate Marks Visible: Yes No
- Locate Marks Correct: Yes No
- Excavator "White Lined": Yes No
- Maps Used to Mark Facilities: Yes No
- Was Locate Provided within Two (2) Working Days: Yes No
- Operator Employees On-site during Excavation: Yes No

Incident Impact Information

Number of Outpatient Treated: 0

Number of Inpatient Treated: 0

Number of Fatalities: 0

- Fire Department Response: Yes No
- Police Department Response: Yes No
- Ambulance Response: Yes No

Additional Information / Comments

SEE ATTACHED "UTILITY HIT REPORT"
 ANY ADDITIONAL QUESTIONS
 CALL JOHN HENRY AT (574) 232-2091

