



Pipeline Safety Division Investigation Report

Investigation regarding: C And E Excavating

UPPAC Database Record ID: 4933

Report Date: 9/26/2013

Investigator: Mike Orr

Damage Date: 6/14/2013 12:16:58 PM

Damage Address: New St, Elkhart, Elkhart

The Parties

Excavator: C And E Excavating

Address: 53767 Co Rt 9, Elkhart, In 46514

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes
6/13/2013

Indiana 811 Ticket Number: 1306110276

Original Start Date:

Locate Instructions: FROM THE INTERSECTION - LOCATE THE ENTIRE ROAD - RIGHT OF WAY TO RIGHT OF WAY - GOING NORTH APPROX 500 FEET TO WEST WILKINSON STREET - PLEASE PAINT AND FLAG

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas service while performing water work.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 7/17/2013. Excavator failed to maintain required clearance from the gas service with the trackhoe.

Conclusion: There was a failure to use hand tools where required within the tolerance zone.

Violation: IC 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.



150 West Market Street, Suite 600
Indianapolis, IN 46204

August 12, 2013

[Via Electronic Transmission – PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)

Pipeline Safety Division – Case No. 4933
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 4933

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 6/14/2013
Event Location: New St
City: Indianapolis
Facility Owner: Nipsco
Excavator: C And E Excavating
Other Party: N/A
Pipeline Division Case No. 4933

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher Earle".

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

| IURC INFORMATION REQUEST | |
|---|---|
| Pipeline Safety Division Case No. 4933 | |
| Date of Event | 6/14/2013 |
| Event Location | New St |
| Event City | Elkhart |
| Facility Owner | Nipsco |
| Excavator | C And E Excavating |
| Date of IURC Information Request | July 12, 2013 |
| THE PARTIES | |
| EXCAVATOR: | |
| BUSINESS NAME | |
| RESPONSIBLE PARTY PERSONAL NAME | C and E Excavating |
| TITLE (IF ANY) | |
| ADDRESS | 53767 CO RT 9 |
| CITY/ STATE/ZIP | Elkhart, IN 46514 |
| PREFERRED TELEPHONE | 574 262 4346 |
| CELL PHONE TELEPHONE | |
| EMAIL ADDRESS | |
| FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE: | |
| BUSINESS NAME | NORTHERN INDIANA PUBLIC SERVICE COMPANY |
| RESPONSIBLE PARTY PERSONAL NAME | LUKE SELKING |
| TITLE | |
| ADDRESS | 1501 HALE AVENUE |
| CITY/STATE/ZIP | FORT WAYNE, IN 46802 |
| PREFERRED TELEPHONE | 260/439-1290 |
| SECONDARY TELEPHONE | |
| EMAIL ADDRESS | LSELKING@NISOURCE.COM |
| LOCATOR SERVICE INFORMATION | |
| BUSINESS NAME | USIC |
| RESPONSIBLE PARTY PERSONAL NAME | Morgan Thompson |
| TITLE (IF ANY) | Claims Coordinator |
| ADDRESS | 9045 N. River Rd. Suite 300 |
| CITY/ STATE/ZIP | Indianapolis, IN 46240 |
| PREFERRED TELEPHONE | 1-317-538-7301 |
| CELL PHONE TELEPHONE | Same |
| EMAIL ADDRESS | morganthompson@usicinc.com |
| OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION | |
| PERSONAL CONTACT | |
| BUSINESS/ORGANIZATION NAME | |
| TITLE (IF ANY) | |

| | |
|---------------------------------------|-------------------|
| ADDRESS | |
| CITY/ STATE/ZIP | |
| PREFERRED TELEPHONE | |
| CELL PHONE TELEPHONE | |
| EMAIL ADDRESS | |
| UTILITY LINE IMPACT | |
| LOCATION OF DAMAGE | |
| ADDRESS | 323 New Street |
| CITY/STATE/ZIP | Goshen, IN, 46528 |
| NEAREST INTERSECTION | |
| PRODUCT TYPE (Select One) | |
| NATURAL GAS | X |
| LIQUID PIPELINE | |
| UNKNOWN/OTHER | |
| FACILITY TYPE (Select One) | |
| DISTRIBUTION | |
| GATHERING | |
| SERVICE/DROP | X |
| TRANSMISSION | |
| UNKNOWN/OTHER | |
| SIZE (DIAMETER/ETC.) | 1 1/8" |
| PRESSURE (PSIG/INCHES) | |
| INTERRUPTION IN SERVICE (YES/NO) | Yes |
| NUMBER OF CUSTOMERS AFFECTED | 1 |
| EVACUATION (YES/NO) | No |
| IF YES, HOW MANY EVACUATED | |
| REPAIR COST (IF KNOWN) (\$) | |
| CAUSE OF DAMAGE INFORMATION: | |
| TYPE OF EQUIPMENT (Select One) | |
| Auger | |
| Backhoe/Trackhoe | X |
| Boring/Drilling | |
| Directional Drilling | |
| Explosives | |
| Farm Equipment | |
| Grader/Scraper | |
| Hand Tools | |
| Milling Equipment | |
| Probing Device | |

| | |
|--|----------------|
| Trancher | |
| Vacuum Equipment | |
| Unknown/Other | |
| TYPE OF WORK PERFORMED (Select One) | |
| Agriculture | |
| Cable TV | |
| Curb/Sidewalk | |
| Bldg. Construction | |
| Bldg. Demolition | |
| Drainage | |
| Driveway | |
| Electric | |
| Engineering/Surveying | |
| Fencing | |
| Grading | |
| Irrigation | |
| Landscaping | |
| Liquid Pipeline | |
| Milling | |
| Natural Gas | |
| Pole | |
| Public Transit Authority | |
| Railroad Maintenance | |
| Road Work | |
| Sewer (Sanitary/Storm) | |
| Site Development | |
| Steam | |
| Storm Drain/Culvert | |
| Street Light | |
| Telecommunications | |
| Traffic Signal | |
| Traffic Sign | |
| Water | X |
| Waterway Improvement | |
| Unknown/Other | |
| | |
| RELEASE OF PRODUCT (YES/NO) | Yes |
| IGNITION AND/OR FIRE (YES/NO) | No |
| EXCAVATOR NOTIFY 811 (YES/NO) | Yes 1306141702 |
| LOCATE INFORMATION: | |
| EXCAVATOR REQUEST LOCATE (YES/NO) | Yes |

| | |
|--|------------|
| INDIANA 811 LOCATE TICKET NUMBER | 1306110276 |
| LOCATE MARKS VISIBLE (YES/NO) | Yes |
| LOCATE MARKS CORRECT (YES/NO) | Yes |
| EXCAVATOR "WHITE LINED" (YES/NO) | No |
| MAPS USED TO MARK FACILITIES (YES/NO) | Yes |
| OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO) | No |
| INCIDENT IMPACT INFORMATION | |
| NUMBER OF OUTPATIENT TREATED | 0 |
| NUMBER OF INPATIENT TREATED | 0 |
| NUMBER OF FATALITIES | 0 |
| FIRE DEPARTMENT RESPONSE (YES/NO) | N/A |
| POLICE DEPARTMENT RESPONSE (YES/NO) | N/A |
| AMBULANCE RESPONSE (YES/NO) | N/A |
| ADDITIONAL INFORMATION/COMMENTS | |
| <p>Failure to use hand tools where required NIPSCO Emergency Repair Ticket Number: 1306141943</p> | |

Fact Based Investigation Report

Notification ID 01820130614005
Damage Date 06/14/2013 12:17
Notified By THAD BESSINGER ()
Damage Address NEW ST
GOSHEN, IN
District Northern Indiana
Notification Date 06/14/2013
12:20

Damaged Customer NIPSCO

Investigation Date From 06/14/2013 12:40:00 **To** 06/14/2013 14:10:00

Excavator Involved C & E EXCAVATING
Type of Excavation NEW STREET - WATER MAIN

Orig. Locate Request 1306110276 **Start Date** 06/13/2013 08:15
Type of Ticket Ongoing Project **Locate Req. Info** N/A

Damage Request # 1306141702 **Start Date** 06/14/2013 12:15

Pictures Taken By Scott Schooley **Date** 06/14/2013 13:30
Photography Type Digital **Frame #** see 1306141702

Investigator Emp. # 130534 **Investigator Name** Josh Scheibelhut
Based on your investigation, is further investigation needed? No

Fact Based Investigation Customer Information

Facility Description Low Profile **Facility ID** Gas Service

Locator Name & EMP # Schooley Scott - 125980 **Locator Not Known**

Investigation Findings

Facility Marked Accurately

Other Notes

Investigation Methods

Investigator Verified Existing Marks By Hooking Up
Visual, Facility Exposed At Time Of Investigation

Investigator Statement/Causal Factors

Excavator got caught on aerial lines and as the operator moved the excavator away from the lines he drug the bucket over the gas service and cut it. Gas service had been marked accurately. USIC not at fault.

Names of Utility Representatives Contacted or on Site and Statement

n/a

Names of Excavator's Representatives Contacted or on Site and Statement

n/a

Other individuals on site

Scott Schooley, USIC

Were any markings visible on the damage site upon arrival? Yes

Were any other indicators of facility present in the area? Yes

| | |
|---|--------|
| Was the excavation within the tolerance zone of marks? | Yes |
| Extent of facility damage | cut |
| Replacement Footage | n/a |
| Was contractor assistance required? If yes, who? | No n/a |
| What contractor equipment was used? | n/a |
| Is the facility shown on the utility records? | No |
| If yes, list record numbers | n/a |

Facility: Distribution Lines; Folder: On-Hold folder; Assigned To: N/A

NIPSCO 00051 IUPPSa 06/11/2013 07:56:13 1306110276-00A NORM NEW GRID

NORMAL NOTICE REMARK SEE REMARKS

Ticket : 1306110276 Date: 06/11/2013 Time: 07:54 Oper: LSTEVENSON Chan:018
Old Tkt: 1305301708 Date: 06/04/2013 Time: 08:30 Oper: LSTEVENSON Rev: 01A

State: IN Cnty: ELKHART Twp: ELKHART
Cityname: GOSHEN Inside: Y Near: N
Subdivision:

Address :

Street : NEW ST

Cross 1 : W PIKE ST Within 1/4 mile: Y

Location: FROM THE INTERSECTION - LOCATE THE ENTIRE ROAD - RIGHT OF WAY TO RIGHT
OF WAY - GOING NORTH APPROX 500 FEET TO WEST WILKINSON STREET - PLEASE PAINT
AND FLAG

:

Grids : 4135C8550C

Boundary: n 41.590668 s 41.588625 w -85.839263 e -85.837716

Work type : NEW STREET - WATER MAIN

Done for : CITY OF GOSHEN

Start date: 06/13/2013 Time: 08:15 Hours notice: 48/048 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N

Duration : 1 MONTH Depth: 6 FEET

Company : C AND E EXCAVATING Type: CONT

Co addr : 53767 CO RT 9

City : ELKHART State: IN Zip: 46514

Caller : THAD BESSINGER Phone: (574)262-4346

Contact : THAD BESSINGER - OFFICE Phone:

BestTime:

Mobile : (574)262-4346

Fax : (574)262-9251

Email : TBESSINGER@CANDEEXCAVATING.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time

REMARK AS NEEDED DUE TO WEATHER---THANK YOU

Will you be white-lining the dig site area? NO

:

Submitted date: 06/11/2013 Time: 07:54

Members: COMCN ID5306 ID7053 ID8000 NIPSCO SM

Facility: Transmission Lines; Folder: N/A; Assigned To: N/A

NIPSCO 00647 IUPPSa 06/14/2013 13:06:07 1306141943-00A EMER NEW STRT

EMERGENCY EMERGENCY

Ticket : 1306141943 Date: 06/14/2013 Time: 13:02 Oper: DWILSON Chan:006

State: IN Cnty: ELKHART Twp: ELKHART
Cityname: GOSHEN Inside: Y Near: N
Subdivision:

Address : 323
Street : NEW ST
Cross 1 : W WILKINSON ST Within 1/4 mile: Y
Location: LOCATE--ENTIRE PROPERTY--
:
Grids : 4135C8550C
Boundary: n 41.591062 s 41.588586 w -85.839325 e -85.837813

Work type : REPAIRING GAS LINE
Done for : NIPSCO
Start date: 06/14/2013 Time: 13:03 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 DAY Depth: 6 FEET

Company : NIPSCO Type: MEMB
Co addr : 801 EAST 86TH AVENUE
City : MERRILLVILLE State: IN Zip: 46410
Caller : ANGELA SCHUFFERT Phone: (800)322-2806
Contact : JOE COLE CELL Phone:
BestTime:
Mobile : (574)312-1916
Fax : (219)647-4764

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW EN ROUTE

Will you be white-lining the dig site area? NO
:

Submitted date: 06/14/2013 Time: 13:02
Members: COMCN ID2708 ID5306 ID7053 ID8000 NIPSCO SM

Facility: Transmission Lines; Folder: N/A; Assigned To: N/A

NIPSCO 00577 IUPPSa 06/14/2013 12:17:09 1306141702-00A EMER DAMG GRID

DAMAGE DAMAGE

Ticket : 1306141702 Date: 06/14/2013 Time: 12:14 Oper: LPORTER Chan:046

State: IN Cnty: ELKHART Twp: ELKHART
Cityname: GOSHEN Inside: Y Near: N
Subdivision:

Address :

Street : NEW ST

Cross 1 : W PIKE ST Within 1/4 mile: Y

Location: FROM THE INTERSECTION - LOCATE THE ENTIRE ROAD - RIGHT OF WAY TO RIGHT
OF WAY - GOING NORTH APPROX 500 FEET TO WEST WILKINSON STREET - PLEASE PAINT
AND FLAG

:

Grids : 4135C8550C

Boundary: n 41.590668 s 41.588625 w -85.839263 e -85.837716

Work type : NEW STREET - WATER MAIN

Done for : CITY OF GOSHEN

Start date: 06/14/2013 Time: 12:14 Hours notice: 0/000 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 1 MONTH Depth: 6 FEET

Company : C AND E EXCAVATING Type: CONT

Co addr : 53767 CO RT 9

City : ELKHART State: IN Zip: 46514

Caller : THAD BESSINGER Phone: (574)262-4346

Contact : THAD BESSINGER - OFFICE Phone:

BestTime:

Mobile : (574)262-4346

Fax : (574)262-9251

Email : TBESSINGER@CANDEEXCAVATING.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
PER JEN BURGESS - -HIT A 1 INCH NIPSCO GAS SERVICE LINES - CREW STILL ON SITE -
DIGGING AT 323 NEW ST IN RIGHT OF WAY - GAS IS BLOWING - 911 AND NIPSCO HAVE
BEEN CALLED - PREVIOUS TICKET 1306110276
Will you be white-lining the dig site area? NO

:

Submitted date: 06/14/2013 Time: 12:14

Members: COMCN ID5306 ID7053 ID8000 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA GOSHEN 110 MAXIMO WO #
OPERATING AREA CONTACT JOE COLE JOB ORDER # 605209
TRACKING NUMBER 018 2013 0614 006 LOCATE REF #
Locate Performed By: USJC

DATE AND TIME OF ACCIDENT 6/14/13 1207 M DATE OF REPORT 6/14/13
PLACE OF DAMAGE (INCLUDE CITY) 323 New St. Goshen, In

DAMAGE WAS TO:
ELECTRIC - POLE / TRANSFORMER: # SIZE YEAR INSTALLED BROKEN YES () NO ()

OTHER (DESCRIBE)

GAS: SERVICE MAIN () SIZE 1 1/4 MATERIAL: PLASTIC () STEEL () METER () REG STATION () STUB ()
OTHER (DESCRIBE)

DEPTH OF FACILITY (inches) 18" PRESSURE (PSI) 40 Lbs.

RELEASE OF GAS: YES () NO () IGNITION OF GAS: YES () NO () EVACUATION REQUIRED: YES (X) # NO ()

INTERRUPTION OF SERVICE: YES (X) NO () NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED 1207 TIME RESTORED 3:00pm

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 1"

LOCATE MARKS ON SITE: YES (X) DISTANCE BETWEEN FACILITY AND LOCATE MARKS NO ()
HOW LOCATED: PAINT () FLAGS () BOTH () WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) C+E EXCAVATING

ADDRESS OF PARTY (INCLUDE CITY) 53767 CR 9 ELIHAMPT, IN. 46514

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE IAN MUNDY

WITNESS NAME AND ADDRESS N/A

WITNESS REMARKS N/A

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY N/A REPORT # N/A

FIRE (X) AGENCY GOSHEN FIRE DEPT REPORT # N/A

OTHER () N/A Any Injuries? () YES # (X) NO

PHOTOS TAKEN: YES (X) NO () TAKEN BY: JOE COLE (Emailed to DAVE KERK Damage) (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES () NO (X)

- WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW
() AGRICULTURE/FARMING () CABLE TV () CURB/SIDEWALK () TELECOMMUNICATIONS
() BLDG CONSTRUCTION () DEMOLITION () DRAINAGE (X) WATER
() DRIVEWAY () ELECTRIC () SURVEYING () DRAINS/CULVERTS
() FENCING () GRADING () IRRIGATION () MOWING
() LANDSCAPING () PIPELINE () MILLING () OTHER
() POLE/SIGN POST () ROAD WORK () SEWER

- TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW
() AUGER () HAND TOOLS (X) BACKHOE/TRACKHOE
() MILLING EQUIPMENT () PROBING DEVICE () BORING / DRILLING
() EXPLOSIVES () TRENCHER () FARM EQUIPMENT
() VACCUUM EQUIPMENT () GRADER () OTHER

- REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW
() AUTOMOTIVE ACCIDENT () EXCAVATING BEFORE LOCATES DUE (X) CARELESS MACHINE OPERATOR
() NO NOTIFICATION () MARKS DISTURBED () STUB () OTHER

COMMENTS :

PERSON PREPARING REPORT

SARAH Vanderwerf

FIELD SUPERVISOR


[Signature]

FIELD MANAGER

[Signature]

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information



FOR OFFICE USE ONLY:

- | | | |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE | YES | NO |
| • NO IN 811 LOCATE CALLED IN | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST | YES | NO |

COMPLETED BY: _____ DATE: _____



Property of United States Infrastructure Corporation
Photo taken on 6/14/2013 2:24:01 PM



Property of United States Infrastructure Corporation
Photo taken on 6/14/2013 2:24:10 PM



INFORMATION REQUEST

State Form 54909 (R / 3-13)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 4933

Date of Damage (*month, day, year*): 6/14/13

Location of Damage:

Address (*number and street*): New St, Elkhart, Elkhart County

City, State and ZIP Code: _____

Nearest Intersection: W. Pike St. Goshen, IN

Excavator Information:

Business Name: C & E Excavating, Inc.

Responsible Party Personal Name: Jennifer Burgess

Title (*if any*): Corporate Secretary

Address (*number and street*): 53767 CR 9 N

City, State and ZIP Code: Elkhart, IN 46514

Preferred Telephone Number (area code): 574-262-4346

Email Address: jburgess@candeexcavating.com

Utility Information:

Utility Name: NIPSCO

Contact Person: _____

Title (*if any*): _____

Cause of Damage Information

Type of Equipment (*select one*):

Backhoe/Trackhoe

Type of Work Performed (*select one*):

Sewer (Sanitary/Storm)

Repair Cost: \$ None at this time

Did a leak result from damage: Yes No

Was there ignition: Yes No

Excavator Notify 911 due to leak: Yes No

Excavator Notify 811 upon damage: Yes No

Excavator Notify Utility upon Damage: Yes No

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1305301708

Locate Marks Visible: Yes No

Locate Marks Correct: Yes No

Excavator "White Lined": Yes No

Was Locate Provided within Two (2) Working Days: Yes No

Utility Employees On-site during Excavation: Yes No

Incident Information:

Fire Department Response: Yes No

Police Department Response: Yes No


Ambulance Response: Yes No

Additional Information / Comments

26 year employee and expert excavator operator was digging along side gas main that was located inside a steel casing. As he was tracking the excavator backwards, a phone line above had become caught on the boom of the excavator. As operator looked up to determine what was caught, the edge of the bucket below brushed the steel casing, which then broke and caused subsequent breakage of gas main. NIPSCO and fire was notified immediately and crew was removed from the area. The incident was discussed at our weekly safety meeting, and the employee was given suggestions to avoid further hits in similar situations.

future

Printed Name: Jennifer L Burgess Corporate Secretary

Signature:  Date (month, day, year): 7/17/13

**If submitting this form electronically, typing your name in the signature box will act as an electronic signature.*

Please return completed form to:

PipelineDamageCase@urc.in.gov

Or mail to:

**Indiana Utility Regulatory Commission
Pipeline Safety Division - Case Number 4933
101 West Washington Street, 1500E
Indianapolis, IN 46204**

**Or fax to:
317-233-2410**

C & E Excavating

Job Name: Dickerson Landing P2

Job Code: DICKERSONLP2

Daily Report

Diary: Date - 06/14/2013 (Friday)

Warm - (75 - 80), Sunny, Sand Site

Foreman - IAN M

ran 86' of 8" dip to north
steve hooked overhead tele line and when he picked up his head he snagged gas service
blew approx 2 hrs
sent guys back to yard
washed and kelly paved patches
i was parking equip and had water service start leaking
i dug up and repaired

x. _____ Date: _____

'c' - indicates a completed item.
'(R)' - indicates a rework quantity.