



Pipeline Safety Division Investigation Report

Investigation regarding: Miller Pipeline

UPPAC Database Record ID: 5166

Report Date: 10/1/2013

Investigator: Mike Orr

Damage Date: 7/19/2013 9:34:29 AM

Damage Address: S Jefferson St, Huntington, Huntington

The Parties

Excavator: Miller Pipeline

Address: 8850 Crawfordsville Rd, Indianapolis, In 46234

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Natural Gas

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$400

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes
7/15/2013

Indiana 811 Ticket Number: 1307110891

Original Start Date:

Locate Instructions: PAINT AND FLAG ENTIRE RIGHT OF WAY ON THE WEST SIDE OF S JEFFERSON ST FROM THE CENTERLINE OF SALAMONE AVE HEADING SOUTH TO THE CENTERLINE OF MCCRUM ST

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas main while performing natural gas work.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 9/25/2013. The excavator had a valid locate ticket and the gas operator provided accurate locate markings; however, the excavator failed to maintain required clearance from the gas main with the backhoe.

Conclusion: There was a failure to maintain clearance with mechanized equipment within the tolerance zone.

Violation: IC 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.



DAMAGE INFORMATION REPORT – PIPELINE SAFETY
State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

INITIAL DOCUMENTS -
OPERATOR

Submitted to IURC-Pipeline Safety on: 8/9/2013

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: Miller Pipeline

Business address (number and street): 8850 Crawfordsville Rd.

City, State, and ZIP code: Indianapolis, IN 46234

Telephone number (area code): 317-295-6417

Fax number (area code): 317-295-6418

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Natural Gas

Date and Location of Damage

Date of damage (*month, day, year*): 7-19-2013

County: Huntington

City: Huntington

Street address (*number and street, city, state, and ZIP code*):
S Jefferson St & W Kitt, Huntington, IN

Nearest intersection: Same

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? No

If yes, how many affected? 0

Time to restore service (*in hours*): 0

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 400

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Distribution

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1307110891

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint

If other, please specify: None

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

Additional Comments

2" plastic main damaged by hoe. Not hand exposed.

Vectren Claim Number: 630#

FDS 0018121

Task No: 103,0509 Capital (O & M) (circle one)

Police Report / MO #: _____

Date of Damage 7/19/2013

Vectren Claims Camera:

Cost Center # 5742

Time Occurred 8:10 am / pm

Time Found 8:19 am / pm

Latitude 40.523242 Longitude: -85.292210

FACILITIES DAMAGE REPORT

GAS

VE02865
4

DAMAGE SITE:

Address S. JEFFERSON ST. E W. KITT ST. Lot # _____

FACILITY TYPE:

- Distribution Propane
- Service Storage
- Transmission: (include supplemental report)

County HUNTINGTON City HUNTINGTON State IN Township HUNTINGTON

FACILITIES DAMAGED:

	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	Other			

1.943

TYPE OF MATERIAL:

- Cast Iron
- Plastic (HDPE)
- Plastic (MDPE)
- Steel
- Other _____

DAMAGE TYPE:

- Severed
- Not Cut
- Severed, Size 2 x 2"

PRESSURE:

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 55 PSIG
- 60 PSIG
- 6 WC (.2163)
- 7 WC (252)
- Other _____

1.204

PROTECTION IN PLACE:

- Building Fence None
- Post Rail Vault N/A
- Other _____

DURATION OF ESCAPING GAS:

Minutes: 5

LEAK REPORT

NUMBER: WO# 10247664

EFV Activated Yes No N/S

Number of Customers Affected: 0

Total Hours Service Was Off: 0

FEED TYPE:

- One-Way Feed
- Two-Way Feed

SERVICE ORDER NUMBER: N5736508

DAMAGED BY:

- Company Crew
- Contractor -MILLER PIPELINE
- County
- Developer
- Farmer
- Municipality
- Property Owner/ Tenant
- Railroad
- State
- Unknown
- Utility
- Vehicle Accident
- Other _____

TYPE OF CONSTRUCTION:

- Agriculture
- Building Construction
- Building Demolition
- Cable TV
- Curbs / Sidewalk
- Drainage
- Driveway
- Electric
- Engineering / Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Pole
- Natural Gas
- Public Transit Authority
- Railroad Maintenance
- Other _____

WORKING FOR:

- City County Developer
- State Property Owner
- Utility

VISUAL OBSERVATION AT DAMAGE SITE:

- Visual Observation: Above Ground Below Ground
- Locate Applicable: Yes No N/S
- Facilities Properly Marked: Yes No N/S
- Marking Methods: Conventional Flags None Offset Paint Stakes Whiskers
- Locate Marking Faded: Yes No N/S
- Wrong Address Requested: Yes No N/S

Facilities Improperly Located:

- Qualified Locator Could Not Have Accurately Located
- Inaccurate Maps / Cards
- Broken or No Tracer Wire (Plastic)
- Insulation Preventing Accurate Locate

Locator Error:

- Failure to Follow Policy
- Inappropriate Site Markings
- Incomplete Locate
- No Locates Performed
- Qualified Locator Could Have Accurately Located
- Wrong Address Located
- Marking Off By: _____ (Feet / Inches)

- Were Facility Marks Visible: Yes No
- Was Area White Lined: Yes No Destroyed
- Positive Response: Yes No Destroyed
- Tolerance Zone Violated: Yes No
- Part of Project: Yes No
- Company Representative On-Site: Yes No

Observation by (ID#): 2130

Name of Locator: _____

LOCATING ORGANIZATION:

- Contract Locator
- Unknown / Other
- Utility Owner

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:

Locate Ticket: 1307110891 DMG 1307190799

Date: _____ Time: _____ am / pm

TYPE OF REQUEST:

- Regular Request Emergency Request
- Locate Company Notified

Contact Name: _____

Time Called: _____ am / pm

Time Locator Arrived at the Site: _____ am / pm

Company Notified of Locate Near Critical Facilities Yes No N/S

Copy of Mark Out Request Provided Within 2 Working Days Yes No N/S

ONE-CALL CENTER:

- IUPPS
- OUPS
- Unknown

Vectren Claim Number: VED 2865 - 0000

TYPE OF EQUIPMENT:

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other _____

ROOT DAMAGING CAUSE:

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other _____

CONTRACTOR REPAIRS:

- Contractor Working for Vectren Made Repairs at Own Expense
 - Yes No N/S
- Contractor Repaired Damage
 - Yes No N/S

Name of Contractor: MILLER PIPELINE
 # of Regular Hours; 2
 # of Overtime Hours; 0
 # of Regular Hours; _____
 Crew Type: 20 Pipe

MATERIALS OR ROAD WORK:

- Meter was replaced _____ (Stores Code)
- Regulator Was Replaced _____ (Stores Code)
- Temporary Asphalt Repair: _____ (sq. ft.)
- Permanent Asphalt Repair: _____ (sq. ft.)

- Did Excavator Notify You Yes No
- Excavation Required Yes No
- Media at Site Yes No
- Was There Ignition of Gas? Yes No

INVOICE: Yes No N/S

RIGHT OF WAY:

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

<p>DAMAGING PARTY:</p> <p>Name: <u>MILLER PIPELINE</u></p> <p>Address: _____</p> <p>City/ State/ Zip: _____</p> <p>Phone: (____) _____</p> <p>Prepared / Investigated By: <u>Mark Uhl</u> Date: <u>7-19-2013</u></p>	<p>PARTY TO INVOICE:</p> <p>Name: <u>MILLER PIPELINE</u></p> <p>Address: _____</p> <p>City/ State/ Zip: _____</p> <p>Phone: (____) _____</p> <p>Reviewed by Field Supervisor: <u>[Signature]</u> Date: <u>7-22-13</u></p>
---	--

Ticket Portal Production

Ticket Text **Photos**

Ticket Text

ID0002 00291 IUPPSa 07/19/2013 09:34:43 1307190799-00A EMER DAMG GRID
 DAMAGE SEE REMARKS
 Ticket : 1307190799 Date: 07/19/2013 Time: 09:32 Oper: SPOPE Chan:044
 State: IN Cnty: HUNTINGTON Twp: HUNTINGTON
 Cityname: HUNTINGTON Inside: Y Near: N
 Subdivision:
 Address :
 Street : S JEFFERSON ST
 Cross 1 : SALAMONIE AVE Within 1/4 mile: Y
 Location: PAINT AND FLAG ENTIRE RIGHT OF WAY ON THE WEST SIDE OF S JEFFERSON ST
 FROM THE CENTERLINE OF SALAMONE AVE HEADING SOUTH TO THE CENTERLINE OF MCCRUM ST
 ***Boring Where = W TAYLOR ST AND MCCRUM ST AND ALLEYS
 :
 Grids : 4052B8529C 4052C8529C 4052C8529D
 Boundary: n 40.876698 s 40.872982 w -85.490961 e -85.486125
 Work type : REPLACE GAS MAIN
 Done for : VECTREN
 Start date: 07/19/2013 Time: 09:33 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y
 Duration : 4 WEEK Depth: 5FT
 Company : MILLER PIPE LINE Type: CONT
 Co addr : 8850 CRAWFORDSVILLE RD
 City : INDIANAPOLIS State: IN Zip: 46234
 Caller : SARAH HEMINGER Phone: (317)295-6417
 Contact : JOHN POLING--CELL Phone:
 BestTime:
 Mobile : (317)710-5143
 Fax : (317)295-6418
 Email : SARAH.HEMINGER@MILLERPIPELINE.COM
 Remarks : All tickets are taken and processed on Eastern Daylight Time
 VECTREN GAS LINE HAS BEEN CUT--LINE IS NOT BLOWING--VECTREN HAS BEEN NOTIFIED--2
 INCH PLASTIC PINK LINE--LINE WAS CUT AT THE INTERSECTION OF JEFFERSON ST AND
 KITT ST--CREW ON SITE--PREV TICKET 1307110891--THANK YOU
 Will you be white-lining the dig site area? NO
 :
 Submitted date: 07/19/2013 Time: 09:32
 Members: ID0002 ID1400 ID4752 ID6671 SBCIN


 Email_From: agt_comm@irth.com
 Email_Subject: Seq# 424: 1307190799 for ID0002 - Electric Distribution (IN)
 Email_Sent_Date: 2013-07-19 08:34:43 CDT
 Email_host: tickets5.811tickets.com
 Email_user: 811.in.duk
 Email_To: 811.in.duk@tickets.811tickets.com
 Email_ContentType: text/Plain; charset=US-ASCII



Property of United States Infrastructure Corporation
Photo taken on 7/18/2013 6:57:05 PM



Property of United States Infrastructure Corporation
Photo taken on 7/18/2013 6:57:47 PM



Property of United States Infrastructure Corporation
Photo taken on 7/18/2013 6:58:44 PM



Property of United States Infrastructure Corporation
Photo taken on 7/18/2013 6:57:19 PM

Monday, August 5, 2013

Service Order Status

Enter Service Order Number:

5736508



[Clear Form](#)

[Print this Page](#)

Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: N5736508

Order Type: INVE

Order Status: Completed

Customer: 008888888 - INACTIVE CUSTOMER

Prem: 5751563 - S JEFFERSON & W KITT

Technician: 2130 - Vice, Mike

Order Dates and Times

Need Date: 7/19/2013 8:14:00 AM
Time Created: 7/19/2013 8:11:08 AM
Time Dispatched: 7/19/2013 8:11:08 AM
Time In Route: 7/19/2013 8:14:26 AM
Time On-Site: 7/19/2013 8:19:27 AM
Tech Complete: 7/19/2013 10:15:33 AM
Time Closed: 7/19/2013 10:15:33 AM

Events Performed/Completion Code

IVEG - CMP

Meter Information

Current ReadStatus

Old Meter:

New Meter:

Completion Notes

MIKE VICE,MADE SAFE AT 8:15 AM. MILLER PIPELINE HIT 2" LP. PL. MAIN WITH BACKHOE
 .CREW MADE SAFE & WILL MAKE REPAIR.ALL OTHER TESTS WERE NEG.

Request Notes

PER JOHN POLING WITH MILLER PIPELINE, HIT 2" LOW PRESSURE PL MAIN AT THISINTERSECTION...ONSITE...CRI
 MPED OFF...LINES LOCATED....PH 317-710-5143...ADV SAFETY....THANKS

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentEnRoute_evt	7/19/2013 8:14:26 AM	Vice, Mike
AsnAssignmentManualAck_evt	7/19/2013 8:14:44 AM	Vice, Mike
AsnAssignmentOnSite_evt	7/19/2013 8:19:27 AM	Vice, Mike
OrdOrderComplete_evt	7/19/2013 10:15:33 AM	Vice, Mike

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.



INFORMATION REQUEST

State Form 54909 (R / 3-13)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 5166 _____

Date of Damage (*month, day, year*): July 19, 2013 _____

Location of Damage:

Address (*number and street*): S. Jefferson St. _____

City, State and ZIP Code: Huntington, IN _____

Nearest Intersection: Jefferson and Kitt _____

Excavator Information:

Business Name: Miller Pipeline _____

Responsible Party Personal Name: James Poling _____

Title (*if any*): Foreman _____

Address (*number and street*): 8850 Crawfordsville Rd. _____

City, State and ZIP Code: Indianapolis, IN 46234 _____

Preferred Telephone Number (area code): 317 293-0278 _____

Email Address: info@millerpipeline.com _____

Utility Information:

Utility Name: Vectren _____

Contact Person: _____

Title (*if any*): _____

Cause of Damage Information

Type of Equipment (*select one*):

Type of Work Performed (*select one*):

Repair Cost: \$ 147.73

Did a leak result from damage: Yes No

Was there ignition: Yes No

Excavator Notify 911 due to leak: Yes No

Excavator Notify 811 upon damage: Yes No

Excavator Notify Utility upon Damage: Yes No

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1307110891

Locate Marks Visible: Yes No

Locate Marks Correct: Yes No

Excavator "White Lined": Yes No

Was Locate Provided within Two (2) Working Days: Yes No

Utility Employees On-site during Excavation: Yes No

Incident Information:

Fire Department Response: Yes No

Police Department Response: Yes No

Ambulance Response: Yes No

Additional Information / Comments

While excavating we had to remove curb and in so doing we cut existing 2" polyethylene gas line that was just beneath the large concrete curb. The yellow locate marks were less than 2 feet away. We disciplined the foreman for this and stripped the entire crew of their OQ qualifications. This resulted in bringing in a different crew to finish this job.

Printed Name: Ralph Miller

Signature: Ralph Miller Date (month, day, year): 9-24-13

**If submitting this form electronically, typing your name in the signature box will act as an electronic signature.*

Please return completed form to:

PipelineDamageCase@urc.in.gov

Or mail to:

**Indiana Utility Regulatory Commission
Pipeline Safety Division - Case Number 5166
101 West Washington Street, 1500E
Indianapolis, IN 46204**

**Or fax to:
317-233-2410**

Woods, Janea

From: Heminger-Frazier, Sarah [Sarah.Frazier@millerpipeline.com]
Sent: Monday, September 16, 2013 7:08 AM
To: Heminger-Frazier, Sarah
Subject: damage ticket for s jefferson st

From: Heminger-Frazier, Sarah
Sent: Friday, July 19, 2013 9:35 AM
To: Poling, John; adrian
Subject: Emailing: IRTH One Call

DAMAGE SEE REMARKS

Ticket : 1307190799 Date: 07/19/2013 Time: 09:32 Oper: SPOPE Chan:044

State: IN Cnty: HUNTINGTON Twp: HUNTINGTON
Cityname: HUNTINGTON Inside: Y Near: N
Subdivision:

Address :

Street : S JEFFERSON ST

Cross 1 : SALAMONIE AVE Within 1/4 mile: Y

Location: PAINT AND FLAG ENTIRE RIGHT OF WAY ON THE WEST SIDE OF S JEFFERSON ST
FROM THE CENTERLINE OF SALAMONE AVE HEADING SOUTH TO THE CENTERLINE OF MCCRUM ST
***Boring Where = W TAYLOR ST AND MCCRUM ST AND ALLEYS

:

Grids : 4052B8529C 4052C8529C 4052C8529D

Boundary: n 40.876698 s 40.872982 w -85.490961 e -85.486125

Work type : REPLACE GAS MAIN

Done for : VECTREN

Start date: 07/19/2013 Time: 09:33 Hours notice: 0/000 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y

Duration : 4 WEEK Depth: 5FT

Company : MILLER PIPE LINE Type: CONT

Co addr : 8850 CRAWFORDSVILLE RD

City : INDIANAPOLIS State: IN Zip: 46234

Caller : SARAH HEMINGER Phone: (317)295-6417

Contact : JOHN POLING--CELL Phone:

BestTime:

Mobile : (317)710-5143

Fax : (317)295-6418

Email : SARAH.HEMINGER@MILLERPIPELINE.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
VECTREN GAS LINE HAS BEEN CUT--LINE IS NOT BLOWING--VECTREN HAS BEEN NOTIFIED--2
INCH PLASTIC PINK LINE--LINE WAS CUT AT THE INTERSECTION OF JEFFERSON ST AND
KITT ST--CREW ON SITE--PREV TICKET 1307110891--THANK YOU
Will you be white-lining the dig site area? NO
:

Submitted date: 07/19/2013 Time: 09:32

Members: ID0002 ID1400 ID4752 ID6671 SBCIN

Member Name	Facility Types
-------------	----------------

AT&T - DISTRIBUTION	COMMUNICATIONS
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
HUNTINGTON, CITY OF	
VECTREN - MARION	GAS
WINDSTREAM KDL	COMMUNICATIONS



DAMAGE
↓



Woods, Janea

From: Heminger-Frazier, Sarah [Sarah.Frazier@millerpipeline.com]
Sent: Monday, September 16, 2013 7:09 AM
To: Heminger-Frazier, Sarah
Subject: original ticket s jefferson st

From: Heminger-Frazier, Sarah
Sent: Thursday, July 11, 2013 10:00 AM
To: Poling, John
Subject: Emailing: IRTH One Call

NORMAL NOTICE JOB EXTENSION

Ticket : 1307110891 Date: 07/11/2013 Time: 09:45 Oper: SARAH.HEMINGER Chan:000
Old Tkt: 1306251198 Date: 06/25/2013 Time: 10:33 Oper: SARAH.HEMINGER Rev: 00A

State: IN Cnty: HUNTINGTON Twp: HUNTINGTON
Cityname: HUNTINGTON Inside: Y Near: N
Subdivision:

Address :
Street : S JEFFERSON ST
Cross 1 : SAALAMONE AVE Within 1/4 mile: Y
Location: PAINT AND FLAG ENTIRE RIGHT OF WAY ON THE WEST SIDE OF S JEFFERSON ST
FROM THE CENTERLINE OF SALAMONE AVE HEADING SOUTH TO THE CENTERLINE OF MCCRUM ST
***Boring Where = W TAYLOR ST AND MCCRUM ST AND ALLEYS
:
Grids : 4052B8529C 4052C8529C 4052C8529D
Boundary: n 40.876698 s 40.872982 w -85.490961 e -85.486125

Work type : REPLACE GAS MAIN
Done for : VECTREN
Start date: 07/15/2013 Time: 10:00 Hours notice: 96/048 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
Duration : 4 WEEK Depth: 5FT

Company : MILLER PIPE LINE Type: CONT
Co addr : 8850 CRAWFORDSVILLE RD
City : INDIANAPOLIS State: IN Zip: 46234
Caller : SARAH HEMINGER Phone: (317)295-6417
Contact : JOHN POLING--CELL Phone:
BestTime:
Mobile : (317)710-5143
Fax : (317)295-6418
Email : SARAH.HEMINGER@MILLERPIPELINE.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
NEED ALL UTILITIES TO RETURN AND REMARK PREVIOUS TICKET 1306251198
Will you be white-lining the dig site area? NO
:

Submitted date: 07/11/2013 Time: 09:45
Members: ID0002 ID1400 ID4752 ID6671 SBCIN

Member Name	Facility Types
-------------	----------------

AT&T - DISTRIBUTION	COMMUNICATIONS
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
HUNTINGTON, CITY OF	
VECTREN - MARION	GAS
WINDSTREAM KDL	COMMUNICATIONS