



INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

## Pipeline Safety Division Investigation Report

### Investigation regarding: Miller Pipeline

UPPAC Database Record ID: 5199

Report Date: 10/1/2013

Investigator: Mike Orr

Damage Date: 7/26/2013 10:55:37 AM

Damage Address: 14011 Northcoat Pl, Fall Creek, Hamilton

### The Parties

Excavator: **Miller Pipeline**

Address: 8850 Crawfordsville Rd, Indianapolis, In 46234

Facility Owner: **Vectren**

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Natural Gas

### Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$200

### Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes  
7/26/2013

Indiana 811 Ticket Number: 1307240717

Original Start Date:

Locate Instructions: PAINT AND FLAG ENTIRE PROPERTY AND ALONG NORTHCOAT PL

Follow-Up Locate Instructions (if applicable):

**Synopsis:** Excavator struck and damaged an underground natural gas main while performing natural gas work.

**Findings:** Reported by Indiana 811; excavator's response to initial notice was received on 9/25/2013. The excavator had a valid locate ticket and the gas operator provided accurate locate markings; however, the excavator failed to maintain required clearance from the gas main with the backhoe.

**Conclusion:** There was a failure to maintain clearance with mechanized equipment within the tolerance zone.

**Violation: IC 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.**



**DAMAGE INFORMATION REPORT – PIPELINE SAFETY**  
State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

INITIAL DOCUMENTS -  
OPERATOR

Submitted to IURC-Pipeline Safety on: 8/9/2013

**Who is submitting this information?**

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

**Excavator Information, if known**

Full name: Miller Pipeline

Business address (*number and street*): 8850 Crawfordsville Rd

City, State, and ZIP code: Indianapolis, IN 46234

Telephone number (*area code*): 317-295-6417

Fax number (*area code*): 317-295-6418

E-mail address: Unknown

**Excavation or Demolition Information**

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Natural Gas

---

**Date and Location of Damage**

Date of damage (*month, day, year*): 7-26-2013

County: Hamilton

City: Fishers

Street address (*number and street, city, state, and ZIP code*):  
14011 Northcoat Place, Fishers, IN

Nearest intersection: Unknown

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? No

If yes, how many affected? 0

Time to restore service (*in hours*): 0

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 200

---

**Affected Facility Information**

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? \_\_\_\_\_

---

**Notification, Locating, Marking**

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1307240717

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC \_\_\_\_\_

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Unknown/Other

Type of markings used: Paint and Flags

If other, please specify: None \_\_\_\_\_

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

### Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

---

### Additional Comments

2" plastic main damaged by hoe. Not hand exposed.

Vectren Claim Number: \_\_\_\_\_

FDS 0018188

Task No: 103,0510 Capital / O & M (circle one)

Police Report / MO #: \_\_\_\_\_

Date of Damage 7/26/2013

Cost Center # 5836

### FACILITIES DAMAGE

Time Occurred 11:00 am / pm

### REPORT

Time Found 11:20 am / pm

### GAS

Latitude 39.99234 Longitude: -85.95297

Vectren Claims Camera:

VE04044

#### DAMAGE SITE:

Address 14011 Northcoat Pl Lot # 196

#### FACILITY TYPE:

- Distribution  Propane
- Service  Storage
- Transmission: (include supplemental report)

County Hamilton City Fisher State Ind Township Fall-creek

#### FACILITIES DAMAGED:

- Farm Tap
- Heater
- Main
- Meter (Residential)
- Meter (Industrial / Commercial)
- Odorizer
- Regulator Station
- Relief Valve
- Riser
- Service Line
- Valve

ORIFICE SIZE(S):	(1)	(2)	(3)
0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Other	<u>N/A</u>		

1.126

#### TYPE OF MATERIAL:

- Cast Iron
- Plastic (HDPE)
- Plastic (MDPE)
- Steel

#### DAMAGE TYPE:

- Severed
- Not Cut
- Pushed
- Siz 1 x 1

#### PRESSURE:

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 55 PSIG
- 60 PSIG
- 6 WC (.2163)
- 7 WC (252)
- Other

42.123

#### PROTECTION IN PLACE:

- Building  Fence  None
- Post  Rail  Vault  N/A
- Other

#### DURATION OF ESCAPING GAS:

Minutes: 10 min

#### LEAK REPORT

NUMBER: 01583

EFV Activated  Yes  No  N/S

Number of Customers

Affected; 0

Total Hours Service

Was Off: \_\_\_\_\_

#### SERVICE ORDER NUMBER:

#### DAMAGED BY:

- Company Crew
- Contractor
- County
- Developer
- Farmer
- Municipality
- Property Owner/ Tenant
- Railroad
- State
- Unknown
- Utility
- Vehicle Accident
- Other

#### TYPE OF CONSTRUCTION:

- Agriculture
- Building Construction
- Building Demolition
- Cable TV
- Curbs / Sidewalk
- Drainage
- Driveway
- Electric
- Engineering / Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Pole
- Natural Gas
- Public Transit Authority
- Railroad Maintenance
- Other

#### WORKING FOR:

- City  County  Developer
- State  Property Owner
- Utility

#### VISUAL OBSERVATION AT DAMAGE SITE:

- Visual Observation:  Above Ground  Below Ground
- Locate Applicable  Yes  No  N/S
- Facilities Properly Marked  Yes  No  N/S
- Marking Methods:  Conventional  Flags  None  Paint  Stakes  Whiskers
- Offset
- Locate Marking Faded:  Yes  No  N/S
- Wrong Address Requested  Yes  No  N/S

#### Facilities Improperly Located:

- Qualified Locator Could Not Have Accurately Located
- Inaccurate Maps / Cards
- Broken or No Tracer Wire (Plastic)
- Insulation Preventing Accurate Locate

#### Locator Error:

- Failure to Follow Policy
- Inappropriate Site Markings
- Incomplete Locate
- No Locates Performed
- Qualified Locator Could Have Accurately Located
- Wrong Address Located
- Marking Off By: \_\_\_\_\_ (Feet / Inches)

N/A

AUG 2 2013

- Were Facility Marks Visible  Yes  No
- Was Area White Lined  Yes  No  Destroyed
- Positive Response  Yes  No  Destroyed
- Tolerance Zone Violated  Yes  No
- Part of Project  Yes  No
- Company Representative On-Site  Yes  No

Observation by (ID#): \_\_\_\_\_

Name of Locator: Tony

#### LOCATING ORGANIZATION:

- Contract Locator
- Unknown / Other
- Utility Owner

#### NOTIFICATIONS AND OTHER DETAILS OF LOCATE:

Locate Ticket: 1307261135  
Date: 7-26 Time: 11:30 (am/pm)

#### TYPE OF REQUEST:

- Regular Request  Emergency Request
- Locate Company Notified
- Contact Name: \_\_\_\_\_
- Time Called: \_\_\_\_\_ am / pm
- Time Locator Arrived at the Site: \_\_\_\_\_ am / pm

Company Notified of Locate Near Critical Facilities

- Yes  No  N/S

Copy of Mark Out Request Provided Within 2 Working Days

- Yes  No  N/S

#### ONE-CALL CENTER:

- IUPPS
- OUPS
- Unknown

Vectren Claim Number: \_\_\_\_\_

**TYPE OF EQUIPMENT:**

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other \_\_\_\_\_

**ROOT DAMAGING CAUSE:**

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other \_\_\_\_\_

**CONTRACTOR REPAIRS:**

- Contractor Working for Vectren Made Repairs at Own Expense
  - Yes  No  N/S
- Contractor Repaired Damage
  - Yes  No  N/S

Name of Contractor: \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 # of Overtime Hours; \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 Crew Type: \_\_\_\_\_

**MATERIALS OR ROAD WORK:**

- Meter was replaced \_\_\_\_\_ (Stores Code)
- Regulator Was Replaced \_\_\_\_\_ (Stores Code)
- Temporary Asphalt Repair: \_\_\_\_\_ (sq. ft.)
- Permanent Asphalt Repair: \_\_\_\_\_ (sq. ft.)

Did Excavator Notify You

Yes  No

Excavation Required

Yes  No

Media at Site

Yes  No

Was There Ignition of Gas?

Yes  No

INVOICE:

Yes  No  N/S

**RIGHT OF WAY:**

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

**DAMAGING PARTY:**

Name: Miller Pipe Line <sup>Devel Post</sup> 710-2314  
 Address: 8850 Crawfordsville Rd  
 City/ State/ Zip: Indpls, Ind, 46234  
 Phone: (317) 710-2341  
 Prepared/ Investigated By: *[Signature]* Date: 7-26-2013

**PARTY TO INVOICE:**

Name: *[Signature]* Miller Pipe Line  
 Address: \_\_\_\_\_  
 City/ State/ Zip: \_\_\_\_\_  
 Phone: ( ) \_\_\_\_\_  
 Reviewed by Field Supervisor: *[Signature]* Date: 7-29-13

## Ticket Portal Production

**Ticket Text**    Photos

### **Ticket Text**

ID0660 00612 IUPPSa 07/24/2013 09:06:36 1307240717-00A NORM NEW GRID  
 NORMAL NOTICE  
 Ticket : 1307240717 Date: 07/24/2013 Time: 09:05 Oper: SARAH.HEMINGER Chan:000  
 State: IN Cnty: HAMILTON Twp: FALL CREEK  
 Cityname: FISHERS Inside: N Near: Y  
 Subdivision: WESTMINSTER Lot: 196  
 Address : 14011  
 Street : NORTHCOAT PL  
 Cross 1 : E 141ST ST Within 1/4 mile: Y  
 Location: PAINT AND FLAG ENTIRE PROPERTY AND ALONG NORTHCOAT PL  
 :  
 Grids : 3959C8557C 3959C8557D  
 Boundary: n 39.990838 s 39.988217 w -85.956990 e -85.951663  
 Work type : INSTALL GAS SERVICE  
 Done for : VECTREN  
 Start date: 07/26/2013 Time: 09:15 Hours notice: 48/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N  
 Duration : 1 DAY Depth: 5FT  
 Company : MILLER PIPE LINE Type: CONT  
 Co addr : 8850 CRAWFORDSVILLE RD  
 City : INDIANAPOLIS State: IN Zip: 46234  
 Caller : SARAH HEMINGER Phone: (317)295-6417  
 Contact : DAVE ROOSE - CELL Phone:  
 BestTime:  
 Mobile : (317)710-2341  
 Fax : (317)295-6418  
 Email : SARAH.HEMINGER@MILLERPIPELINE.COM  
 Remarks : All tickets are taken and processed on Eastern Daylight Time  
 Will you be white-lining the dig site area? NO  
 :  
 Submitted date: 07/24/2013 Time: 09:05  
 Members: ID0002 ID0103 ID0660 ID2862 ID3162 ID3642 ID4636 ID9411 SBCIN SM  
 -----  
 Email\_From: irth@iupps.org  
 Email\_Subject: IUPPS ID0660 2013/07/24 #00612 1307240717-00A NORM NEW  
 Email\_Sent\_Date: 2013-07-24 08:06:37 CDT  
 Email\_host: tickets7.811tickets.com  
 Email\_user: 811.in.oc  
 Email\_To: 811.in.oc@tickets.811tickets.com  
 Email\_ContentType: text/plain; charset=us-ascii

## Ticket Portal Production

**Ticket Text**   Photos

**Ticket Text**

ATTIN Seq: 682 Transmitted: Fri Jul 26 10:00:46 CDT 2013  
 SBCIN 00652 IUPPSa 07/26/2013 10:55:44 1307261135-00A EMER DAMG GRID  
 DAMAGE DAMAGE  
 Ticket : 1307261135 Date: 07/26/2013 Time: 10:53 Oper: LPORTER Chan:046  
 State: IN Cnty: HAMILTON Twp: FALL CREEK  
 Cityname: FISHERS Inside: N Near: Y  
 Subdivision: WESTMINSTER Lot: 196  
 Address : 14011  
 Street : NORTHCOAT PL  
 Cross 1 : E 141ST ST Within 1/4 mile: Y  
 Location: PAINT AND FLAG ENTIRE PROPERTY AND ALONG NORTHCOAT PL  
 :  
 Grids : 3959C8557C 3959C8557D  
 Boundary: n 39.990838 s 39.988217 w -85.956990 e -85.951663  
 Work type : INSTALL GAS SERVICE  
 Done for : VECTREN  
 Start date: 07/26/2013 Time: 10:53 Hours notice: 0/000 Priority: EMER  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y  
 Duration : 1 DAY Depth: 5FT  
 Company : MILLER PIPE LINE Type: CONT  
 Co addr : 8850 CRAWFORDSVILLE RD  
 City : INDIANAPOLIS State: IN Zip: 46234  
 Caller : SARAH HEMINGER Phone: (317)295-6417  
 Contact : DAVE ROOSE - CELL Phone:  
 BestTime:  
 Mobile : (317)710-2341  
 Fax : (317)295-6418  
 Email : SARAH.HEMINGER@MILLERPIPELINE.COM  
 Remarks : All tickets are taken and processed on Eastern Daylight Time  
 PER SARAH HEMINGER - HIT A VECTREN GAS LINE - -DIGGING IN FRONT OF PROPERTY -  
 GAS NOT BLOWING - HAS TAKEN CARE OF LEAK - LINE DESCRIPTION 2INCH YELLOW PLASTIC  
 LINE - - CREW STILL ON SITE - PREVIOUS TICKET 1307240717  
 Will you be white-lining the dig site area? NO  
 :  
 Submitted date: 07/26/2013 Time: 10:53  
 Members: ID0002 ID0103 ID0660 ID2862 ID3162 ID3642 ID4636 SBCIN SM  
 -----  
 Email\_From: att-tickets@tickets.translore.com  
 Email\_Subject: ATT Translore - 1307261135  
 Email\_Sent\_Date: 2013-07-26 10:00:46 CDT  
 Email\_MessageID: <1374850846168.393242626.TransLore.att-tickets@tickets.translore.com>  
 Email\_host: tickets5.811tickets.com  
 Email\_user: 811.in.att  
 Email\_To: 811.in.att@tickets.811tickets.com  
 Email\_ContentType: text/plain; charset=ISO-8859-1



Property of United States Infrastructure Corporation  
Photo taken on 7/26/2013 11:08:24 AM



Property of United States Infrastructure Corporation  
Photo taken on 7/26/2013 11:08:14 AM

Friday, August 2, 2013

# Service Order Status

**Enter Service Order Number:**

5745310



Clear Form

Refresh Data

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD

**Order Number:** N5745310

**Order Type:** LEAK

**Order Status:** Completed

**Customer:** 600624158 - RYLAND HOMES OF INDIANAPOLIS  
**Prem:** 5751445 - 14011 NORTHCOAT PL

**Technician:** 3327 - Webster, Ervin

**Order Dates and Times**

**Need Date:** 7/26/2013 11:15:00 AM  
**Time Created:** 7/26/2013 11:01:49 AM  
**Time Dispatched:** 7/26/2013 11:01:49 AM  
**Time In Route:** 7/26/2013 12:19:48 PM  
**Time On-Site:** 7/26/2013 12:19:51 PM  
**Tech Complete:** 7/26/2013 12:27:38 PM  
**Time Closed:** 7/26/2013 12:27:38 PM

**Events Performed/Completion Code**

LKNS - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:**

**New Meter:**

**Completion Notes**

miler pipe line cut the main putting in a service all test were neg they had squeezed off the main repaires were made by miller

**Request Notes**

PER KRISTIN WITH 811/REPORTING HIT LINE AT THIS PREMISE/HIT BY MILLER PIPELINECONTACT PER DAVE ROOSE /317 710 2341/2 IN PLASTIC LINE/DAM TICKET#1307261135/NO OTHER INFO AVAIL/CLAMPED OFF/

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentManualAck_evt	7/26/2013 11:38:01 AM	Webster, Ervin
AsnAssignmentEnRoute_evt	7/26/2013 12:19:48 PM	Webster, Ervin
AsnAssignmentOnSite_evt	7/26/2013 12:19:51 PM	Webster, Ervin
OrdOrderComplete_evt	7/26/2013 12:27:38 PM	Webster, Ervin

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

**INFORMATION REQUEST**

State Form 54909 (R / 3-13)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 5199 \_\_\_\_\_

Date of Damage (month, day, year): July 26, 2013 \_\_\_\_\_

**Location of Damage:**

Address (number and street): 14011 Northcoat Pl. \_\_\_\_\_

City, State and ZIP Code: Fishers, IN 46037 \_\_\_\_\_

Nearest Intersection: Elipse Pkwy and Kinetta Court \_\_\_\_\_

**Excavator Information:**

Business Name: Miller Pipeline \_\_\_\_\_

Responsible Party Personal Name: Todd Doyle \_\_\_\_\_

Title (if any): Foreman \_\_\_\_\_

Address (number and street): 8850 Crawfordsville Rd. \_\_\_\_\_

City, State and ZIP Code: Indianapolis, IN 46234 \_\_\_\_\_

Preferred Telephone Number (area code): 317 293-0278 \_\_\_\_\_

Email Address: info@millerpipeline.com \_\_\_\_\_

**Utility Information:**

Utility Name: Vectren \_\_\_\_\_

Contact Person: \_\_\_\_\_

Title (if any): \_\_\_\_\_

**Cause of Damage Information**

Type of Equipment (*select one*):

Backhoe/Trackhoe

Type of Work Performed (*select one*):

Natural Gas

Repair Cost: \$ 129.66

- Did a leak result from damage:  Yes  No
- Was there ignition:  Yes  No
- Excavator Notify 911 due to leak:  Yes  No
- Excavator Notify 811 upon damage:  Yes  No
- Excavator Notify Utility upon Damage:  Yes  No

---

**Locate Information**

- Excavator Request Locate:  Yes  No
- Indiana 811 Locate Ticket Number: 11307240717
- Locate Marks Visible:  Yes  No
- Locate Marks Correct:  Yes  No
- Excavator "White Lined":  Yes  No
- Was Locate Provided within Two (2) Working Days:  Yes  No
- Utility Employees On-site during Excavation:  Yes  No

---


**Incident Information:**

- Fire Department Response:  Yes  No
- Police Department Response:  Yes  No
- Ambulance Response:  Yes  No

**Additional Information / Comments**

We were installing new gas service and while digging bell hole around/near existing 2" polyethylene main, the main had a side bend within a few horizontal feet of the ditch and we caught bottom of 2" with bucket tooth. Since it was already almost dug up it was easy to safely squeeze off and stop gas leak quickly. We disciplined the foreman, suspended the crew for this and stripped the entire crew of their OQ qualifications.

Printed Name: Ralph Miller

Signature: 

Date (month, day, year): 9-25-13

*\*If submitting this form electronically, typing your name in the signature box will act as an electronic signature.*

**Please return completed form to:**

**[PipelineDamageCase@urc.iu.gov](mailto:PipelineDamageCase@urc.iu.gov)**

**Or mail to:**

**Indiana Utility Regulatory Commission  
Pipeline Safety Division - Case Number 5199  
101 West Washington Street, 1500E  
Indianapolis, IN 46204**

**Or fax to:  
317-233-2410**

## Woods, Janea

---

**From:** Heminger-Frazier, Sarah [Sarah.Frazier@millerpipeline.com]  
**Sent:** Monday, September 16, 2013 7:11 AM  
**To:** Heminger-Frazier, Sarah  
**Subject:** original ticket for 14011 northcoat pl

NORMAL NOTICE

Ticket : 1307240717 Date: 07/24/2013 Time: 09:05 Oper: SARAH.HEMINGER Chan:000

State: IN Cnty: HAMILTON Twp: FALL CREEK  
Cityname: FISHERS Inside: N Near: Y  
Subdivision: WESTMINSTER Lot: 196

Address : 14011  
Street : NORTHCOAT PL  
Cross 1 : E 141ST ST Within 1/4 mile: Y  
Location: PAINT AND FLAG ENTIRE PROPERTY AND ALONG NORTHCOAT PL  
:  
Grids : 3959C8557C 3959C8557D  
Boundary: n 39.990838 s 39.988217 w -85.956990 e -85.951663

Work type : INSTALL GAS SERVICE  
Done for : VECTREN  
Start date: 07/26/2013 Time: 09:15 Hours notice: 48/048 Priority: NORM  
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N  
Duration : 1 DAY Depth: 5FT

Company : MILLER PIPE LINE Type: CONT  
Co addr : 8850 CRAWFORDSVILLE RD  
City : INDIANAPOLIS State: IN Zip: 46234  
Caller : SARAH HEMINGER Phone: (317)295-6417  
Contact : DAVE ROOSE - CELL Phone:  
BestTime:  
Mobile : (317)710-2341  
Fax : (317)295-6418  
Email : [SARAH.HEMINGER@MILLERPIPELINE.COM](mailto:SARAH.HEMINGER@MILLERPIPELINE.COM)

Remarks : All tickets are taken and processed on Eastern Daylight Time  
Will you be white-lining the dig site area? NO  
:

Submitted date: 07/24/2013 Time: 09:05  
Members: ID0002 ID0103 ID0660 ID2862 ID3162 ID3642 ID4636 ID9411 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FISHERS, TOWN OF	
HAMILTON SOUTHEASTERN UTILITIES	
IN AMERICAN WATER NOBLESVILLE	
INDIANA FIBER NETWORK, LLC	FIBER OPTIC

VECTREN - NOBLESVILLE #1	GAS
VECTRENS-HCJMR	

## Woods, Janea

---

**From:** Heminger-Frazier, Sarah [Sarah.Frazier@millerpipeline.com]  
**Sent:** Monday, September 16, 2013 7:10 AM  
**To:** Heminger-Frazier, Sarah  
**Subject:** damage ticket for 14011 northcoat pl

---

**From:** Heminger-Frazier, Sarah  
**Sent:** Friday, July 26, 2013 10:58 AM  
**To:** Doyle, Todd  
**Subject:** 811 damage ticket number

DAMAGE DAMAGE

Ticket : 1307261135 Date: 07/26/2013 Time: 10:53 Oper: LPORTER Chan:046

State: IN Cnty: HAMILTON Twp: FALL CREEK  
Cityname: FISHERS Inside: N Near: Y  
Subdivision: WESTMINSTER Lot: 196

Address : 14011  
Street : NORTHCOAT PL  
Cross 1 : E 141ST ST Within 1/4 mile: Y  
Location: PAINT AND FLAG ENTIRE PROPERTY AND ALONG NORTHCOAT PL  
:  
Grids : 3959C8557C 3959C8557D  
Boundary: n 39.990838 s 39.988217 w -85.956990 e -85.951663

Work type : INSTALL GAS SERVICE  
Done for : VECTREN  
Start date: 07/26/2013 Time: 10:53 Hours notice: 0/000 Priority: EMER  
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y  
Duration : 1 DAY Depth: 5FT

Company : MILLER PIPE LINE Type: CONT  
Co addr : 8850 CRAWFORDSVILLE RD  
City : INDIANAPOLIS State: IN Zip: 46234  
Caller : SARAH HEMINGER Phone: (317)295-6417  
Contact : DAVE ROOSE - CELL Phone:  
BestTime:  
Mobile : (317)710-2341  
Fax : (317)295-6418  
Email : [SARAH.HEMINGER@MILLERPIPELINE.COM](mailto:SARAH.HEMINGER@MILLERPIPELINE.COM)

Remarks : All tickets are taken and processed on Eastern Daylight Time  
PER SARAH HEMINGER - HIT A VECTREN GAS LINE - -DIGGING IN FRONT OF PROPERTY -  
GAS NOT BLOWING - HAS TAKEN CARE OF LEAK - LINE DESCRIPTION 2INCH YELLOW PLASTIC  
LINE - - CREW STILL ON SITE - PREVIOUS TICKET 1307240717  
Will you be white-lining the dig site area? NO  
:

Submitted date: 07/26/2013 Time: 10:53  
Members: ID0002 ID0103 ID0660 ID2862 ID3162 ID3642 ID4636 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS

COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FISHERS, TOWN OF	
HAMILTON SOUTHEASTERN UTILITIES	
IN AMERICAN WATER NOBLESVILLE	
INDIANA FIBER NETWORK, LLC	FIBER OPTIC
VECTREN - NOBLESVILLE #1	GAS