



## Pipeline Safety Division Investigation Report

**Investigation regarding:** Dave O'Mara Contractor

UPPAC Database Record ID: 5801

Investigator: Grant Gray

Report Date: 9/24/13

### The Parties

Excavator: Dave O'Mara Contractor

Contact: Rachel Rice

Address (City, State): 1100 E. O and M Ave., North Vernon, IN 47265

Telephone: 812-346-4135

### Facility Owner Information:

Business Name: Vectren

**Synopsis:** A natural gas distribution line was damaged during excavation related to underdrain work.

**Findings:** Operator indicated it was failure to maintain clearance as the cause of the damage, excavator provided no explanation for the cause of the damage. Pictures provided by operator indicate the markings were accurate. Based on information provided this is an excavator violation, failure to maintain clearance with mechanized equipment.

**Conclusion:** Failure to maintain clearance with mechanized equipment.

**Violation:** IC 8-1-26-20(b): Failure to maintain 2 feet of clearance with mechanized equipment.



# DAMAGE INFORMATION REPORT – PIPELINE SAFETY

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

INITIAL DOCUMENTS -  
OPERATOR

Submitted to IURC-Pipeline Safety on: 07/31/2013

## Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

## Excavator Information, if known

Full name: Dave O'Mara Contractor

Business address (number and street): 1100 East O and M Avenue

City, State, and ZIP code: N Vernon, IN 47265

Telephone number (area code): 812-346-4135

Fax number (area code): 812-352-1235

E-mail address: Unknown

## Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Drainage

---

**Date and Location of Damage**

Date of damage (month, day, year): 7-18-2013

County: Bartholomew

City: Columbus

Street address (number and street, city, state, and ZIP code):  
1231 Bitterwood, Columbus, IN

Nearest intersection: Bitterwood &amp; Champion

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? No

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? No

If yes, how many affected? 0

Time to restore service (in hours): 0

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$<sup>950</sup>

---

**Affected Facility Information**

What type of pipeline was damaged? Natural Gas

What was the affected facility? Distribution

What was the depth of the facility, in inches? \_\_\_\_\_

---

**Notification, Locating, Marking**

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1307090555

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint and Flags

If other, please specify: \_\_\_\_\_

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

### **Description of Cause**

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

---

### **Additional Comments**

2" plastic main damaged by hoe. Not hand exposed.

major # 101 394 34

001813

FDS001813

Task No: 103.05101 Capital / O & M (circle one)

Vectren Claim Number: \_\_\_\_\_

Date of Damage 7/18/13

Police Report / MO #: \_\_\_\_\_

Cost Center # 41

# FACILITIES DAMAGE REPORT

Vectren Claims Camera:

Time Occurred 1:30 am / pm

**VE03023**  
4

Time Found 1:34 am / pm

Latitude 39.183645 Longitude: -85.9808833

**DAMAGE SITE:** C intersection of Bitterwood & champion  
Address 1231 Bitterwood Drive Lot # \_\_\_\_\_

**FACILITY TYPE:**  
 Distribution  Propane  
 Service  Storage  
 Transmission: (include supplemental report)

County Bartholomew City Columbus State IND Township Columbus

FACILITIES DAMAGED:	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**VISUAL OBSERVATION AT DAMAGE SITE:** 7/18/13  
 Visual Observation:  Above Ground  Below Ground  
 Locate Applicable:  Yes  No  N/S  
 Facilities Properly Marked:  Yes  No  N/S  
**Marking Methods:**  Conventional  Flags  None  
 Offset  Paint  Stakes  Whiskers  
 Locate Marking Faded:  Yes  No  N/S  
 Wrong Address Requested:  Yes  No  N/S

**TYPE OF MATERIAL:**  Cast Iron  Plastic (HDPE)  Plastic (MDPE)  Steel  Other \_\_\_\_\_

**DAMAGE TYPE:**  Severed  Not Cut  Severed Size \_\_\_\_\_ x \_\_\_\_\_

**PRESSURE:**  25 PSIG  40 PSIG  50 PSIG  55 PSIG  60 PSIG  6 WC (.2163)  7 WC (252)  Other \_\_\_\_\_

**Facilities Improperly Located:**  
 Qualified Locator Could Not Have Accurately Located  
 Inaccurate Maps / Cards  
 Broken or No Tracer Wire (Plastic)  
 Insulation Preventing Accurate Locate

**Locator Error:**  
 Failure to Follow Policy  
 Inappropriate Site Markings  
 Incomplete Locate  
 No Locates Performed  
 Qualified Locator Could Have Accurately Located  
 Wrong Address Located  
 Marking Off By: \_\_\_\_\_ (Feet / Inches)

**PROTECTION IN PLACE:**  
 Building  Fence  None  
 Post  Rail  Vault  N/A  
 Other \_\_\_\_\_

**DURATION OF ESCAPING GAS:**  
 Minutes: N/A

Were Facility Marks Visible:  Yes  No  
 Was Area White Lined:  Yes  No  Destroyed  
 Positive Response:  Yes  No  Destroyed  
 Tolerance Zone Violated:  Yes  No  
 Part of Project:  Yes  No  
 Company Representative On-Site:  Yes  No

**LEAK REPORT NUMBER:** N/A

EFV Activated  Yes  No  N/S

Observation by (ID#): 2658

**FEED TYPE:**  
 One-Way Feed  
 Two-Way Feed

Number of Customers Affected: N/A  
 Total Hours Service: \_\_\_\_\_  
 Was Off: N/A

Name of Locator: \_\_\_\_\_  
**LOCATING ORGANIZATION:**  
 Contract Locator  
 Unknown / Other  
 Utility Owner

**SERVICE ORDER NUMBER:** \_\_\_\_\_

**DAMAGED BY:**  
 Company Crew  
 Contractor  
 County  
 Developer  
 Farmer  
 Municipality  
 Property Owner/ Tenant  
 Railroad  
 State  
 Unknown  
 Utility  
 Vehicle Accident  
 Other \_\_\_\_\_

**TYPE OF CONSTRUCTION:**  
 Agriculture  
 Building Construction  
 Building Demolition  
 Cable TV  
 Curbs / Sidewalk  
 Drainage  
 Driveway  
 Electric  
 Engineering / Surveying  
 Fencing  
 Grading  
 Irrigation  
 Landscaping  
 Liquid Pipeline  
 Milling  
 Pole  
 Natural Gas  
 Public Transit Authority  
 Railroad Maintenance  
 Other \_\_\_\_\_

**NOTIFICATIONS AND OTHER DETAILS OF LOCATE:**

Locate Ticket: 1307090555  
 Date: \_\_\_\_\_ Time: \_\_\_\_\_ am / pm

**TYPE OF REQUEST:**  
 Regular Request  Emergency Request  
 Locate Company Notified  
 Contact Name: \_\_\_\_\_  
 Time Called: \_\_\_\_\_ am / pm  
 Time Locator Arrived at the Site: \_\_\_\_\_ am / pm

Company Notified of Locate Near Critical Facilities  
 Yes  No  N/S  
 Copy of Mark Out Request Provided Within 2 Working Days  
 Yes  No  N/S

**ONE-CALL CENTER:**  
 IUPPS  
 OUPS  
 Unknown

Vectren Claim Number: \_\_\_\_\_

**TYPE OF EQUIPMENT:**

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other \_\_\_\_\_

**ROOT DAMAGING CAUSE:**

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other \_\_\_\_\_

**CONTRACTOR REPAIRS:**

- Contractor Working for Vectren Made Repairs at Own Expense
  - Yes  No  N/S
- Contractor Repaired Damage
  - Yes  No  N/S

Name of Contractor: \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 # of Overtime Hours; \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 Crew Type: \_\_\_\_\_

**MATERIALS OR ROAD WORK:**

- Meter was replaced \_\_\_\_\_ (Stores Code)
- Regulator Was Replaced \_\_\_\_\_ (Stores Code)
- Temporary Asphalt Repair: \_\_\_\_\_ (sq. ft.)
- Permanent Asphalt Repair: \_\_\_\_\_ (sq. ft.)

**RIGHT OF WAY:**

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

- Did Excavator Notify You  Yes  No
- Excavation Required  Yes  No
- Media at Site  Yes  No
- Was There Ignition of Gas?  Yes  No
- INVOICE:  Yes  No  N/S

**DAMAGING PARTY:**

Name: DAVE OHATA CONT.  
 Address: 1100 EAST OANDM AVE,  
 City/ State/ Zip: NORTH VERNON 47265  
 Phone: (812) 346-4135  
 Prepared / Investigated By: [Signature] Date: 7-18-13

**PARTY TO INVOICE:**

Name: \_\_\_\_\_  
 Address: \_\_\_\_\_  
 City/ State/ Zip: \_\_\_\_\_  
 Phone: \_\_\_\_\_  
 Reviewed by: [Signature] Field Supervisor: \_\_\_\_\_ Date: 7/18/13

## Ticket Portal Production

**Ticket Text**   Photos

**Ticket Text**

ATTIN Seq: 387 Transmitted: Tue Jul 09 07:43:37 CDT 2013  
 SBCIN 00376 IUPPSa 07/09/2013 08:41:55 1307090555-00A NORM NEW STRT  
 NORMAL NOTICE  
 Ticket : 1307090555 Date: 07/09/2013 Time: 08:38 Oper: RACHEL.RICE Chan:000  
 State: IN Cnty: BARTHOLOMEW Twp: COLUMBUS  
 Cityname: COLUMBUS Inside: Y Near: N  
 Subdivision:  
 Address :  
 Street : CHAMPION DR  
 Cross 1 : TIPTON LAKES BLVD Within 1/4 mile: Y  
 Location: FROM THE INTERSECTION OF CHAMPION AND TIPTON LAKES BLVD LOCATE SOUTH  
 ON CHAMPION FOR 1020 FEET ON THE WEST SIDE OF THE ROAD  
 :  
 Grids : 3910A8558A 3910B8558A 3910B8558B 3911D8558A  
 Boundary: n 39.185678 s 39.177873 w -85.981834 e -85.978814  
 Work type : UNDERDRAIN WORK  
 Done for : CITY OF COLUMBUS  
 Start date: 07/11/2013 Time: 09:00 Hours notice: 48/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N  
 Duration : UNKNOWN Depth: 3 FEET  
 Company : DAVE OMARA CONTRACTOR Type: CONT  
 Co addr : 1100 EAST O AND M AVENUE  
 City : NORTH VERNON State: IN Zip: 47265  
 Caller : RACHEL RICE Phone: (812)346-4135  
 Contact : DANNY DUCKWORTH Phone:  
 BestTime:  
 Mobile : (812)592-0673  
 Fax : (812)352-1235  
 Email : RACHELR@DAVEOMARA.COM  
 Remarks : All tickets are taken and processed on Eastern Daylight Time  
 REF JOB CHAMPION DR - 2  
 Will you be white-lining the dig site area? NO  
 :  
 Submitted date: 07/09/2013 Time: 08:38  
 Members: ID0002 ID0413 ID2419 ID2512 ID2546 ID4401 ID4421 SBCIN SM  
 -----  
 Email\_From: att-tickets@tickets.translore.com  
 Email\_Subject: ATT Translore - 1307090555  
 Email\_Sent\_Date: 2013-07-09 07:43:37 CDT  
 Email\_MessageID: <1373373817778.219407782.TransLore.att-tickets@tickets.translore.com>  
 Email\_host: tickets5.811tickets.com  
 Email\_user: 811.in.att  
 Email\_To: 811.in.att@tickets.811tickets.com  
 Email\_ContentType: text/plain; charset=ISO-8859-1

## Ticket Portal Production

**Ticket Text**    **Photos**

### Ticket Text

ID0002 00705 IUPPSa 07/18/2013 13:30:01 1307182084-00A EMER DAMG STRT  
 DAMAGE SEE REMARKS  
 Ticket : 1307182084 Date: 07/18/2013 Time: 13:26 Oper: LSTEVENSON Chan:018  
 State: IN Cnty: BARTHOLOMEW Twp: COLUMBUS  
 Cityname: COLUMBUS Inside: Y Near: N  
 Subdivision:  
 Address :  
 Street : CHAMPION DR  
 Cross 1 : TIPTON LAKES BLVD Within 1/4 mile: Y  
 Location: FROM THE INTERSECTION OF CHAMPION AND TIPTON LAKES BLVD LOCATE SOUTH  
 ON CHAMPION FOR 1020 FEET ON THE WEST SIDE OF THE ROAD  
 :  
 Grids : 3910A8558A 3910B8558A 3910B8558B 3911D8558A  
 Boundary: n 39.185678 s 39.177873 w -85.981834 e -85.978814  
 Work type : UNDERDRAIN WORK  
 Done for : CITY OF COLUMBUS  
 Start date: 07/18/2013 Time: 13:26 Hours notice: 0/000 Priority: EMER  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y  
 Duration : UNKNOWN Depth: 3 FEET  
 Company : DAVE OMARA CONTRACTOR Type: CONT  
 Co addr : 1100 EAST O AND M AVENUE  
 City : NORTH VERNON State: IN Zip: 47265  
 Caller : RACHEL RICE Phone: (812)346-4135  
 Contact : DANNY DUCKWORTH Phone:  
 BestTime:  
 Mobile : (812)592-0673  
 Fax : (812)352-1235  
 Email : RACHELR@DAVEOMARA.COM  
 Remarks : All tickets are taken and processed on Eastern Daylight Time  
 VECTREN GAS LINE WAS EXPOSED ON THE WEST SIDE OF CHAMPION DR---AT THE  
 INTERSECTION OF CHAMPION DR AND BITTERWOOD CT----LINE DESCRIPTION IS  
 UNKNOWN---GAS IS NOT BLOWING---VECTREN HAS BEEN NOTIFIED---CREW IS ON  
 SITE---PREVIOUS TICKET NUMBER IS 1307090555--THANK YOU  
 Will you be white-lining the dig site area? NO  
 :  
 Submitted date: 07/18/2013 Time: 13:26  
 Members: ID0002 ID0413 ID2419 ID2512 ID2546 ID4401 ID4421 SBCIN SM  
 -----  
 Email\_From: agt\_comm@irth.com  
 Email\_Subject: Seq# 834: 1307182084 for ID0002 - Electric Distribution (IN)  
 Email\_Sent\_Date: 2013-07-18 12:30:06 CDT  
 Email\_host: tickets5.811tickets.com  
 Email\_user: 811.in.duk  
 Email\_To: 811.in.duk@tickets.811tickets.com  
 Email\_ContentType: text/Plain; charset=US-ASCII



Property of United States Infrastructure Corporation  
Photo taken on 7/18/2013 2:20:08 PM



Property of United States Infrastructure Corporation  
Photo taken on 7/18/2013 2:23:42 PM



Property of United States Infrastructure Corporation  
Photo taken on 7/18/2013 2:23:52 PM



Property of United States Infrastructure Corporation  
Photo taken on 7/18/2013 2:24:32 PM

# Service Order Status

**Enter Service Order Number:**

5735297



Clear Form

Refresh Data

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD

**Order Number:** N5735297

**Order Type:** INVE

**Order Status:** Completed

**Customer:** 008888888 - INACTIVE CUSTOMER

**Prem:** 5751534 - BITTERWOOD CT & CHAMPION DR

**Technician:** 2658 - Jones, Robin

**Order Dates and Times**

**Need Date:** 7/18/2013 1:27:00 PM  
**Time Created:** 7/18/2013 1:17:23 PM  
**Time Dispatched:** 7/18/2013 1:17:23 PM  
**Time In Route:** 7/18/2013 1:20:47 PM  
**Time On-Site:** 7/18/2013 1:35:21 PM  
**Tech Complete:** 7/18/2013 2:24:28 PM  
**Time Closed:** 7/18/2013 2:24:28 PM

**Events Performed/Completion Code**

IVEG - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:**

**New Meter:**

**Completion Notes**

Dave omara cont. pulled 2inch main with hoe didn't cut or leak.crimped main.Crew called out arrived 1:54 pm to replace section of 2inch.


**Request Notes**

07/18/13 MATT CLAPP # 812-592-7444 CALLED AND ADV THEY HOOKED A GAS LINE,FELT IT PULL, AND STOPPED DIGGING W/ EXCAVATOR. NO HISSONG/BLOWING/ODOR.WILL BE ON SITE. LINES WERE LOCATED PRIOR TO DIGGING.

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentManualAck_evt	7/18/2013 1:18:59 PM	Jones, Robin
AsnAssignmentEnRoute_evt	7/18/2013 1:19:19 PM	Jones, Robin
OrdOrderSuspend_evt	7/18/2013 1:20:10 PM	Jones, Robin
AsnAssignmentEnRoute_evt	7/18/2013 1:20:47 PM	Jones, Robin
AsnAssignmentOnSite_evt	7/18/2013 1:35:21 PM	Jones, Robin
OrdOrderComplete_evt	7/18/2013 2:24:28 PM	Jones, Robin

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.



Dave O'Mara Contractor, Inc.  
1100 East O & M Avenue, PO Box 1139  
North Vernon, Indiana 47265

Phone: 812.346.4135

www.daveomara.com

Fax: 812.346.6305

---

**VIA E-MAIL**

August 28, 2013

Pipeline Safety Division – Case No. 5108  
Indiana Utility Regulatory Commission  
101 West Washington Street, Suite 1500 E  
Indianapolis, Indiana 46204  
PipelineDamageCase@urc.in.gov

RE: Notice of Preliminary Determination of Violation  
Pipeline Safety Division Case No. 5108 – Information Request

To Whom It May Concern:

This letter and the documents submitted herewith are the response of Dave O'Mara Contractors, Inc. ("DOCI") to a letter, dated July 31, 2013, from William Boyd, Director of the Pipeline Safety Division of the Indiana Utility Regulatory Commission.

Please note that any further information or communication with respect to this matter should be directed to Jessica A. Hill, Stites & Harbison PLLC, 100 East RiverCenter Boulevard, Suite 450, Covington, KY 41011.

**DOCI'S RESPONSES TO THE PIPELINE SAFETY DIVISION OF THE  
INDIANA UTILITY REGULATORY COMMISSION'S INFORMATION REQUESTS**

1. The Parties:

▪ Excavator Information:

Response: Dave O'Mara Contractor, Inc.  
Kyle Schneider, Operator  
1100 East O & M Avenue  
P.O. Box 1139  
North Vernon, Indiana 47265  
Preferred Phone: 812-346-4135  
rachelr@daveomara.com

- Facility Information:

Response: Vectren Utilities Holding  
Vectren Energy Delivery of Indiana - North  
1239 Reliable Parkway  
Chicago, IL 60686  
1-877-902-2934

- Locator Service Information:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request.

- Other (Witness, Police, fire, Other) Information:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request and believes that there no other individuals or entities involved.

## 2. Utility Line Impact:

- Location of Damage:

Response: Champion Drive  
Columbus, IN 47201  
The nearest intersection is Bitterwood Court

- Product Type:

Response: The product type involved was natural gas.

- Facility Type:

Response: Service/Drop

- Size (Diameter/etc.):

Response: The diameter of the facility is unknown.

- Pressure (PSIG/Inches):

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI does not know the pressure that was within the facility.

- Interruption in Service:

Response: No, there was no interruption in service.

- Number of Customers Affected:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI does not know whether any customers were affected.

- Evacuation:

Response: There was no need for an evacuation, and therefore, no evacuation occurred.

- Repair Cost (if known):

Response: DOCI has not been billed for any repair cost.

3. Cause of Damage Information:

- Type of Equipment:

Response: The equipment used was an Excavator.

- Type of Work Performed:

Response: DOCI was performing underdrain work.

- Release of Product:

Response: Yes, there was a minimal release of product.

- Ignition and/or Fire:

Response: There was not any ignition or fire involved.

- Excavator Notify 811:

Response: Yes, 811 was notified after the incident occurred.

#### 4. Locate Information:

- Excavator Request Locate:

Response: Yes, the excavator did make a locate request. The Request Ticket Number from Indiana 811 is 1307090555. A copy of the Request Ticket Number 1307090555 is enclosed.

- Locate Marks Visible:

Response: Yes, the locate marks were visible.

- Locate Marks Correct:

Response: Yes, the locate marks were correct.

- Excavator "White Lined":

Response: No, the excavator did not "white line."

- Maps Used to Mark Facilities:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request.

- Was Locate Provided within Two (2) Working Days?

Response: Yes, locates were provided within two working days.

- Operator Employees On-site: Were operator's employees on site at the time of the incident?

Response: Yes, the employees were on-site.

#### 5. Incident Impact Information:

- Number of Outpatient Treated:

Response: There were no injuries or fatalities related to this incident, and therefore, there were no patients treated through out-patient treatment.

▪ Number of Inpatient Treated:

Response: There were no injuries or fatalities related to this incident, and therefore, there were no patients treated through in-patient treatment.

▪ Number of Fatalities:

Response: There were no fatalities as a result of this incident.

▪ Fire Department Response:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI believes that the local fire department was not called in regards to this incident.

▪ Police Department Response:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI believes that the local police department was not called in regards to this incident.

▪ Ambulance Response:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI believes that the local ambulance service was not called in regards to this incident.


6. Additional Information/Comments:

Response: There is no additional information or comments that DOCI would like to make at this time.

This concludes the response of DOCI to the foregoing request regarding Pipeline Safety Division Case No. 5108.

Sincerely,

DAVE O'MARA CONTRACTORS, INC.  
1100 East O & M Avenue, P.O. Box 1139  
North Vernon, Indiana 47265  
812-346-4135

By:   
Dave O'Mara

Title: President

Date: August 28, 2013

Enclosures

NORMAL NOTICE

Ticket : 1307090555 Date: 07/09/2013 Time: 08:38 Oper: RACHEL.RICE Chan:000

State: IN Cnty: BARTHOLOMEW Twp: COLUMBUS  
 Cityname: COLUMBUS Inside: Y Near: N  
 Subdivision:

Address :

Street : CHAMPION DR  
 Cross 1 : TIPTON LAKES BLVD Within 1/4 mile: Y  
 Location: FROM THE INTERSECTION OF CHAMPION AND TIPTON LAKES BLVD LOCATE SOUTH  
 ON CHAMPION FOR 1020 FEET ON THE WEST SIDE OF THE ROAD

Grids : 3910A8558A 3910B8558A 3910B8558B 3911D8558A  
 Boundary: n 39.185678 s 39.177873 w -85.981834 e -85.978814

Work type : UNDERDRAIN WORK  
 Done for : CITY OF COLUMBUS  
 Start date: 07/11/2013 Time: 09:00 Hours notice: 48/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N  
 Duration : UNKNOWN Depth: 3 FEET

Company : DAVE OMARA CONTRACTOR Type: CONT  
 Co addr : 1100 EAST O AND M AVENUE  
 City : NORTH VERNON State: IN Zip: 47265  
 Caller : RACHEL RICE Phone: (812)346-4135  
 Contact : DANNY DUCKWORTH Phone:  
 BestTime:  
 Mobile : (812)592-0673  
 Fax : (812)352-1235  
 Email : RACHELR@DAVEOMARA.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 REF JOB CHAMPION DR - 2

Will you be white-lining the dig site area? NO  
 :

Submitted date: 07/09/2013 Time: 08:38

Members: ID0002 ID0413 ID2419 ID2512 ID2546 ID4401 ID4421 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BARTHOLOMEW COUNTY R.E.M.C.	ELECTRIC
COLUMBUS CITY UTILITIES	SEWER & WATER
COMCAST - COLUMBUS	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
INDIANA NATURAL GAS CORP., NASHVILLE	GAS
SOUTHWESTERN BARTHOLOMEW WATER CORP.	
VECTREN - COLUMBUS	GAS