



Pipeline Safety Division Investigation Report

Investigation regarding: Anderson Construction

UPPAC Database Record ID: 1119

Investigator: Howard Friend

Telephone: (317) 232-2717

Report Date: 01/17/2012

Damage Date: 08/09/2010

Damage Address: 118 N East St

City: Greenfield

County: Hancock

The Parties

Excavator: Anderson Construction
Commercial Business

Contact: Carlos Anderson

Address: 2586 S State Road 9, Greenfield, In 46140

Telephone: (317) 727-5840

Facility Owner: Vectren

Contact: Darlene Kulhanek, Manager, Facilities Damages

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Pipeline Safety Division Investigation Report

Investigation regarding: Anderson Construction

UPPAC Database Record ID: 1119

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: Yes

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$802

Excavator Activities

Indiana 811 Locate Request Number: NA

Excavation Equipment: Backhoe/Trackhoe

Nature of Excavation: Curb/Sidewalk

Synopsis: 1 1/4" steel low pressure natural gas service damaged by backhoe during the removal of a section of sidewalk.

Findings: Reported by Indiana 811; excavator signed for initial mailing on 09/27/2011. From documents submitted, it seems that the service was directly under the sidewalk, however, excavator failed to request locates prior to beginning work.

Conclusion: Excavator failed to provide notice of excavation.

Violation: IC 8-1-26-16(g): Failure to provide notice of excavation.

Anderson Construction has no other damage reports in the record.


NO

LOCATE

TICKET

PROVIDED

STATE OF INDIANA



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

September 20, 2011

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

RECEIVED

SEP 23 2011

INDIANA UTILITY
REGULATORY COMMISSION

Subject: Investigation Request for Information

Date of Event: 8/9/2010

Event Location: 118 N East St., Greenfield

Facility Owner: Vectren

Excavator: Anderson Construction

Other Party: N/A

Pipeline Division Case No. 1119

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation,**

maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.

Please promptly provide your information to: Pipeline Safety Division – Case No. 1119, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204. Also, please include the Investigation Number referenced above on your materials. In the alternative, if you would prefer to scan the materials and send them electronically, please send the documents to: PipelineDamageCase@urc.in.gov.

Although you are not a formal party in this investigation, please treat this request for information seriously, because the potential civil penalties for violations include: a potential civil fine up to \$10,000.00; mandatory education and training for employees regarding pipeline safety; a required development plan to avoid future violations; or a warning letter for certain homeowner/tenants who are first time offenders. Consequently, your input will assist the Pipeline Division with its determination and may have a substantial impact on the case.

After the investigation is completed, the Pipeline Division will prepare an Investigation Report with findings and forward it to the Underground Plant Protection Advisory Committee (“Advisory Committee”). This is a statutory committee, comprised of excavators, facility operators, investor and municipal utilities, the 811 Association and facility locate marking companies, whose role is to evaluate the Pipeline Division’s findings and make a recommendation for a civil penalty. In the event there is disagreement regarding the Advisory Committee’s recommendation to the Commission, parties are entitled to request a hearing before the full Commission. If there is a violation, the Indiana Utility Regulatory Commission (“Commission”) will impose the penalty. Any fines imposed are statutorily required to be spent funding the Commission’s training and educational programming to promote excavation and pipeline safety.

Thank you for your *prompt* assistance in providing written information to the Pipeline Division regarding the previously referenced incident. Any information received after the deadlines will not be considered in the investigation, will be unavailable to the Advisory Committee and will result in a lack of full information being made available; hence, your participation is vital to serving the interests of justice and enhancing the public’s safety. In an effort to assist you, please find an enclosure entitled “Information Request.” Should you have procedural or legal questions regarding the Underground Plant Protection Advisory Committee or the Indiana Utility Regulatory Commission, please contact David L. Welch, Assistant General Counsel, at (317) 234-4715. Should you have questions regarding the pipeline damage identified above, or our investigation, please contact me at (317) 232-2718. Thank you for your assistance.

Sincerely,



William Boyd
Director, Pipeline Safety Division

Enclosure: Information Request

Information Request

Pipeline Safety Division
Indiana Utility Regulatory Commission

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information:

Business Name: **Anderson Construction**

Responsible Party Personal Name: **Unknown**

Title (if any): **Unknown**

Address: **2586 S. State Rd 9**

City, State Zip: **Greenfield, IN 46140**

Preferred Telephone:

Cell Phone Number:

Email Address:

Facility Information:

Business Name: **Vectren Energy**

Responsible Party Personal Name: **Darlene Kulhanek**

Title (if any): **Manager Facilities Damages**

City, State, Zip **Evansville, IN 47711**

Address: **1 Main Street**

Preferred Telephone: **812-491-4227**

Cell Phone Number: **812-568-5235**

Email Address: **Dkulhanek@vectren.com**

Locator Service Information:

Business Name: **USIC Inc.**

Responsible Party Personal Name: **Tim Sanders**

Title (if any): **Southern Indiana District Manager**

Address: **3818 E Morgan Avenue**

City, State Zip: **Evansville, IN 47715**

Preferred Telephone: **812-479-9236**

Cell Phone Number:

Email Address: **timsanders@usicinc.com**

Other (Witness, Police, Fire, Othea) Information: **Warrick Co Sheriff's Dept.**

Personal Contact: Business/Organization Name: N/A

Title (if any)

Address:

City, State, Zip

Preferred Telephone:

Cell Phone Number:

Email Address:

Utility Line Impact:

Product Type (circle one):

Natural Gas

Liquid Pipeline

Unknown/Other

Facility Type (circle one):

Distribution

Gathering

Service/Drop

Transmission

Unknown/Other

Size (Diameter/etc.): 1.25'

Pressure (PSIG/Inches): .2163 psig

Interruption in Service: Yes / No

Number of Customers Affected: 1

Evacuation: Yes / No If yes, How Many Evacuated? 0

Repair Cost (if known): \$ 802.18

Cause of Damage Information:

Type of Equipment (circle one):

Auger

Backhoe/Trackhoe

Boring /Drilling

Directional Drilling

Explosives

Farm Equipment

Grader/Scraper

Hand Tools

Milling Equipment

Probing Device

Trencher

Vacuum Equipment

Unknown/Other

Type of Work Performed (circle one):

- Agriculture Cable
- TV Curb/Sidewalk
- Bldg. Construction
- Bldg. Demolition
- Drainage
- Driveway Electric
- Engineering/Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Natural Gas
- Pole
- Public Transit Authority
- Railroad Maintenance
- Road Work
- Sewer (Sanitary/Stom1)
- Site Development
- Steam
- Storm Drain/Culvert
- Street Light
- Telecommunications
- Traffic Signal
- Traffic Sign
- Water
- Waterway Improvement
- Unknown/Other

Release of Product: Yes / No

Ignition and/or Fire: Yes / No

Excavator Notify 811: Yes / No

Locate Information:

Excavator Request Locate: Yes / No


Indiana 811 Locate Ticket Number: _____

Locate Marks Visible: Yes / No

Locate Marks Correct: Yes / No

Excavator "White Lined": Yes / No

Maps Used to Mark Facilities: Yes / No



VECTREN

Vectren Corporation

P.O. Box 209

Evansville, Indiana 47702-0209

PAID

November 25, 2010

VIA CERTIFIED MAIL; RETURN RECEIPT REQUESTED

ANDERSON CONSTRUCTION
2586 S. STATE ROAD 9,
GREENFIELD, IN 46140

Re:

Invoice #: FDS0012999

Description: 118 N East Street, Greenfield - 1 1/4" Steel Service Severed By Backhoe. Did Not Request Locates.

Damage Date: 8/9/2010

Balance: \$802.18

Dear Sir or Madam:

You were notified on 9/1/2010 and again on 9/23/2010 regarding the above balance.


NOTICE: Payment must be made by December 7, 2010. If you fail to make payment, your account will be turned over to our collection agency.

To protect your credit rating and avoid any embarrassment this action will create, make payment by return mail or call me at 1-877-902-2934.

Sincerely,

Darlene Kulhanek
Manager Of Facilities Damages

cc: Laura Pamplin, General Counsel




2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

NOW DUE
FINAL
\$802.18

ANDERSON CONSTRUCTION
2586 S. STATE ROAD 9,
GREENFIELD, IN 46140

Type: GAS
Invoice: FDS0012999
BillToID: 29040
Billing Date: 9/23/2010
Date of Loss: 8/9/2010
5833 103.0510

Please return this portion with your remittance.



Mail Payment To: VECTREN ENERGY DELIVERY OF INDIANA - NORTH
Vectren Utilities Holding Group, Inc.
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE
FINAL
\$802.18

ANDERSON CONSTRUCTION
2586 S. STATE ROAD 9,
GREENFIELD, IN 46140

Type: GAS
Invoice: FDS0012999
BillToID: 29040
Billing Date: 9/23/2010
Date of Loss: 8/9/2010

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 118 N EAST STREET, GREENFIELD

1 1/4" STEEL SERVICIE SEVERED BY BACKHOE. DID NOT REQUEST LOCATES.

Material:	\$89.36
Company Labor:	\$640.65
Contract Labor:	\$0.00
Transportation/Equipment:	\$57.98
Misc:	\$0.00
Gas Loss:	\$14.19
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$802.18

5833 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Vectren Corporation

Form 3112 (Rev. 10/04)

Indiana Gas

Sigeco

Vectren Energy Delivery of Ohio

Task No.: 103.0510

Capital / O&M (circle one)

FDS 0012999

TIME: 3:00 AM (circle PM)

DATE OF DAMAGE 8/9/10

Cost Center No.: 5833

DAMAGE SITE ADDRESS: 118 N EAST ST.

LOT #: CITY: GREENFIELD

FACILITIES DAMAGED

<input type="checkbox"/> MAIN	<input type="checkbox"/> SIZE(S)
<input checked="" type="checkbox"/> SERVICE	<input type="checkbox"/> 0.50 INCH
<input type="checkbox"/> REGULATOR STATION	<input type="checkbox"/> 0.75 INCH
<input type="checkbox"/> FARM TAP	<input type="checkbox"/> 1.00 INCH
<input type="checkbox"/> RESIDENTIAL METER	<input type="checkbox"/> 2.00 INCH
<input type="checkbox"/> METER INDUSTRIAL/COMMERCIAL	<input type="checkbox"/> 4.00 INCH
<input type="checkbox"/> OTHER	<input type="checkbox"/> 6.00 INCH
	<input checked="" type="checkbox"/> OTHER 1 1/4

TYPE OF MATERIAL DAMAGE TYPE PRESSURE

<input type="checkbox"/> PLASTIC	<input checked="" type="checkbox"/> SEVERED	<input type="checkbox"/> 25 PSIG
<input checked="" type="checkbox"/> STEEL	<input type="checkbox"/> NOT CUT	<input type="checkbox"/> 40 PSIG
<input type="checkbox"/> CAST IRON	<input type="checkbox"/> PUNCTURE	<input type="checkbox"/> 50 PSIG
<input type="checkbox"/> OTHER	SIZE X	<input type="checkbox"/> 60 PSIG
		<input checked="" type="checkbox"/> 6 WC
		<input type="checkbox"/> OTHER

PROTECTION IN PLACE

RAIL POST NONE N/A

LEAK REPORT DURATION OF ESCAPING GAS

539940 MINUTES 1 HR

ONE-WAY FEED EFV ACTIVATED YES NO

TWO-WAY FEED

DAMAGED BY TYPE OF CONSTRUCTION

<input checked="" type="checkbox"/> CONTRACTOR	<input type="checkbox"/> SEWER/DRAIN
<input type="checkbox"/> MUNICIPALITY/UTILITY	<input type="checkbox"/> WATER
<input type="checkbox"/> VEHICULAR ACCIDENT	<input type="checkbox"/> ELECTRIC
<input type="checkbox"/> COMPANY CREW	<input type="checkbox"/> TELEPHONE
<input type="checkbox"/> UNKNOWN	<input type="checkbox"/> CEMENT/PAVING
<input type="checkbox"/> PROPERTY OWNER/TENANT	<input type="checkbox"/> TV CABLE
<input type="checkbox"/> OTHER	<input type="checkbox"/> FENCING
	<input type="checkbox"/> FOOTERS

WORKING FOR

CITY STATE PROPERTY OWNER OTHER SIDEWALK

NAME ANDERSON CONST. City of Greenfield

TYPE OF EQUIPMENT DAMAGING PARTY

<input checked="" type="checkbox"/> BACKHOE	<input checked="" type="checkbox"/> DID NOT REQUEST LOCATES
<input type="checkbox"/> TRACKHOE	<input type="checkbox"/> DID NOT HAND DIG
<input type="checkbox"/> PLOW	<input type="checkbox"/> USED EXPIRED LOCATES
<input type="checkbox"/> TRENCHER	<input type="checkbox"/> OTHER
<input type="checkbox"/> BULLDOZER	

NUMBER OF CUSTOMERS AFFECTED: 1

TOTAL HOURS SERVICE WAS OFF: 2.50

INVOICE: YES NO

DAMAGING PARTY

NAME: ANDERSON CONST.

ADDRESS: 2586 S. ST RD 9

CITY/STATE/ZIP: GREENFIELD IN 46140

JACE BRINSTEAD 8-9-10

PREPARED BY DATE

VISUAL OBSERVATION AT DAMAGE SITE

LOCATE NOT APPLICABLE (Above Ground Damage Only)

FACILITIES PROPERLY MARKED

MARKING METHODS: CONVENTIONAL OFFSET

FLAGS PAINT STAKES WHISKERS

LOCATE MARKINGS FADED: YES NO

WRONG ADDRESS REQUESTED

FACILITIES IMPROPERLY LOCATED

QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED

INACCURATE MAPS/CARDS

BROKEN OR NO TRACER WIRE (PLASTIC)

INSULATION PREVENTING ACCURATE LOCATE

LOCATOR ERROR

QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED

INCOMPLETE LOCATE

MARKINGS OFF BY (FEET/INCHES)

INAPPROPRIATE SITE MARKINGS

NO LOCATE PERFORMED

FAILURE TO FOLLOW POLICY

WRONG ADDRESS LOCATED

OBSERVATION BY: JACE BRINSTEAD

NAME OF LOCATOR:

COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS

NOTIFICATION AND OTHER DETAILS OF LOCATE

LOCATE TICKET #:

DATE: TIME: AM/PM

REGULAR REQUEST EMERGENCY REQUEST

LOCATE COMPANY NOTIFIED

CONTACT NAME:

TIME CALLED: AM/PM

TIME LOCATOR ARRIVED AT SITE: AM/PM

COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES:

YES NO

CONTRACTOR REPAIRS

CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE

CONTRACTOR REPAIRED DAMAGE

NAME OF CONTRACTOR:

OF REGULAR HOURS

OF OVERTIME HOURS

CREW TYPE

MATERIALS OR ROAD WORK

METER WAS REPLACED (STORES CODE)

REGULATOR WAS REPLACED (STORES CODE)

TEMPORARY ASPHALT REPAIR (SQ. FT.)

PERMANENT ASPHALT REPAIR (SQ. FT.)

PARTY TO INVOICE

NAME: ANDERSON CONST.

ADDRESS: 2586 S ST RD 9

CITY/STATE/ZIP: GREENFIELD IN 46140

REVIEWED BY FIELD SUPERVISOR DATE 8-12-10

CONTRACTOR DIDN'T CALL COLATES

Service Order Status

Thursday, September 22, 2011

Enter Service Order Number:

4504542



Banner Instance: CS03PROD CS01PROD CS02PROD
Order Number: N4504542
Order Type: INVE
Order Status: Completed

Customer: 600449004 - MOORE ROBERT E
Prem: 5483195 - 118 N EAST ST

Technician: 6839 - Hicks, Jeremy

Order Dates and Times

Need Date: 8/9/2010 3:09:00 PM
Time Created: 8/9/2010 3:08:48 PM
Time Dispatched: 8/9/2010 3:08:48 PM
Time In Route: 8/9/2010 5:18:31 PM
Time On-Site: 8/9/2010 5:18:35 PM
Tech Complete: 8/9/2010 5:18:44 PM
Time Closed: 8/9/2010 5:18:44 PM

Events Performed/Completion Code

IVEG - CMP

Meter Information

Current ReadStatus
Old Meter:
New Meter:

Completion Notes

GAS ON...CONT. HIT SERV. LINE...CREW FIXED THE SERV. ..RELIT AFTER REPAIRS WAS M ADE...ALL LEAK TESTS ARE GOOD..APPL. ARE ALL RUNNING GOOD...LEFT SAFE...ARRIVED AT 3:10PM...

Request Notes

8-9-10 PER 811-HIT LINE BY ANDERSON CONST. NO LOC#. MTR ? PET? XST NORTH.CREW ONSITE.

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentEnRoute_evt	8/9/2010 4:21:24 PM	Hicks, Jeremy
AsnAssignmentManualAck_evt	8/9/2010 4:21:25 PM	Hicks, Jeremy
AsnAssignmentOnSite_evt	8/9/2010 4:21:33 PM	Hicks, Jeremy
AsnAssignmentEnRoute_evt	8/9/2010 5:18:31 PM	Hicks, Jeremy
AsnAssignmentOnSite_evt	8/9/2010 5:18:35 PM	Hicks, Jeremy
OrdOrderComplete_evt	8/9/2010 5:18:44 PM	Hicks, Jeremy

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

MISCELLANEOUS CASH RECEIPT

(PLEASE ATTACH A COPY OF ALL CHECKS TO THIS FORM AND
USE PAPER CLIPS/DO NOT STAPLE CHECKS TO FORM)

PROCESS ROUTING FOR ALL VECTREN COMPANIES INCLUDING UTILITIES
AND NON REGULATED SUBSIDIARIES: SEND COMPLETED FORM,
ORIGINAL CHECK AND COPY OF CHECK TO REBECCA MINEAR IN
FINANCIAL ACCOUNTING, BRAUN BUILDING, EVANSVILLE. RETAIN COPY
OF CHECK AND FORM FOR YOUR RECORDS. PLEASE INCLUDE PROPER
ACCOUNTING SO RECEIPT MAY BE CREDITED ACCURATELY. PLEASE
INCLUDE YOUR PHONE NUMBER SO THE RECEIPT MAY BE EASILY
RESEARCHED BY THE FINANCIAL ACCOUNTING GROUP.

Activity Date: 12/20/2010
12:00:00 AM

Your Name, not your initials (employee): DARLENE Kulhanek

Your Phone Number (employee): 812-491-4227

Party Check Received From (Check Payor):

Address of Check Writer (Check Payor):
BATCH1-THE CINCINNATI INSURANCE COMPANY

Check Number 211662859

Amount of Check \$802.18

Utility/Company Name VECTREN ENERGY DELIVERY OF INDIANA - NORTH

Task Number 103.0510

Job Number FDS0012999

Date Printed: 12/27/2010



Transaction Information G-2337774 CHI-861239 2010/12/20

[Back to Table of Contents](#)

Transaction Level Details

Env Num	1	Envelope	G-2337774
Transaction	G-2337774	Lockbox	CHI-861239
Date	2010/12/20	Time	04:00
Batch	1	Batch Item	1
Check	1	Amount	\$802.18
ABA/RT	042100272	Account Num	7480494827
Check Num	211662859		

Envelope and Check Image



Transaction Level Keyed Data

Remitter Name : THE CINCINNATI INSURANCE COMPANY Check Date : 2010/12/15

Invoice Level Keyed Data

Invoice Number	Reference Number
FDS0012999	9999999

3342089

Check No 211662859

VECTREN UTILITIES HOLDING GROUP INC
1239 RELIABLE PARKWAY
CHICAGO IL 60686

Check No 211662859

CLAIM No	Policy Holder	Policy No	Loss Date	Claimant	Amount
1441835	ANDERSON CONSTRUCTION CO	05EPP0019945	08/09/2010	VECTREN UTILITIE	802.18
COVERAGE: CFP GL, BI & YD-Occur INVOICE: FOR: FDS0012999					
Total					802.18

Mail: Pipeline Safety Division - Case No. 1119
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 E
Indianapolis, IN 46204

RECEIVED

NOV 21 2011

Email: PipelineDamageCase@urc.in.gov

INDIANA UTILITY
REGULATORY COMMISSION

ATTN: Bill Boyd - Director
wboyd@urc.in.gov

317-232-2718

Mr. Boyd,

I am asking for an extension -
 on case #1119 - Vectren - Anderson Construction
 Loc: 118 N. EAST ST. GREENFIELD, IN 46114

- Would some one meet me on the job?
- I'd like a chance to show someone this > I am not at fault on the damage to the gas line in question!
- > The gas line is not buried - (CODE? ^{GUIDE LINES?})
- > This is not considered a "DIG"
- > Replacing sidewalk - only lifted cover

The gas line in question was not under ground - and was Repaired just as installed - And I do not feel I am responsible for damage, or their "improperly installed" gas line that should be under ground (not skinned over by a very few inches of dirt.) Is nt there a safety code to gas line's ? (DEPTH?)

* PLEASE CONTACT : CARLOS ANDERSON @ 317-727-5840
 OPERATOR - OWNER

RECEIVED

Mail: Pipeline Safety Division - Case No. 1119
 Indiana Utility Regulatory Commission
 101 West Washington Street, Suite 1500 E
 Indianapolis, IN 46204

AUG 21 2011

INDIANA UTILITY
 REGULATORY COMMISSION

Email: PipelineDamageCase@urc.in.gov

ATTN: Bill Boyd - Director
 wboyd@urc.in.gov

317-232-2718

Mr. Boyd,

I am asking for an extension
 on case #1119 - Vectren - Anderson Construction
 Loc: 118 N. East St. Greensburg, IN 46146

- Would some one meet me on the job?
- I'd like a chance to show someone
 this > I am not at fault on the
 damage to the gas line in question!
 } The gas line is not buried ^{GUIDE LINES} - (CODE?)
 } This is not considered a "DIG"
 } Replacing sidewalk - only lifted concrete

The gas line in question was not
 under ground - and was Repaired
 just as installed - and I
 do not feel I am responsible
 for damage, on their "improperly
 installed gas line that should
 be under ground (not skimmed
 over by a very few inches of dirt.)
 Is nt there a safety code to gas
 line's? (DEPTH?)

Please contact me - Carlos Anderson 317-727-5840

Telephone
 11/22/2011