



## Pipeline Safety Division Investigation Report

### Investigation regarding: **Rieth-riley**

UPPAC Database Record ID: 3267

Investigator: Howard Friend

Report Date: 9/10/2012

Damage Date: 6/27/2012 12:21:41 PM

Damage Address: E Douglas Dr

City: Brownsburg

County: Hendricks

### The Parties

Excavator: **Rieth-riley**

Contact: Kim Beard, Risk Manager

Address: 1751 West Minnesota, Indianapolis, In 46206

Telephone:

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

**Investigation regarding: Rieth-riley**

UPPAC Database Record ID: 3267

**Damage Impact**

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 3

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1100

**Excavator Activities/Cause of damage information:**

Excavator request locates: Yes Indiana 811 ticket Number: 1206100103

Type of Equipment: Unknown/Other

Type of work performed: Curb/Sidewalk

**Synopsis:** A natural gas line was damaged during excavation for curb/sidewalk installation.

**Findings:** Reported by Indiana 811; excavator's response to initial notice was received on 8/10/2012. The excavator had a valid locate request however, there was a failure to maintain the locate markings.

**Conclusion:** There was a failure to avoid damage or interference with underground facilities.

**Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.**

# STATE OF INDIANA



INITIAL DOCUMENTS -  
OPERATOR

INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

July 13, 2012

Ms. Darlene Kulhanek  
Vectren  
1 N Main Street  
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 6/27/2012

Event Location: E Douglas Dr, Brownsburg

Facility Owner: Vectren

Excavator: Rieth Riley Construction

Other Party: N/A

Pipeline Division Case No. 3267

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



## DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 07-19-2012

### Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

### Excavator Information, if known

Full name: Rieth Riley Construction

Business address (*number and street*): 1751 W Minnesota

City, State, and ZIP code: Indianapolis, IN 46206

Telephone number (*area code*): 317-634-5561

Fax number (*area code*): 317-631-6423

E-mail address: Unknown

### Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Data Not Collected

Type of work performed: Curb/Sidewalk

## Date and Location of Damage

Date of damage (*month, day, year*): 6-27-2012

County: Hendricks

City: Brownsburg

Street address (*number and street, city, state, and ZIP code*):  
442 E Douglas Drive, Brownsburg, IN

Nearest intersection: Unknown

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 3

Time to restore service (*in hours*): 3

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$<sup>1,100</sup>

## Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Distribution

What was the depth of the facility, in inches?

## Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1206100103

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint

If other, please specify: \_\_\_\_\_

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Yes

### **Description of Cause**

Select from the list the most accurate cause for the damage: --Failure to maintain the marks

### **Additional Comments**

2" plastic main damaged by form stake. Failure to maintain marks and failure to maintain clearance.

Task No: 1030509 Capital / O & M (circle one)

Vectren Claim Number: \_\_\_\_\_

Date of Damage 6/27/12

Police Report / MO #: \_\_\_\_\_

Cost Center # 5953

Time Occurred 12:30 am / pm


Time Found 12:35 am / pm

Latitude 37.845470 Longitude -86.388850

# FACILITIES DAMAGE REPORT

## GAS

Vectren Claims Camera:



DAMAGE SITE:  
Address 492 E. Douglas Dr. Lot # \_\_\_\_\_  
County Hendricks City Brownshurg State IN Township Lincoln

FACILITY TYPE:  
 Distribution  Propane  
 Service  Storage  
 Transmission: (include supplemental report)

FACILITIES DAMAGED:	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Other _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**VISUAL OBSERVATION AT DAMAGE SITE:**  
 Visual Observation:  Above Ground  Below Ground  
 Yes  No  N/S  
 Locate Applicable:  Yes  No  N/S  
 Facilities Properly Marked:  Yes  No  N/S  
 Marking Methods:  Conventional  Flags  None  
 Offset  Paint  Stakes  Whiskers  
 Locate Marking Faded:  Yes  No  N/S  
 Wrong Address Requested:  Yes  No  N/S

**TYPE OF MATERIAL:**  Cast Iron  Plastic (HDPE)  Plastic (MDPE)  Steel  Other \_\_\_\_\_  
**DAMAGE TYPE:**  Severed  Not Cut  Severed  
 Size 1/4" x 1/4"  
 (Purethane)  
**PRESSURE:**  25 PSIG  40 PSIG  50 PSIG  55 PSIG  60 PSIG  6 WC (.2163)  7 WC (252)  Other \_\_\_\_\_

**Facilities Improperly Located:**  
 Qualified Locator Could Not Have Accurately Located  
 Inaccurate Maps / Cards  
 Broken or No Tracer Wire (Plastic)  
 Insulation Preventing Accurate Locate  
**Locator Error:**  
 Failure to Follow Policy  
 Inappropriate Site Markings  
 Incomplete Locate  
 No Locates Performed  
 Qualified Locator Could Have Accurately Located  
 Wrong Address Located  
 Marking Off By: \_\_\_\_\_ (Feet / Inches)

**PROTECTION IN PLACE:**  Building  Fence  None  Post  Rail  Vault  N/A  Other \_\_\_\_\_  
**DURATION OF ESCAPING GAS:**  
 Minutes: 70

Were Facility Marks Visible:  Yes  No  
 Was Area White Lined:  Yes  No  Destroyed  
 Positive Response:  Yes  No  Destroyed  
 Tolerance Zone Violated:  Yes  No  
 Part of Project:  Yes  No  
 Company Representative On-Site:  Yes  No

**LEAK REPORT NUMBER:** 08778  
 EFV Activated  Yes  No  N/S

Observation by (ID#): M. Cordray 113562

**FEED TYPE:**  One-Way Feed  Two-Way Feed  
 Number of Customers Affected: 3  
 Total Hours Service Was Off: 3

Name of Locator: \_\_\_\_\_  
**LOCATING ORGANIZATION:**  
 Contract Locator  Unknown / Other  Utility Owner

SERVICE ORDER NUMBER: N5291965

**DAMAGED BY:**  Company Crew  Contractor  County  Developer  Farmer  Municipality  Property Owner/ Tenant  Railroad  State  Unknown  Utility  Vehicle Accident  Other \_\_\_\_\_  
**TYPE OF CONSTRUCTION:**  Agriculture  Building Construction  Building Demolition  Cable TV  Curbs / Sidewalk  Drainage  Driveway  Electric  Engineering / Surveying  Fencing  Grading  Irrigation  Landscaping  Liquid Pipeline  Milling  Pole  Natural Gas  Public Transit Authority  Railroad Maintenance  Other \_\_\_\_\_

**NOTIFICATIONS AND OTHER DETAILS OF LOCATE:**  
 Locate Ticket: 1206108103 & 120425277  
 Date: \_\_\_\_\_ Time: \_\_\_\_\_ am / pm  
 DIPP. Loc.

**TYPE OF REQUEST:**  
 Regular Request  Emergency Request  
 Locate Company Notified  
 Contact Name: \_\_\_\_\_  
 Time Called: \_\_\_\_\_ am / pm  
 Time Locator Arrived at the Site: \_\_\_\_\_ am / pm

Company Notified of Locate Near Critical Facilities:  Yes  No  N/S  
 Copy of Mark Out Request Provided Within 2 Working Days:  Yes  No  N/S

**ONE-CALL CENTER:**  
 IUPPS  OUPS  Unknown

Vectren Claim Number: \_\_\_\_\_

**TYPE OF EQUIPMENT:**

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle

Other FORM STAKE

**ROOT DAMAGING CAUSE:**

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided

Other \_\_\_\_\_

Did Excavator Notify You

Yes  No

Excavation Required

Yes  No

Media at Site

Yes  No

Was There Ignition of Gas?

Yes  No

INVOICE:

Yes  No  N/S

*See post locate photos*

**CONTRACTOR REPAIRS:**

- Contractor Working for Vectren Made Repairs at Own Expense  
 Yes  No  N/S
- Contractor Repaired Damage  
 Yes  No  N/S

Name of Contractor: \_\_\_\_\_

# of Regular Hours; \_\_\_\_\_

# of Overtime Hours; \_\_\_\_\_

# of Regular Hours; \_\_\_\_\_

Crew Type: \_\_\_\_\_

**MATERIALS OR ROAD WORK:**

- Meter was replaced \_\_\_\_\_ (Stores Code)
- Regulator Was Replaced \_\_\_\_\_ (Stores Code)
- Temporary Asphalt Repair: \_\_\_\_\_ (sq. ft.)
- Permanent Asphalt Repair: \_\_\_\_\_ (sq. ft.)

**RIGHT OF WAY:**

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

**DAMAGING PARTY:**

Name: Reith Riley / Mike Springer

Address: 1751 W. MINNESOTA

City/ State/ Zip: INDIANAPOLIS, IN, 46204

Phone: (317) 434-9561

Prepared / Investigated By: M. Gardner Date: 6-27-12

**PARTY TO INVOICE:**

Name: USIC

Address: \_\_\_\_\_

City/ State/ Zip: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_

Reviewed by Field Supervisor: \_\_\_\_\_ Date: 6-29-12

*Concrete Form Stake driven into main, noticed when they went to pull out stake. No new locate marks in area.*

*INVOICE USIC IF LOCATES WERE GOOD*

NORMAL NOTICE

Ticket : 1206100103 Date: 06/10/2012 Time: 16:20 Oper: JELEWITZ Chan:086

State: IN Cnty: HENDRICKS Twp: LINCOLN  
 Cityname: BROWNSBURG Inside: Y Near: N  
 Subdivision:

Address :  
 Street : E DOUGLAS DR  
 Cross 1 : N GRANT ST Within 1/4 mile: Y  
 Location: FROM THE ABOVE INTERSECTION -- LOCATE GOING EAST ON THE NORTH SIDE OF  
 EAST DOUGLAS DRIVE FOR APPROX 1000 FEET ENDING AT DOUGLAS COURT TO INCLUDE  
 APPROX 100 FEET NORTH OF THE CENTER LINE

:  
 Grids : 3950B8623C 3950A8623C 3950B8623B

Work type : INSTALL WATER STORM AND SANITARY  
 Done for : CITY OF BROWNSBURG  
 Start date: 06/13/2012 Time: 07:00 Hours notice: 62/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N  
 Duration : 6 MONTHS Depth: 20 FEET

Company : RIETH RILEY CONSTRUCTION Type: CONT  
 Co addr : 1751 WEST MINNESOTA  
 City : INDIANAPOLIS State: IN Zip: 46206  
 Caller : MIKE ROMINGER Phone: (317)634-5561  
 Contact : MIKE ROMINGER--CELL Phone:  
 BestTime:  
 Mobile : (317)281-5035  
 Fax : (317)631-6423

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 Will you be white-lining the dig site area? NO  
 :

Submitted date: 06/10/2012 Time: 16:20  
 Members: CV ID0002 ID2020 ID4471 ID5693 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
BROWNSBURG, TOWN OF	SEWER & WATER
COMCAST CABLEVISION - INDIANAPOLIS	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
QWEST COMMUNICATIONS	FIBER OPTIC
VECTREN - DANVILLE	GAS

[View Map](#) | [Close Map](#)

DAMAGE DAMAGE

Ticket : 1206272144 Date: 06/27/2012 Time: 12:17 Oper: BTHOMPSON Chan:084

State: IN Cnty: HENDRICKS Twp: LINCOLN  
 Cityname: BROWNSBURG Inside: Y Near: N  
 Subdivision:

## Address :

Street : E DOUGLAS DR

Cross 1 : N GRANT ST Within 1/4 mile: Y

Location: FROM THE ABOVE INTERSECTION -- LOCATE GOING EAST ON THE NORTH SIDE OF  
 EAST DOUGLAS DRIVE FOR APPROX 1000 FEET ENDING AT DOUGLAS COURT TO INCLUDE  
 APPROX 100 FEET NORTH OF THE CENTER LINE

:

Grids : 3950B8623C 3950A8623C 3950B8623B

Work type : INSTALL WATER STORM AND SANITARY

Done for : CITY OF BROWNSBURG

Start date: 06/27/2012 Time: 12:18 Hours notice: 0/000 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 6 MONTHS Depth: 20 FEET

Company : RIETH RILEY CONSTRUCTION Type: CONT

Co addr : 1751 WEST MINNESOTA

City : INDIANAPOLIS State: IN Zip: 46206

Caller : MIKE ROMINGER Phone: (317)634-5561

Contact : MIKE ROMINGER--CELL Phone:

BestTime:

Mobile : (317)281-5035

Fax : (317)631-6423

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 PER MIKE ROMINGER--A VECTREN GAS LINE HAS BEEN HIT AND IS BLOWING AT 442 DOUGLAS  
 DRIVE IN THE FRONT RIGHT OF WAY--CALLER HAS NO DESCRIPTION--ADVISED TO CALL  
 911--CREW IS ONSITE--PREVIOUS TICKET NUMBER 1206100103--THANK YOU  
 Will you be white-lining the dig site area? NO

:

Submitted date: 06/27/2012 Time: 12:17

Members: CV ID0002 ID2020 ID4471 ID5693 ID9999 SBCIN SM

**Member Name****Facility Types**

AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
BROWNSBURG, TOWN OF	SEWER & WATER
COMCAST CABLEVISION - INDIANAPOLIS	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
QWEST COMMUNICATIONS	FIBER OPTIC
VECTREN - DANVILLE	GAS

[View Map](#)[Close Map](#)

# Service Order Status

Friday, July 6, 2012

Enter Service Order Number:

5291695



Clear Form Refresh Data

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD  
**Order Number:** N5291695  
**Order Type:** LEAK  
**Order Status:** Completed

**Customer:** 620789266 - GUNN DIANE  
**Prem:** 5069741 - 442 E DOUGLAS DR

**Technician:** 3562 - Cordray, Mark

**Order Dates and Times**

**Need Date:** 6/27/2012 12:43:00 PM  
**Time Created:** 6/27/2012 12:34:41 PM  
**Time Dispatched:** 6/27/2012 12:34:40 PM  
**Time In Route:** 6/27/2012 12:34:50 PM  
**Time On-Site:** 6/27/2012 12:40:07 PM  
**Tech Complete:** 6/27/2012 2:25:01 PM  
**Time Closed:** 6/27/2012 2:25:01 PM

**Events Performed/Completion Code**

LKOT - CMP

**Meter Information**

Current ReadStatus

**Old Meter:** 0000 Active  
**New Meter:**

**Completion Notes**

DAMAGED 2" PL. MAIN BY FORM STAKE, CREW ONSITE TO SQUEEZE OFF AND REPAIR AT 12:38, JKNECHT ONSITE, MADE SAFE AT 1:40, NO READ, MCORDRAY

**Request Notes**

HIT BLOWING GAS LINE PER MIKE ROMINGER 317-281-5035 CE.RIETH RILEY CONSTRUCT(317-634-5561)...FORM PI N DROVE INTO GAS LINE...30 FT FROM BUILDING..NOT GETTING I.S..XST GRANT..LINES WERE LOCATED..DAMAGE # 1206272144...UPDATE 811..

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentManualAck_evt	6/27/2012 12:34:50 PM	Cordray, Mark
AsnAssignmentEnRoute_evt	6/27/2012 12:34:50 PM	Cordray, Mark
AsnAssignmentOnSite_evt	6/27/2012 12:40:07 PM	Cordray, Mark
OrdOrderComplete_evt	6/27/2012 2:25:01 PM	Cordray, Mark

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

Ticket

1206100114



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206100114	20120611110258_10 00937.jpg	Jun 11, 2012 10:45 AM CDT	Waits, Bradley	6/11/12 11:02	



Property of United States Infrastructure Corporation  
Photo taken on 6/11/2012 11:02:58 AM

↑  
paint

Ticket

1206100114



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206100114	20120611110306_10 00939.jpg	Jun 11, 2012 10:44 AM CDT	Waits, Bradley	6/11/12 11:03	



Property of United States Infrastructure Corporation  
Photo taken on 6/11/2012 11:03:06 AM

Ticket

1206272462



Attachments

Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627125746_10 06199.jpg	Jun 27, 2012 1.31 PM CDT	Waits, Bradley	6/27/12 12:57	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 12:57:46 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627125746_10 06200.jpg	Jun 27, 2012 1:31 PM CDT	Waits, Bradley	6/27/12 12:57	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 12:57:46 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627125750_10 06201.jpg	Jun 27, 2012 1.31 PM CDT	Waits, Bradley	6/27/12 12:57	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 12:57:50 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627125754_10 06202.jpg	Jun 27, 2012 1:31 PM CDT	Waits, Bradley	6/27/12 12:57	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 12:57:54 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627125800_10 06203.jpg	Jun 27, 2012 1:31 PM CDT	Waits, Bradley	6/27/12 12:57	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 12:58:00 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627125806_10 06204.jpg	Jun 27, 2012 1.31 PM CDT	Waits, Bradley	6/27/12 12:58	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 12:58:06 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627125808_10 06205.jpg	Jun 27, 2012 1:31 PM CDT	Waits, Bradley	6/27/12 12:58	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 12:58:08 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627125810_10 06206.jpg	Jun 27, 2012 1:31 PM CDT	Waits, Bradley	6/27/12 12:58	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 12:58:10 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627135950_10 06207.jpg	Jun 27, 2012 1:14 PM CDT	Waits, Bradley	6/27/12 1:59	




Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 1:59:50 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627135954_10 06208.jpg	Jun 27, 2012 1:14 PM CDT	Waits, Bradley	6/27/12 1:59	




Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 1:59:54 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627135956_10 06209.jpg	Jun 27, 2012 1:14 PM CDT	Waits, Bradley	6/27/12 1:59	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 1:59:56 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627135958_10 06210.jpg	Jun 27, 2012 1:14 PM CDT	Waits, Bradley	6/27/12 1:59	




Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 1:59:58 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627140010_10 06211.jpg	Jun 27, 2012 1:14 PM CDT	Waits, Bradley	6/27/12 2:00	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 2:00:10 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627140014_10 06212.jpg	Jun 27, 2012 1:13 PM CDT	Waits, Bradley	6/27/12 2:00	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 2:00:14 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627140022_10 06213.jpg	Jun 27, 2012 1:13 PM CDT	Waits, Bradley	6/27/12 2:00	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 2:00:22 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627140030_10 06214.jpg	Jun 27, 2012 1:13 PM CDT	Waits, Bradley	6/27/12 2:00	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 2:00:30 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627140036_10 06215.jpg	Jun 27, 2012 1:13 PM CDT	Waits, Bradley	6/27/12 2:00	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 2:00:36 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	20120627140038_10 06216.jpg	Jun 27, 2012 1:13 PM CDT	Waits, Bradley	6/27/12 2:00	



Property of United States Infrastructure Corporation  
Photo taken on 6/27/2012 2:00:38 PM

Ticket

1206272462



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206272462	callout_2012-06-27- 12-20-04.wav	Jun 27, 2012 12.43 PM CDT	Waits, Bradley		

# INITIAL DOCUMENTS – EXCAVATOR



## INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 3267

---

*The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.*

*Upon completion of answers select email button for submission.*

---

### The Parties

#### Excavator Information:

Business Name: Rieth-Riley Construction Co., Inc.

Responsible Party Personal Name: Kim Beard

Title (if any): Risk Manager

Address (number and street): P.O. Box 477

City, State and ZIP Code: Goshen, IN 46527

Preferred Telephone Number (area code): (574) 875-5183 ext. 20214

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: kbeard@rieth-riley.com

#### Facility Information:

Business Name: \_\_\_\_\_

Responsible Party Personal Name: \_\_\_\_\_

Title (if any): \_\_\_\_\_

Address (number and street): \_\_\_\_\_

City, State and ZIP Code: \_\_\_\_\_

Preferred Telephone Number (area code): \_\_\_\_\_

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

**Locator Service Information:**

Business Name: \_\_\_\_\_

Responsible Party Personal Name: \_\_\_\_\_

Title (*if any*): \_\_\_\_\_

Address (*number and street*): \_\_\_\_\_

City, State and ZIP Code: \_\_\_\_\_

Preferred Telephone Number (area code): \_\_\_\_\_

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

---

**Cause of Damage Information**

**Type of Equipment (*select one*):** Hand Tools

**Type of Work Performed (*select one*):** Curb/Sidewalk

**Other Information (Witness, Police, Fire, Other):**

Personal Contact: \_\_\_\_\_

Business/Organization Name: \_\_\_\_\_

Title (*if any*): \_\_\_\_\_

Address (*number and street*): \_\_\_\_\_

City, State and ZIP Code: \_\_\_\_\_

Preferred Telephone Number (area code): \_\_\_\_\_

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

---

**Utility Line Impact**

**Location of Damage:**

Address (*number and street*): near 442 E. Douglas Drive \_\_\_\_\_

City, State and ZIP Code: Brownsburg, IN \_\_\_\_\_

Nearest Intersection: N. Grant Street \_\_\_\_\_

**Product Type (*select one*):** Natural Gas

**Facility Type (*select one*):** Service/Drop

**Size (Diameter/etc.):** 2" \_\_\_\_\_

**Pressure (PSIG/Inches):** \_\_\_\_\_

**Interruption in Service:**       Yes       No      **Number of Customers Affected:** \_\_\_\_\_

**Evacuation:**       Yes       No      **If yes, How Many Evacuated?** \_\_\_\_\_

**Repair Cost (if known):** \$ \_\_\_\_\_

**Release of Product:**       Yes       No

**Ignition and/or Fire:**       Yes       No

**Excavator Notify 811:**       Yes       No

---

**Locate Information**

**Excavator Request Locate:**       Yes       No

**Indiana 811 Locate Ticket Number:** 1206100103 and 1206272144 \_\_\_\_\_

- Locate Marks Visible:  Yes  No
- Locate Marks Correct:  Yes  No
- Excavator "White Lined":  Yes  No
- Maps Used to Mark Facilities:  Yes  No
- Was Locate Provided within Two (2) Working Days:  Yes  No
- Operator Employees On-site during Excavation:  Yes  No

---

### Incident Impact Information

Number of Outpatient Treated: none

Number of Inpatient Treated: none

Number of Fatalities: none

Fire Department Response:  Yes  No

Police Department Response:  Yes  No

Ambulance Response:  Yes  No

---

### Additional Information / Comments

\* Unaware line had been damaged until form pin was removed

**NARRATIVE STATEMENT**

Your Pipeline Safety Division Case Number: 3267

Your Full Name: Kim Beard

Full Name of Business / Entity (if applicable): Rieth-Riley Construction Co., Inc.

Your Business Title (if applicable): Risk Manager

Address (number and street): P.O. Box 477

City: Goshen State: IN ZIP Code: 46527

Your E-mail Address: kbeard@rieth-riley.com

Today's Date (month, day, year): 8-10-12

Your Signature: Kim Beard Title (if any) Risk Manager

Please return your Narrative Statement to:

**Pipeline Safety Division – Case Number 3267**  
**Indiana Utility Regulatory Commission**  
**101 West Washington Street, 1500E**  
**Indianapolis, IN 46204**

Or scan the statement and Email to:

**[PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)**

Ticket ID: Version: 00 Notice ID: IUPPS2012061000113  
Taken Time: 06/10/2012 16:20  
NoticeType: Normal Notice

NORMAL NOTICE

Ticket : 1206100103 Date: 06/10/2012 Time: 16:20 Oper: JELEWITZ Chan:086

State: IN Cnty: HENDRICKS Twp: LINCOLN  
Cityname: BROWNSBURG Inside: Y Near: N  
Subdivision:

Address :

Street : E DOUGLAS DR

Cross 1 : N GRANT ST Within 1/4 mile: Y

Location: FROM THE ABOVE INTERSECTION -- LOCATE GOING EAST ON THE NORTH SIDE OF  
EAST DOUGLAS DRIVE FOR APPROX 1000 FEET ENDING AT DOUGLAS COURT TO INCLUDE  
APPROX 100 FEET NORTH OF THE CENTER LINE

:

Grids : 3950B8623C 3950A8623C 3950B8623B

Work type : INSTALL WATER STORM AND SANITARY

Done for : CITY OF BROWNSBURG

Start date: 06/13/2012 Time: 07:00 Hours notice: 62/048 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N

Duration : 6 MONTHS Depth: 20 FEET

Company : RIETH RILEY CONSTRUCTION Type: CONT

Co addr : 1751 WEST MINNESOTA

City : INDIANAPOLIS State: IN Zip: 46206

Caller : MIKE ROMINGER Phone: (317)634-5561

Contact : MIKE ROMINGER--CELL Phone:

BestTime:

Mobile : (317)281-5035

Fax : (317)631-6423

Remarks : All tickets are taken and processed on Eastern Daylight Time

Will you be white-lining the dig site area? NO

:

Submitted date: 06/10/2012 Time: 16:20

Members: CV ID0002 ID2020 ID4471 ID5693 ID9999 SBCIN SM

Ticket ID: Version: 00 Notice ID: IUPPS2012062702202  
Taken Time: 06/27/2012 12:17  
NoticeType: Damage

DAMAGE DAMAGE

Ticket : 1206272144 Date: 06/27/2012 Time: 12:17 Oper: BTHOMPSON Chan:084

State: IN Cnty: HENDRICKS Twp: LINCOLN  
Cityname: BROWNSBURG Inside: Y Near: N  
Subdivision:

Address :

Street : E DOUGLAS DR

Cross 1 : N GRANT ST Within 1/4 mile: Y

Location: FROM THE ABOVE INTERSECTION -- LOCATE GOING EAST ON THE NORTH SIDE OF  
EAST DOUGLAS DRIVE FOR APPROX 1000 FEET ENDING AT DOUGLAS COURT TO INCLUDE  
APPROX 100 FEET NORTH OF THE CENTER LINE

Grids : 3950B8623C 3950A8623C 3950B8623B

Work type : INSTALL WATER STORM AND SANITARY

Done for : CITY OF BROWNSBURG

Start date: 06/27/2012 Time: 12:18 Hours notice: 0/000 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 6 MONTHS Depth: 20 FEET

Company : RIETH RILEY CONSTRUCTION Type: CONT

Co addr : 1751 WEST MINNESOTA

City : INDIANAPOLIS State: IN Zip: 46206

Caller : MIKE ROMINGER Phone: (317)634-5561

Contact : MIKE ROMINGER--CELL Phone:

BestTime:

Mobile : (317)281-5035

Fax : (317)631-6423

Remarks : All tickets are taken and processed on Eastern Daylight Time  
PER MIKE ROMINGER--A VECTREN GAS LINE HAS BEEN HIT AND IS BLOWING AT 442 DOUGLAS  
DRIVE IN THE FRONT RIGHT OF WAY--CALLER HAS NO DESCRIPTION--ADVISED TO CALL  
911--CREW IS ONSITE--PREVIOUS TICKET NUMBER 1206100103--THANK YOU  
Will you be white-lining the dig site area? NO

Submitted date: 06/27/2012 Time: 12:17

Members: CV ID0002 ID2020 ID4471 ID5693 ID9999 SBCIN SM