



Pipeline Safety Division Investigation Report

Investigation regarding: **Lineal Contracting**

UPPAC Database Record ID: 3298

Investigator: John McLaughlin

Report Date: 8/27/2012

Damage Date: 7/4/2012 5:10:52 PM

Damage Address: Us Rt 31 /

City: Westfield

County: Hamilton

The Parties

Excavator: **Lineal Contracting**

Contact: Brian Busick

Address: 2922 Mitchell Road, Bedford, In 47421

Telephone:

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Investigation regarding: Lineal Contracting

UPPAC Database Record ID: 3298

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$750

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1206150237

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Telecommunications

Synopsis: Gas operator reported a natural gas main was damaged while performing telecommunication work with a backhoe.

Findings: Reported by Indiana 811; excavator did not respond to initial notice mailed July 13, 2012. A 2" PE main was damaged by a backhoe after excavator had secured a valid locate and the gas operator had provided accurate markings.

Conclusion: Excavator failed to maintain the required clearance with mechanized equipment.

Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.

STATE OF INDIANA



INITIAL DOCUMENTS -
OPERATOR

INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

July 13, 2012

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 7/4/2012

Event Location: Us Rt 31 /, Westfield

Facility Owner: Vectren

Excavator: Lineal Contracting

Other Party: N/A

Pipeline Division Case No. 3298

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 07-18-2012 _____

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek _____

Business address (*number and street*): 1 Main Street _____

City, State, and ZIP code: Evansville, IN 47711 _____

Telephone number (*area code*): 812-491-4227 _____

Fax number (*area code*): 812-491-4504 _____

E-mail address: dkulhanek@vectren.com _____

Excavator Information, if known

Full name: Lineal Contracting _____

Business address (*number and street*): 2922 Mitchell Road _____

City, State, and ZIP code: Bed _____

Telephone number (*area code*): 800-421-0582 _____

Fax number (*area code*): 260-563-0963 _____

E-mail address: Unknown _____

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Telecommunications

Date and Location of Damage

Date of damage (month, day, year): 7-4-2012

County: Hamilton

City: Westfield

Street address (number and street, city, state, and ZIP code):
US 31 & Greyhound Pass, Westfield, IN

Nearest intersection: Same

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? No

If yes, how many affected? 0

Time to restore service (in hours): 0

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 750

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1206150237

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC _____

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint

If other, please specify: _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

Additional Comments

2" plastic main damaged by hoe. Not hand exposed.

FDS 0016498

Task No: 103,0509 Capital (O & M) (circle one)
Date of Damage 7/14/12

Vectren Claim Number: _____
Police Report / MO #: _____

Vectren Claims Camera:
VE01360
Form 3112

FACILITIES DAMAGE REPORT

GAS

Cost Center # _____
Time Occurred 1100 am/pm
Time Found 1159 am/pm
Latitude 40.104105 Longitude: -82.126501

DAMAGE SITE:
Address LIS 31, GREYHOUND PASS Lot # _____
County HAMILTON City WESTFIELD State IN Township WASHINGTON

FACILITY TYPE:
 Distribution Propane
 Service Storage
 Transmission: (include supplemental report)

FACILITIES DAMAGED:	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	Other _____			

1.12692
2.252

VISUAL OBSERVATION AT DAMAGE SITE: 7/6
Visual Observation: Above Ground Below Ground
Locate Applicable: Yes No N/S
Facilities Properly Marked: Yes No N/S
Marking Methods: Conventional Flags None
 Offset Paint Stakes Whiskers
Locate Marking Faded: Yes No N/S
Wrong Address Requested: Yes No N/S

7/10 6M MOCLEY

TYPE OF MATERIAL: Cast Iron Plastic (HDPE) Plastic (MDPE) Steel Other _____
DAMAGE TYPE: Severed Not Cut Severed
Size 1" x 1" 2 HOLES
PRESSURE: 25 PSIG 40 PSIG 50 PSIG 55 PSIG 60 PSIG 6 WC (.2163) 7 WC (.252) Other _____

48.460

Facilities Improperly Located:
 Qualified Locator Could Not Have Accurately Located
 Inaccurate Maps / Cards
 Broken or No Tracer Wire (Plastic)
 Insulation Preventing Accurate Locate
Locator Error:
 Failure to Follow Policy
 Inappropriate Site Markings
 Incomplete Locate
 No Locates Performed
 Qualified Locator Could Have Accurately Located
 Wrong Address Located
 Marking Off By: _____ (Feet / Inches)

JUL 10 2012

PROTECTION IN PLACE: Building Fence None Post Rail Vault N/A
DURATION OF ESCAPING GAS: Minutes: 120

Were Facility Marks Visible: Yes No Destroyed
Was Area White Lined: Yes No Destroyed
Positive Response: Yes No Destroyed
Tolerance Zone Violated: Yes No
Part of Project: Yes No
Company Representative On-Site: Yes No

LEAK REPORT NUMBER: 02497
EFV Activated Yes No N/S

Observation by (ID#): 5417

FEED TYPE: One-Way Feed Two-Way Feed
Number of Customers Affected: 0
Total Hours Service Was Off: 2 HRS

Name of Locator: _____
LOCATING ORGANIZATION:
 Contract Locator
 Unknown / Other
 Utility Owner

SERVICE ORDER NUMBER: 5298857

DAMAGED BY: Company Crew Contractor County Developer Farmer Municipality Property Owner/ Tenant Railroad State Unknown Utility Vehicle Accident Other _____
TYPE OF CONSTRUCTION: Agriculture Building Construction Building Demolition Cable TV Curbs / Sidewalk Drainage Driveway Electric Engineering / Surveying Fencing Grading Irrigation Landscaping Liquid Pipeline Milling Pole Natural Gas Public Transit Authority Railroad Maintenance Other TELEPHONE

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:
 Locate Ticket: _____
Date: _____ Time: _____ am / pm

TYPE OF REQUEST:
 Regular Request Emergency Request
 Locate Company Notified
Contact Name: _____
Time Called: _____ am / pm
Time Locator Arrived at the Site: _____ am / pm

Company Notified of Locate Near Critical Facilities
 Yes No N/S
Copy of Mark Out Request Provided Within 2 Working Days
 Yes No N/S

ONE-CALL CENTER:
 TUPPS
 OUPS
 Unknown

TYPE OF EQUIPMENT:

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other _____

ROOT DAMAGING CAUSE:

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other _____

CONTRACTOR REPAIRS:

- Contractor Working for Vectren Made Repairs at Own Expense
 Yes No N/S
- Contractor Repaired Damage
 Yes No N/S

Name of Contractor: _____
 # of Regular Hours; _____
 # of Overtime Hours; _____
 # of Regular Hours; _____
 Crew Type: _____

MATERIALS OR ROAD WORK:

- Meter was replaced _____ (Stores Code)
- Regulator Was Replaced _____ (Stores Code)
- Temporary Asphalt Repair: _____ (sq. ft.)
- Permanent Asphalt Repair: _____ (sq. ft.)

Did Excavator Notify You

Yes No

Excavation Required

Yes No

Media at Site

Yes No

Was There Ignition of Gas?

Yes No

INVOICE:

Yes No N/S

RIGHT OF WAY:

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

BRIAN BUSICK

DAMAGING PARTY:
 Name: LINEAL CONTRACTING INC
 Address: 722 MITCHELL RD
 City/ State/ Zip: BEDFORD IN 47421
 Phone: (812) 277-0477
S. HOUST 7-4-12
 Prepared / Investigated By: _____ Date: _____

PARTY TO INVOICE:
 Name: SAME
 Address: _____
 City/ State/ Zip: _____
 Phone: (____) _____
[Signature] 7-5-12
 Reviewed by Field Supervisor: _____ Date: _____

NORMAL NOTICE

Ticket : 1206150237 Date: 06/15/2012 Time: 08:02 Oper: TSPAINHOWER Chan:049

State: IN Cnty: HAMILTON Twp: WASHINGTON
 Cityname: WESTFIELD Inside: Y Near: N
 Subdivision:

Address :

Street : US RT 31

Cross 1 : E GREYHOUND PASS Within 1/4 mile: Y

Location: STARTING AT THE ABOVE INTERSECTION - LOCATE EAST SIDE OF THE NORTH
 BOUND LANE OF US RT 31 GOING NORTH FOR 1500 FEET

***Boring Where = DIRECTIONAL UNDER DRIVEWAYS AND ROADS

:

Grids : 4000D8607B 4000C8607B

Work type : INSTALLING A CEV VAULT

Done for : AT AND T

Start date: 06/19/2012 Time: 08:15 Hours notice: 96/048 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N

Duration : 4 WEEKS Depth: 20 FEET

Company : LINEAL CONTRACTING Type: CONT

Co addr : 2922 MITCHELL ROAD

City : BEDFORD State: IN Zip: 47421

Caller : BRIAN BUSICK Phone: (812)277-0477

Contact : BRIAN BUSICK - CELL Phone:

BestTime:

Mobile : (812)521-3474

Fax : (812)275-6706

Email : MLACKEYLCI@HOTMAIL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 Will you be white-lining the dig site area? NO

:

Submitted date: 06/15/2012 Time: 08:02

Members: BE ID0002 ID0103 ID0202 ID0660 ID8000 ID8025 ID9999 PE SBCIN
 SM

Member Name**Facility Types**

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
BUCKEYE	PIPELINE
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
PANHANDLE EASTERN PIPELINE CO.	PIPELINE
VECTREN - NOBLESVILLE #1	GAS
WESTFIELD UTILITIES	SEWER & WATER
WESTFIELD, CITY OF - WESTFIELD CONNECTS	

[View Map](#)[Close Map](#)

DAMAGE SEE REMARKS

Ticket : 1207040436 Date: 07/04/2012 Time: 16:05 Oper: AROYSTON Chan:015

State: IN Cnty: HAMILTON Twp: WASHINGTON
 Cityname: WESTFIELD Inside: Y Near: N
 Subdivision:

Address :

Street : US RT 31
 Cross 1 : E GREYHOUND PASS Within 1/4 mile: Y
 Location: STARTING AT THE ABOVE INTERSECTION - LOCATE EAST SIDE OF THE NORTH
 BOUND LANE OF US RT 31 GOING NORTH FOR 1500 FEET
 ***Boring Where = DIRECTIONAL UNDER DRIVEWAYS AND ROADS

:
 Grids : 4000D8607B 4000C8607B

Work type : INSTALLING A CEV VAULT

Done for : AT AND T

Start date: 07/04/2012 Time: 16:06 Hours notice: 0/000 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y

Duration : 4 WEEKS Depth: 20 FEET

Company : LINEAL CONTRACTING Type: CONT
 Co addr : 2922 MITCHELL ROAD
 City : BEDFORD State: IN Zip: 47421
 Caller : BRIAN BUSICK Phone: (812)277-0477
 Contact : BRIAN BUSICK - CELL Phone:
 BestTime:
 Mobile : (812)521-3474
 Fax : (812)275-6706
 Email : MLACKEYLCI@HOTMAIL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 CABLE LINE HAS BEEN HIT ON THE NORTHEAST CORNER OF GREYHOUND PAST AND US RT 31
 -- CALLER IS UNSURE OF THE UTILITY COMPANY-- GAS CAN BE RULED OUT -- CALLER DOES
 NOT SMELL OR HEAR GAS BLOWING-- LINE IS BLACK APPROX 3/4 INCH DIAMETER PLASTIC
 MATERIAL -- CREW IS ON SITE -- PREVIOUS TICKET NUMBER 1206150237
 Will you be white-lining the dig site area? NO

Submitted date: 07/04/2012 Time: 16:05

Members: BE ID0002 ID0103 ID0202 ID0660 ID8000 ID8025 ID9999 PE SBCIN
 SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
BUCKEYE	PIPELINE
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
PANHANDLE EASTERN PIPELINE CO.	PIPELINE
VECTREN - NOBLESVILLE #1	GAS
WESTFIELD UTILITIES	SEWER & WATER
WESTFIELD, CITY OF - WESTFIELD CONNECTS	

View Map

Close Map

DAMAGE SEE REMARKS

Ticket : 1207040463 Date: 07/04/2012 Time: 17:08 Oper: BLIEVERTZ Chan:025

State: IN Cnty: HAMILTON Twp: WASHINGTON
 Cityname: WESTFIELD Inside: Y Near: N
 Subdivision:

Address :
 Street : US RT 31
 Cross 1 : E GREYHOUND PASS Within 1/4 mile: Y
 Location: STARTING AT THE ABOVE INTERSECTION - LOCATE EAST SIDE OF THE NORTH
 BOUND LANE OF US RT 31 GOING NORTH FOR 1500 FEET
 ***Boring Where = DIRECTIONAL UNDER DRIVEWAYS AND ROADS
 ;
 Grids : 4000D8607B 4000C8607B

Work type : INSTALLING A CEV VAULT
 Done for : AT AND T
 Start date: 07/04/2012 Time: 17:08 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y
 Duration : 4 WEEKS Depth: 20 FEET

Company : LINEAL CONTRACTING Type: CONT
 Co addr : 2922 MITCHELL ROAD
 City : BEDFORD State: IN Zip: 47421
 Caller : BRIAN BUSICK Phone: (812)277-0477
 Contact : BRIAN BUSICK - CELL Phone:
 BestTime:
 Mobile : (812)521-3474
 Fax : (812)275-6706
 Email : MLACKEYLCI@HOTMAIL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 A VECTREN GAS LINE WAS HIT ON THE NORTHEAST CORNER OF THE INTERSECTION OF US RT
 31 AND GREYHOUND PASS - GAS LINE IS BLOWING - CALLER CAN HEAR AND SMELL IT -
 UNKNOWN SIZE/COLOR/MATERIAL - CALLER HAS CALLED 911 - CALLERS CREW IS ON SITE -
 ADVISED TO CALL VECTREN - PREVIOUS TICKET NUMBER IS 1206150237 - THANK YOU
 Will you be white-lining the dig site area? NO
 ;

Submitted date: 07/04/2012 Time: 17:08
 Members: BE ID0002 ID0103 ID0202 ID0660 ID8000 ID8025 ID9999 PE SBCIN
 SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
BUCKEYE	PIPELINE
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
PANHANDLE EASTERN PIPELINE CO.	PIPELINE
VECTREN - NOBLESVILLE #1	GAS
WESTFIELD UTILITIES	SEWER & WATER
WESTFIELD, CITY OF - WESTFIELD CONNECTS	

[View Map](#)

[Close Map](#)

Service Order Status

Tuesday, July 10, 2012

Enter Service Order Number:

5298857



Clear Form

Refresh Data

Banner Instance: CS03PROD CS01PROD CS02PROD
Order Number: N5298857
Order Type: INVE
Order Status: Completed

Customer: 008888888 - INACTIVE CUSTOMER
Prem: 5719528 - HWY 31 & GRAYHOUND PASS

Technician: 5417 - Houpt, Steve

Order Dates and Times

Need Date: 7/4/2012 5:30:00 PM
Time Created: 7/4/2012 5:22:42 PM
Time Dispatched: 7/4/2012 5:22:42 PM
Time In Route: 7/4/2012 5:27:09 PM
Time On-Site: 7/4/2012 5:39:50 PM
Tech Complete: 7/4/2012 9:57:48 PM
Time Closed: 7/4/2012 9:57:48 PM

Events Performed/Completion Code

IVEG - CMP

Meter Information

Current ReadStatus

Old Meter:
New Meter:

Completion Notes

IVEG/CONTRACTOR SEVERED 2 INCH MAIN/LEAK # 2497/FDS PENDING/LEEVER CALDWELL REPA
 IRED/

Request Notes

HIT GAS LINE, BLOWING, PER BRIAN BUSICK WITH LINEAL CONTRACTING/ LOC # 1206150237/ 812 521 3474/ HIT
 BY MINI EXCAVATOR UNDER SOD/ HIT IN NE CORNER OF INTERSECTION--/100 TO 150 FT FROM A H.W./ ADV PREC

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	7/4/2012 5:27:09 PM	Houpt, Steve
AsnAssignmentEnRoute_evt	7/4/2012 5:27:09 PM	Houpt, Steve
AsnAssignmentOnSite_evt	7/4/2012 5:39:50 PM	Houpt, Steve
OrdOrderComplete_evt	7/4/2012 9:57:48 PM	Houpt, Steve

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.