



## Pipeline Safety Division Investigation Report

### Investigation regarding: Jay Troy'S Sewer & Septic Tank Service

UPPAC Database Record ID: 361

Investigator: William Boyd

Telephone: (317) 232-2718

Report Date: 11/29/2011

Damage Date: 05/03/2011

Damage Address: 11511 River Drive E

City: Carmel

County: Hamilton

### The Parties

Excavator: Jay Troy'S Sewer & Septic Tank Service  
Commercial Business

Contact: Ray Halfacre

Address: 630 Danver Lane, Beech Grove, In 46107

Telephone: (317) 787-0524

Facility Owner: Vectren

Contact: Darlene Kulhanek, Manager, Facilities Damages

Address: 1 N Main Street, Evansville, IN 47702

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

# Pipeline Safety Division Investigation Report

## Investigation regarding: Jay Troy'S Sewer & Septic Tank Service

UPPAC Database Record ID: 361

### Damage Impact

Product release: Yes

Ignition: No

Service Interruption: No

Number of Customers Affected:

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$235

### Excavator Activities

Indiana 811 Locate Request Number: NA

Excavation Equipment: Probing Device

Nature of Excavation: Sewer (Sanitary/Storm)

**Synopsis:** 1" plastic service damaged by a probe bar while excavator was attempting to locate a septic tank.

**Findings:** Reported by Indiana 811; excavator signed for initial mailing on 09/27/2011. Excavator did not call to request locates prior to beginning work. Mr. Halfacre's company is named Jay Troy's Sewer and Septic Tank Service.

**Conclusion:** Excavator failed to provide notice of excavation.

**Violation: IC 8-1-26-16(g): Failure to provide notice of excavation.**

Jay Troy'S Sewer & Septic Tank Service has no other damage reports in the record.


NO

LOCATE

TICKET

PROVIDED

STATE OF INDIANA



INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

September 23, 2011

Ms. Darlene Kulhanek  
Vectren  
1 N Main Street  
Evansville, IN 47702

RECEIVED

OCT 4 - 2011

INDIANA UTILITY  
REGULATORY COMMISSION

Subject: Investigation Request for Information

Date of Event: 5/3/2011

Event Location: 11511 River Drive S, Carmel

Facility Owner: Vectren

Excavator: Ray Halfacre

Other Party: N/A

Pipeline Division Case No. 361

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation,**

maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.

Please promptly provide your information to: Pipeline Safety Division – Case No. 361, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204. Also, please include the Investigation Number referenced above on your materials. In the alternative, if you would prefer to scan the materials and send them electronically, please send the documents to: *PipelineDamageCase@urc.in.gov*.

Although you are not a formal party in this investigation, please treat this request for information seriously, because the potential civil penalties for violations include: a potential civil fine up to \$10,000.00; mandatory education and training for employees regarding pipeline safety; a required development plan to avoid future violations; or a warning letter for certain homeowner/tenants who are first time offenders. Consequently, your input will assist the Pipeline Division with its determination and may have a substantial impact on the case.

After the investigation is completed, the Pipeline Division will prepare an Investigation Report with findings and forward it to the Underground Plant Protection Advisory Committee (“Advisory Committee”). This is a statutory committee, comprised of excavators, facility operators, investor and municipal utilities, the 811 Association and facility locate marking companies, whose role is to evaluate the Pipeline Division’s findings and make a recommendation for a civil penalty. In the event there is disagreement regarding the Advisory Committee’s recommendation to the Commission, parties are entitled to request a hearing before the full Commission. If there is a violation, the Indiana Utility Regulatory Commission (“Commission”) will impose the penalty. Any fines imposed are statutorily required to be spent funding the Commission’s training and educational programming to promote excavation and pipeline safety.

Thank you for your *prompt* assistance in providing written information to the Pipeline Division regarding the previously referenced incident. Any information received after the deadlines will not be considered in the investigation, will be unavailable to the Advisory Committee and will result in a lack of full information being made available; hence, your participation is vital to serving the interests of justice and enhancing the public’s safety. In an effort to assist you, please find an enclosure entitled “Information Request.” Should you have procedural or legal questions regarding the Underground Plant Protection Advisory Committee or the Indiana Utility Regulatory Commission, please contact David L. Welch, Assistant General Counsel, at (317) 234-4715. Should you have questions regarding the pipeline damage identified above, or our investigation, please contact me at (317) 232-2718. Thank you for your assistance.

Sincerely,



William Boyd  
Director, Pipeline Safety Division

Enclosure: Information Request

## Information Request

Pipeline Safety Division  
Indiana Utility Regulatory Commission  
Case No. 361

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information:

Business Name: **Ray Halfacre**

Responsible Party Personal Name: **Ray**

Title (if any): **Unknown**

Address: **830 Sander Lane**

City, State Zip: **Beechgrove, IN 46107**

Preferred Telephone: 317-787-0524

Cell Phone Number:

Email Address:

Facility Information:

Business Name: **Vectren Energy**

Responsible Party Personal Name: **Darlene Kulhanek**

Title (if any): **Manager Facilities Damages**

City, State, Zip **Evansville, IN 47711**

Address: **1 Main Street**

Preferred Telephone: **812-491-4227**

Cell Phone Number: **812-568-5235**

Email Address: **Dkulhanek@vectren.com**

Locator Service Information:

Business Name: **USIC Inc.**

Responsible Party Personal Name: **Morgan Thompson**

Title (if any): **Claims Coordinator**

Address: **9045 N. River Rd., Suite 300**

City, State Zip: **Indianapolis, IN 46240**

Preferred Telephone: **317-575-7800x109**

Cell Phone Number:

Email Address: **morganthompson@usicinc.com**

Other (Witness, Police, Fire, Othea) Information: N/A  
Personal Contact: Business/Organization Name: N/A

Title (if any)

Address:

City, State, Zip Preferred Telephone:

Cell Phone Number:

Email Address:

Utility Line Impact:

Product Type (circle one):

- Natural Gas
- Liquid Pipeline
- Unknown/Other

Facility Type (circle one):

- Distribution
- Gathering
- Service/Drop
- Transmission
- Unknown/Other

Size (Diameter/etc.): 1"

Pressure (PSIG/Inches): 60 PSIG

Interruption in Service:  Yes /  No

Number of Customers Affected: 1

Evacuation: Yes /  No      If yes, How Many Evacuated? 0

Repair Cost (if known): \$ 234.71

Cause of Damage Information:

Type of Equipment (circle one):

- Auger
- Backhoe/Trackhoe
- Boring /Drilling
- Directional Drilling
- Explosives
- Farm Equipment
- Grader/Scraper
- Hand Tools
- Milling Equipment
- Probing Device
- Trencher
- Vacuum Equipment
- Unknown/Other

Type of Work Performed (circle one):

- Agriculture Cable
- TV Curb/Sidewalk
- Bldg. Construction
- Bldg. Demolition
- Drainage
- Driveway Electric
- Engineering/Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Natural Gas
- Pole
- Public Transit Authority
- Railroad Maintenance
- Road Work
- Sewer (Sanitary/Stom1)
- Site Development
- Steam
- Storm Drain/Culvert
- Street Light
- Telecommunications
- Traffic Signal
- Traffic Sign
- Water
- Waterway Improvement
- Unknown/Other *SEPTIC TANK CLEANING*

Release of Product: Yes /  No

Ignition and/or Fire: Yes /  No

Excavator Notify 811:  Yes / No

Locate Information:

Excavator Request Locate: Yes /  No

Indiana 811 Locate Ticket Number: 0


Locate Marks Visible: Yes /  No

Locate Marks Correct: Yes /  No

Excavator "White Lined": Yes /  No

Maps Used to Mark Facilities: Yes /  No





PAID

NOW DUE


2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

\$234.71

HALFACRE, RAY  
630 SANDER LN  
BEECHGROVE, IN 46107

Type: GAS  
Invoice: FDS0014234  
BillToID: 30150  
Billing Date: 6/2/2011  
Date of Loss: 5/3/2011  
5830 103.0510

Please return this portion with your remittance.



Mail Payment To:  
Vectren Utilities Holding Group, Inc.  
1239 Reliable Parkway  
Chicago, IL 60686-0012  
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5  
Risk Management/Claims Department

NOW DUE  
\$234.71

HALFACRE, RAY  
630 SANDER LN  
BEECHGROVE, IN 46107

Type: GAS  
Invoice: FDS0014234  
BillToID: 30150  
Billing Date: 6/2/2011  
Date of Loss: 5/3/2011

**Invoice For Costs to Repair and Reconstruct Damaged Property**

Address: 11511 RIVER DR E, NOBLESVILLE

1" PLASSTIC SERVICE DAMAGED BY PROBE ROD. DID NOT REQUEST LOCATES.

Material:	\$29.63
Company Labor:	\$166.16
Contract Labor:	\$0.00
Transportation/Equipment:	\$33.44
Misc:	\$0.00
Gas Loss:	\$5.48
Adjustments:	\$0.00
Payments:	\$0.00
<b>Total:</b>	<b>\$234.71</b>

5830 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Vectren Corporation  
Form 3112 (Rev. 10/04)

- Indiana Gas
- Sigeco
- Vectren Energy Delivery of Ohio

Task No.: 183-051P

Capital  O&M  (circle one)

FDS 0014234

TIME: 1100  AM  PM

DATE OF DAMAGE: 5-13-11

Cost Center No.: 5830

DAMAGE SITE ADDRESS: 11511 RIVERDR E.

LOT #: \_\_\_\_\_ CITY: FISHERS

FACILITIES DAMAGED

- MAIN
- SERVICE
- REGULATOR STATION
- FARM TAP
- RESIDENTIAL METER
- METER INDUSTRIAL/COMMERCIAL
- OTHER \_\_\_\_\_

- SIZE(S)
- 0.50 INCH
  - 0.75 INCH
  - 1.00 INCH
  - 2.00 INCH
  - 4.00 INCH
  - 6.00 INCH
  - OTHER \_\_\_\_\_

TYPE OF MATERIAL

- PLASTIC
- STEEL
- CAST IRON
- OTHER \_\_\_\_\_

DAMAGE TYPE

- SEVERED
  - NOT CUT
  - PUNCTURE
- SIZE 1/4" X 1/4"

PRESSURE

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 60 PSIG
- 6 WC
- OTHER \_\_\_\_\_

PROTECTION IN PLACE

- RAIL
- POST
- NONE
- N/A

LEAK REPORT

# 590579

DURATION OF ESCAPING GAS

MINUTES 10

- ONE-WAY FEED
- TWO-WAY FEED

EFV ACTIVATED  YES  NO

DAMAGED BY

- CONTRACTOR
- MUNICIPALITY/UTILITY
- VEHICULAR ACCIDENT
- COMPANY CREW
- UNKNOWN
- PROPERTY OWNER/TENANT
- OTHER \_\_\_\_\_

TYPE OF CONSTRUCTION

- SEWER/DRAIN
- WATER
- ELECTRIC
- TELEPHONE
- CEMENT/PAVING
- TV CABLE
- FENCING
- FOOTERS

WORKING FOR

- CITY
- STATE
- PROPERTY OWNER
- OTHER \_\_\_\_\_

OTHER SEWER TANK CLEANING

NAME KYAN ADKINS

TYPE OF EQUIPMENT

- BACKHOE
- TRACKHOE
- PLOW
- TRENCHER
- BULLDOZER
- POSTHOLE DIGGERS
- BORE
- AUGER
- STAKE/SHOVEL
- OTHER PHONE RED

DAMAGING PARTY

- DID NOT REQUEST LOCATES
- DID NOT HAND DIG
- USED EXPIRED LOCATES
- OTHER \_\_\_\_\_

NUMBER OF CUSTOMERS

AFFECTED: 1

TOTAL HOURS SERVICE

WAS OFF: 2

INVOICE: YES  NO

DAMAGING PARTY

NAME: KAY HALLGREN

ADDRESS: 630 DANFORTH LN

CITY/STATE/ZIP: BEECHER IN 46011

PREPARED BY: S HOUST

DATE: 5-3-11

PN 787-0524

VISUAL OBSERVATION AT DAMAGE SITE 5/3

- LOCATE NOT APPLICABLE (Above Ground Damage Only)
- FACILITIES PROPERLY MARKED
  - MARKING METHODS:  CONVENTIONAL  OFFSET
  - FLAGS  PAINT  STAKES  WHISKERS
- LOCATE MARKINGS FADED:  YES  NO
- WRONG ADDRESS REQUESTED
- FACILITIES IMPROPERLY LOCATED
- QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED
- INACCURATE MAPS/CARDS
- BROKEN OR NO TRACER WIRE (PLASTIC)
- INSULATION PREVENTING ACCURATE LOCATE
- LOCATOR ERROR
- QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
- INCOMPLETE LOCATE
- MARKINGS OFF BY \_\_\_\_\_ (FEET/INCHES)
- INAPPROPRIATE SITE MARKINGS
- NO LOCATE PERFORMED
- FAILURE TO FOLLOW POLICY
- WRONG ADDRESS LOCATED

OBSERVATION BY: \_\_\_\_\_

NAME OF LOCATOR: \_\_\_\_\_

- COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS

NOTIFICATION AND OTHER DETAILS OF LOCATE

- LOCATE TICKET #: \_\_\_\_\_
- DATE: \_\_\_\_\_ TIME: \_\_\_\_\_ AM/PM
  - REGULAR REQUEST
  - EMERGENCY REQUEST
- LOCATE COMPANY NOTIFIED
- CONTACT NAME: \_\_\_\_\_
- TIME CALLED: \_\_\_\_\_ AM/PM
- TIME LOCATOR ARRIVED AT SITE: \_\_\_\_\_ AM/PM
- COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES:
  - YES
  - NO

CONTRACTOR REPAIRS

- CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE
- CONTRACTOR REPAIRED DAMAGE

NAME OF CONTRACTOR: \_\_\_\_\_

# OF REGULAR HOURS: \_\_\_\_\_

# OF OVERTIME HOURS: \_\_\_\_\_

CREW TYPE: \_\_\_\_\_

MATERIALS OR ROAD WORK

- METER WAS REPLACED \_\_\_\_\_ (STORES CODE)
- REGULATOR WAS REPLACED \_\_\_\_\_ (STORES CODE)
- TEMPORARY ASPHALT REPAIR \_\_\_\_\_ (SQ. FT.)
- PERMANENT ASPHALT REPAIR \_\_\_\_\_ (SQ. FT.)

PARTY TO INVOICE

NAME: SAME

ADDRESS: \_\_\_\_\_

CITY/STATE/ZIP: \_\_\_\_\_

REVIEWED BY FIELD SUPERVISOR: [Signature] DATE: 5-13-11

# Service Order Status

**Enter Service Order Number:**

4804033



**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD

**Order Number:** N4804033

**Order Type:** LEAK

**Order Status:** Completed

**Customer:** 620472683 - ADKINS RYAN D

**Prem:** 5344144 - 11511 RIVER DR E

**Technician:** 5417 - Houpt, Steve

**Order Dates and Times**

**Need Date:** 5/3/2011 11:02:00 AM  
**Time Created:** 5/3/2011 10:52:25 AM  
**Time Dispatched:** 5/3/2011 10:52:25 AM  
**Time In Route:** 5/3/2011 10:58:59 AM  
**Time On-Site:** 5/3/2011 11:20:14 AM  
**Tech Complete:** 5/3/2011 12:17:20 PM  
**Time Closed:** 5/3/2011 12:17:20 PM

**Events Performed/Completion Code**

LKOT - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:** 7084 Active

**New Meter:**

**Completion Notes**

LKOT/CONTRACTOR PUNCTURED 1 INCH SERVICE WITH PROBE ROD TRYING TO FIND EDGE OF S  
 EPTIC TANK//COMPANY CREW WILL REPAIR

**Request Notes**

PER AMBER WITH 811/REP HIT LINE AT THIS ADDRESS/BLOWING/HIT BY RAY HALFACRE/NO PHONE/XST: ELLER RD/O  
 RIG CALLED IN AT RIVER DR S/NO SUCH ADDRESS WITHTHIS XST STREET IN SYSTEM.

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentEnRoute_evt	5/3/2011 10:58:59 AM	Houpt, Steve
AsnAssignmentManualAck_evt	5/3/2011 10:59:02 AM	Houpt, Steve
AsnAssignmentOnSite_evt	5/3/2011 11:20:14 AM	Houpt, Steve
OrdOrderComplete_evt	5/3/2011 12:17:20 PM	Houpt, Steve

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

## MISCELLANEOUS CASH RECEIPT

(PLEASE ATTACH A COPY OF ALL CHECKS TO THIS FORM AND  
USE PAPER CLIPS/DO NOT STAPLE CHECKS TO FORM)

PROCESS ROUTING FOR ALL VECTREN COMPANIES INCLUDING UTILITIES  
AND NON REGULATED SUBSIDIARIES: SEND COMPLETED FORM,  
ORIGINAL CHECK AND COPY OF CHECK TO REBECCA MINEAR IN  
FINANCIAL ACCOUNTING, BRAUN BUILDING, EVANSVILLE. RETAIN COPY  
OF CHECK AND FORM FOR YOUR RECORDS. PLEASE INCLUDE PROPER  
ACCOUNTING SO RECEIPT MAY BE CREDITED ACCURATELY. PLEASE  
INCLUDE YOUR PHONE NUMBER SO THE RECEIPT MAY BE EASILY  
RESEARCHED BY THE FINANCIAL ACCOUNTING GROUP.

Activity Date: **6/22/2011  
12:00:00 AM**

Your Name, not your initials (employee): **Pam Barber**

Your Phone Number (employee): **812-491-4734**

Party Check Received From (Check Payor):

Address of Check Writer (Check Payor):  
**BATCH1-TINA M HALFAKER**

Check Number **10756**

Amount of Check **\$234.71**

Utility/Company Name **VECTREN ENERGY DELIVERY OF INDIANA - NORTH**

Task Number **103.0510**

Job Number **FDS0014234**

Date Printed: 6/23/2011


### Transaction Information G-5446451 CHI-861239 2011/06/22


[Back to Table of Contents](#)

#### Transaction Level Details

Env Num	2	Envelope	G-5446451
Transaction	G-5446451	Lockbox	CHI-861239
Date	2011/06/22	Time	16:00
Batch	1	Batch Item	2
Check	2	Amount	\$234.71
ABA/RT	274070439	Account Num	0050021563
Check Num	10756		

#### Envelope and Check Image






### Transaction Level Keyed Data

Remitter Name : TINA M HALFAKER Check Date : 2011/06/21

### Invoice Level Keyed Data

Invoice Number	Reference Number
FDS0014234	30150

		<b>NOW DUE</b> 234.71 \$234.71
<b>2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH</b>		
<b>HALFACRE, RAY 630 SANDER LN BEECHGROVE, IN 46107</b>	<b>Type: GAS Invoice: FDS0014234 BillToID: 30150 Billing Date: 6/2/2011 Date of Loss: 5/3/2011 5830 103.0510</b>	
<small>Please return this portion with your remittance.</small>		

**Information Request**  
**Pipeline Safety Division**  
**Indiana Utility Regulatory Commission**

**RECEIVED**

OCT 3 - 2011

INDIANA UTILITY  
REGULATORY COMMISSION

Case No. 361

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

**The Parties:**

**Excavator Information:**

Business Name: JAY TROY SEPTIC and Sewer  
Responsible Party Personal Name: Raymond Halfaker  
Title (if any): Owner  
Address: 630 DAVENPORT AVE  
City, State Zip: BEECH GROVE, IN 46107  
Preferred Telephone: 317-787-0524  
Cell Phone Number: 317-213-4177  
Email Address:

**Facility Information:**

Business Name: Vectren Utilities  
Responsible Party Personal Name:  
Title (if any):  
Address: 1239 Reliable Parkway  
City, State, Zip: Chicago, IL 60686-0012  
Preferred Telephone: 1-877-902-2934  
Cell Phone Number:  
Email Address:

**Locator Service Information:**

Business Name:  
Responsible Party Personal Name:  
Title (if any):  
Address:  
City, State Zip:  
Preferred Telephone:  
Cell Phone Number:  
Email Address:

**Other (Witness, Police, Fire, Other) Information:**

Personal Contact: MR. ADKINS

Business/Organization Name:

Title (if any) homeowner

Address: 11511 River Dr. E.

City, State, Zip: Noblesville, IN

Preferred Telephone: 281-3670

Cell Phone Number:

Email Address:

**Utility Line Impact:**

**Location of Damage:**

Address: 11511 River Dr. E.

City, State Zip: Noblesville IN

Nearest Intersection: 116th & White River.

**Product Type (circle one):**

Natural Gas

Liquid Pipeline

Unknown/Other

**Facility Type (circle one):**

Distribution

Gathering

Service/Drop

Transmission

Unknown/Other

Size (Diameter/etc.): ~~2~~<sup>3</sup> 1"

Pressure (PSIG/Inches): unknown

Interruption in Service: Yes No Number of Customers Affected: 1

Evacuation: Yes No If yes, How Many Evacuated? \_\_\_\_\_

Repair Cost (if known): \$ 234.71 \* pd. receipt attached

**Cause of Damage Information:**

**Type of Equipment (circle one):**

- Auger
- Backhoe/Trackhoe
- Boring /Drilling
- Directional Drilling
- Explosives
- Farm Equipment
- Grader/Scraper
- Hand Tools
- Milling Equipment
- Probing Device
- Trencher
- Vacuum Equipment
- Unknown/Other

**Type of Work Performed (circle one):**

- Agriculture
- Cable TV
- Curb/Sidewalk
- Bldg. Construction
- Bldg. Demolition
- Drainage
- Driveway
- Electric
- Engineering/Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Natural Gas
- Pole
- Public Transit Authority
- Railroad Maintenance
- Road Work
- Sewer (Sanitary/Storm)
- Site Development
- Steam
- Storm Drain/Culvert
- Street Light
- Telecommunications
- Traffic Signal
- Traffic Sign
- Water
- Waterway Improvement
- Unknown/Other

SEPTIC TANK Pumping

Release of Product:  Yes /  No

Ignition and/or Fire: Yes /  No

Excavator Notify 811:  Yes /  No

**Locate Information:**

Excavator Request Locate: Yes /  No

Indiana 811 Locate Ticket Number: \_\_\_\_\_

Locate Marks Visible: Yes / No

Locate Marks Correct: Yes/No

Excavator "White Lined": Yes / No

Maps Used to Mark Facilities: Yes / No

Was Locate Provided within Two (2) Working Days: Yes / No

Operator Employees On-site during Excavation: Yes / No

**Incident Impact Information:**

Number of Outpatient Treated: 0

Number of Inpatient Treated: 0


Number of Fatalities: 0

Fire Department Response: Yes /  No

Police Department Response: Yes /  No

Ambulance Response: Yes /  No

Additional Information/Comments: My company was called to locate +  
probe septic tank for homeowner. Probed 3 times for septic.  
on 3rd probe, found edge of septic tank. Gas line was partially  
punctured at top of plastic line due to closeness of septic  
tank. In the future, we will call INDIANA 811 to locate  
lines in the event that the customer does NOT have septic  
exposed. We have been in business since 1952 and have used  
INDIANA 811's service for all of our excavating locate needs.  
Attached is copy of bill we received and paid to Vectron Utilities along  
with copy of cancelled check.



Mail Payment To:  
**Vectren Utilities Holding Company**  
 1239 Reliable Parkway  
 Chicago, IL 60686-0012  
 Inquiries: 1-877-902-2934, Mon.-Fri., 8-5  
 Risk Management/Claims Department

**NOW DUE**

**\$234.71**

HALFACRE, RAY  
 630 SANDER LN  
 BEECHGROVE, IN 46107

Type: GAS  
 Invoice: FDS0014234  
 BillToID: 30150  
 Billing Date: 6/2/2011  
 Date of Loss: 5/3/2011

**Invoice For Costs to Repair and Reconstruct Damaged Property**

Address: 11511 RIVER DR E, NOBLESVILLE

1" PLASSTIC SERVICE DAMAGED BY PROBE ROD. DID NOT REQUEST LOCATES.

*Site: →*  
*5/3/11*  
*ADKINS.*  
*BAS line ran over*  
*TOP OF SEPTIC TANK*  
*HIT w/ ROD.*

Material:	\$29.63
Company Labor:	\$166.16
Contract Labor:	\$0.00
Transportation/Equipment:	\$33.44
Misc:	\$0.00
Gas Loss:	\$5.48
Adjustments:	\$0.00
Payments:	\$0.00
<b>Total:</b>	<b>\$234.71</b>

*Ad*  
*6/2/11*  
*✓ # 10756*  
*\$234.71*

5830 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

