PRINTED: 02/10/2021 FORM APPROVED

Indiana State Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING:		(X3) DATE SURVEY COMPLETED	
			A. BOILDING.			
005008		B. WING		02/03/2021		
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE						
ST CATHERINE HOSPITAL INC 4321 FIR STREET EAST CHICAGO, IN 46312						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	(EACH CORRECTIVE ACTION SHOULD	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (X5) COMPLETE DATE	
S 000	000 INITIAL COMMENTS		S 000			
	This visit was for a licensure review of negative pressure patient rooms per ISDH CSHCR: Program Advisory Letter Number: AC-2020-01-HOSP. Facility Number: 005008					
	Date of Survey: 2/3/2021					
	The following patient rooms at St. Catherine Hospital, Inc were successfully verified as negative pressure: Emergency Department: Ward/area containing rooms: Waiting room and Exam room: # 3. ICU (Intensive Care Unit) - Rooms: 3001, 3002, 3004, 3005, 3006, 3007, 3008, 3010 and 3011. The following patient rooms failed to be successfully verified as negative pressure: None.					
	QA: 2/9/21					

Indiana State Department of Health
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE