

Indiana State Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 005004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 11/13/2020
NAME OF PROVIDER OR SUPPLIER FRANCISCAN HEALTH HAMMOND		STREET ADDRESS, CITY, STATE, ZIP CODE 5454 HOHMAN AVE HAMMOND, IN 46320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S 000	<p>INITIAL COMMENTS</p> <p>This visit was for a licensure review of negative pressure patient rooms per ISDH CSHCR: Program Advisory Letter Number: AC-2020-01-HOSP.</p> <p>Facility Number: 005004</p> <p>Date Of Survey: 11/13/2020</p> <p>The following patient rooms at Franciscan Health Hammond were successfully verified as negative pressure:</p> <p>2nd floor- ICU (Intensive Care Unit) - Rooms: 2302 and 2319; IMCU (Intermediate Care Unit) - Rooms 2327 and 2328.</p> <p>The following patient rooms failed to be successfully verified as negative pressure: None.</p> <p>QA: 11/18/20</p>	S 000		

Indiana State Department of Health

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE