Indiana State Department of Health

AND PLAN OF CORRECTION IDENTIFICATION NUMBER	A. BUILDING:	(X3) DATE SURVEY COMPLETED
005109	B. WING	
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1402 E COUNTY LINE RD S INDIANAPOLIS, IN 46227		
(X4) ID SUMMARY STATEMENT OF DEFICIENCIES PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION	ID PROVIDER'S PREFIX (EACH CORREC CROSS-REFEREN	S PLAN OF CORRECTION CTIVE ACTION SHOULD BE NCED TO THE APPROPRIATE DEFICIENCY) (X5) COMPLETE DATE
This visit was for a licensure review of negative pressure patient rooms per ISDH CSHCR: Program Advisory Letter Number: AC-2020-01-HOSP. Facility Number: 005109 Survey Date: 1/13/2021 The following patient rooms were successfully verified as negative pressure: 2108, 2109, 21 2111, 2112, 2113, 2114, and 2115. The following patient rooms failed to be successfully verified as negative pressure: No. QA: 1/25/21	10,	

Indiana State Department of Health

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE