

Indiana State Department of Health

| | | | |
|---|--|--|--|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 005079 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____ | (X3) DATE SURVEY COMPLETED 11/20/2020 |
|---|--|--|--|

NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE

INDIANA UNIVERSITY HEALTH BALL MEMORIAL HOSPITAL **2401 UNIVERSITY AVE**
MUNCIE, IN 47303

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------------|--|---------------------|--|--------------------------|
| S 000 | <p>INITIAL COMMENTS</p> <p>This visit was for a licensure review of negative pressure patient rooms per ISDH CSHCR: Program Advisory Letter Number: AC-2020-01-HOSP.</p> <p>Facility Number: 005079</p> <p>Survey Date: 11-20-2020</p> <p>The following patient rooms were successfully verified as negative pressure by a visual monitoring mechanism indicating the air pressure status at all times: CIC room 2333 and MTU room 4311.</p> <p>The following patient rooms failed to be successfully verified as negative pressure: none.</p> <p>QA: 12/4/20</p> | S 000 | | |

Indiana State Department of Health

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE