

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/15/2024  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155290</b>		(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/08/2024</b>	
NAME OF PROVIDER OR SUPPLIER  <b>ST ELIZABETH HEALTHCARE CENTER</b>				STREET ADDRESS, CITY, STATE, ZIP CODE <b>701 ARMORY RD</b> <b>DELPHI, IN 46923</b>			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 04/30/24 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a).</p> <p>Survey Date: 07/08/24</p> <p>Facility Number: 000187 Provider Number: 155290 AIM Number: 100267300</p> <p>At this PSR survey, St. Elizabeth Healthcare Center was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire, and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. The 500 wing, a 2018 addition, was surveyed under LSC Chapter 18, New Health Care Occupancies.</p> <p>This one-story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors and hard-wired smoke detectors in all resident sleeping rooms. The Healthcare Center is connected to an Assisted Living, Residential Board and Care occupancy, from which it is separated by a Fire Wall with a 2-hour Fire Resistance Rating. The building is fully protected by a 135-kW diesel-powered generator. The facility has a capacity of 64 and had a census of 54 at the time of this survey.</p>			{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/15/2024  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155290</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/08/2024</b>
NAME OF PROVIDER OR SUPPLIER  <b>ST ELIZABETH HEALTHCARE CENTER</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>701 ARMORY RD</b> <b>DELPHI, IN 46923</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 1 All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered except two detached garages and two detached storage sheds which were not sprinklered.	{K 000}			
{K 000}	Quality Review completed on 07/10/24 INITIAL COMMENTS  A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 04/30/24 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a).  Survey Date: 07/08/24  Facility Number: 000187 Provider Number: 155290 AIM Number: 100267300  At this PSR survey, St. Elizabeth Healthcare Center was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire, and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. The 500 wing, a 2018 addition, was surveyed under LSC Chapter 18, New Health Care Occupancies.  This one-story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors and hard-wired smoke detectors in all resident sleeping rooms. The	{K 000}			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155290</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/08/2024</b>
NAME OF PROVIDER OR SUPPLIER  <b>ST ELIZABETH HEALTHCARE CENTER</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>701 ARMORY RD</b> <b>DELPHI, IN 46923</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>Continued From page 2</p> <p>Healthcare Center is connected to an Assisted Living, Residential Board and Care occupancy, from which it is separated by a Fire Wall with a 2-hour Fire Resistance Rating. The building is fully protected by a 135-kW diesel-powered generator. The facility has a capacity of 64 and had a census of 54 at the time of this survey.</p> <p>All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered except two detached garages and two detached storage sheds which were not sprinklered.</p> <p>Quality Review completed on 07/10/24</p>	{K 000}			