DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/17/2017 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		(X3) DATE SURVEY COMPLETED		
		155324	B. WING				R 1 13/2017
NAME OF PROVIDER OR SUPPLIER					STREET ADDRESS, CITY, STATE, ZIP CODE	1 017	10/2017
MITCHELI	MANOR				24 TEKE BURTON DR		
WILLCHELL	- WANOR				MITCHELL, IN 47446		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	} INITIAL COMMENTS		{K 0	000)}		
	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 12/01/16 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 01/13/17 Facility Number: 000217 Provider Number: 155324 AIM Number: 100289590 At this PSR survey, Mitchell Manor was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2012 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility, consisting of Building 0101 and Building 0202 each constructed prior to 2003, was determined to be of Type V (000) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. The facility has battery operated smoke detectors in all resident sleeping rooms. The facility has a capacity of 171 and had a census of 58 at the time of this visit. All areas where residents have customary access were sprinklered. The facility has one detached garage and two storage barns providing facility storage services which were not sprinklered. Quality Review completed on 01/13/17 - DA						

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/17/2017 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI A. BUILDIN	PLE CONSTRUCTION G 01		(X3) DATE SURVEY COMPLETED	
						R	
		155324	B. WING _			01/13/2017	
NAME OF PR	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE			
MITOLIELL	MANOD			24 TEKE BURTON DR			
MITCHELL	. WANUR			MITCHELL, IN 47446			
(X4) ID SUMMARY STATEMENT OF DEFICIENCIES			ID	PROVIDER'S PLAN OF CORRI	ECTION	(X5)	
PREFIX		Y MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SH		COMPLETION DATE	
TAG	REGULATORY OR I	LSC IDENTIFYING INFORMATION)	TAG	CROSS-REFERENCED TO THE AP DEFICIENCY)	PROPRIATE	BALL	
			-	,			