



Grant County Health Department
401 South Adams Street
Marion, 46953
Office - (765)651-2401

Swimming Pool Inspection Report

Owner

N/A
Pearson Mill Assembly
3522 N. 1000 W 27
Converse, IN 46919

Facility

Ark Christian Ministries, Inc.
3522 N. 1000 W 27
Converse, IN 46919
License Number :

The Ark Christian Ministries, Inc. Swimming Pool was inspected on 05/13/2026 by Cassie Leech & Josh Keller.

This pool is in compliance with 410 IAC 6-2.1 and 675 IAC 20.

1. A gate or door to the pool enclosure is not effectively self-closing, with a positive self-latching closure mechanism. This presents a serious drowning hazard to young children, who could therefore access the pool enclosure on their own, without an adult caretaker. This is a violation of 410 IAC 6-2.1-26(a) and 675 IAC 20-2-26(f). This was corrected same day and verified with a video.

2. Lifeguard platforms or chairs were not elevated 5 to 6 feet above the deck at pool areas with a depth of 5 feet or greater. This is a violation of 410 IAC 6-2.1-35(h). Conversation took place and lifeguards are to be on patron surveillance duty by standing and walking. If no lifeguard chairs will be provided. If during inspection it is observed the lifeguards on duty fail to comply, a violation will be noted. Per code 410 IAC 6-7.2-30 (b & c), there must be a minimum of 1 counselor for 15 campers & 1 certified lifeguard for 30 campers must be provided during swimming activities.

3. The alkalinity of the water was 140ppm. This is out of the acceptable range of least 80 and no more than 120 part per million (mg/l). This is a violation of 410 IAC 6-2.1-30(n).

If you have questions, please contact the Grant County Health Department.

Field Data

Free Disinfectant Level : N/A
Total Disinfectant Level : N/A
pH : 8
Combined Chlorine : N/A
Cyanuric Acid Level : N/A
Calcium Hardness : N/A

Total Alkalinity : 140 mg/l
Total Dissolved Solids : N/A
Temperature : N/A
Saturation Index : N/A
Maximum Bather Load : N/A